T					
(08/11 /13) Wef ASS_ REC. BY: / Tayfilm REF: CS HUA	23006011/tng3				
	SIGNMENT				
From: Date:	Veh No: SHA 5981 K Yr Regn: 2019, July				
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /				
OD / TP WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or				
To In ≤pect Vehicle No:	Make: Myunder long, c.c /580,				
at Workshop m/s	Colour Lute A/C: Insured / Std / NI / NA				
of	Sp.Reading 746476 T/Radio: Insured / Std / NI / NA				
Insured:	Eng/No:				
Policy No.	C/No: 02 My M C8 STCVK9 164543.				
Claimas No.	Gen. Cond: Good / Fair / Poor / Burnt				
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or				
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or				
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or				
nA .	Tyre Size: F: 195/65/RI5				
(Policy Condition)	R:				
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /				
repair at the time of inspection.	TOYO/YOKO or Wes flate.				
Bal. or Market Value:	Front Rear				
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm				
GIA / PR Seen: Consistent? : Yes or No	L/Bal. L/Bal. 6, mm				
Est. Repairs: 2 days Res.: Yes or No	D.O.A. D.O.I. 14673				
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfort Logy				
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or				
Date: Person Contacted: Vehicle: IN / OUT					
	The U/C / Chassis frame / Body Structure affected due to collision.				
Date / Time Action / Instruction					
Taufikh confirmed lump sum \$1700	and 2 repair days				
(red, \$3037.72, 64%)					
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 2				
1) : Final Report	Resurvey No. of Trip: Survey Fee:				
Oate/Time, File Return to?	Transportation:				
2) Add Fee	e:: Site Insp (\$)s+Rssi				
	: Interview (\$) Photos				

Report Format:

Lump Sum / I.B.I: (\$

Others

TOTAL

: Tech. Invs (\$

:Weekend (\$

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

Lim Tien Sions

TP INSURER:

CTPL

Singapore

HL Assurance Pte Ltd (HC

PARTICULARS OF CLAIM

Claim Type:

THIRD PARTY

Ref. No:

Driveable?

Date of Loss:

12/06/2023

Policy No:

Vehicle Reg. No.:

SHA5981K

UNKNOWN

Make/Model:

Party At Fault:

HYUNDAI IONIQ HYBRID, 1.6 GLS

Vehicle Reg. Date:

02/07/2019

Vehicle Colour:

DCT (A)

BLUE

G4LEKU296306

Chassis No:

KMHC851CVKU164543

Engine No: Odometer:

0 KM

Paint Type:

List Item Discount:

20.00 %

Total Loss?

NO

Est. Duration of Repair (day) 3

Present Location:

COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)

COST OF CLAIMS		Amount
Parts		3,257.72
Miscellaneous Items		0.00
Labour		1,480.00
Paintwork Labour		0.00
Towing		0.00
-	Gross Total (S\$)	4,737.72
	+ GST 8.00% (S\$)	379.02
	Nett Amount (S\$)	5,116.74

This claim is handled by: LIM TIEN SIONG

Generated using Merimen e-Claims Internet Estimation & Adjusting System

13/6@16:15hs.

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 13 Jun 2023)

Lim Tien Siong

Parts:

HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)

Labour:

(Price-denominated Standard List) Repairer's

Validity:

Print Code: ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15 These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

	Qty Part No.	Particulars	%Disc	%Depr	Amount
	2.9		20.00	0.00	de *481.10FL
1	1	*FRT BUMPER	20.00	0.00	× *368.50 FL
2	1	*FRT BUMPER UPPER MOULDING	20.00	0.00	ve/ *22.00 FL
3	10	*FRT BUMPER CLIPS	20.00	0.00	★ *35.00 FL
4	1	*FRT BUMPER SIDE BRKT LH	20.00	0.00	7 *2,110.30 FL
5	1	*HEADLAMP LH	20.00	0.00	cut /*93.45 FL
6	1	*DAYLIGHT GRILLE LH	20.00	0.00	15€ *588.80 FL
7	1	*FRT FENDER LH	20.00	0.00	ug/ *26.60 FL
8	1	*FRT FENDER (BLUE-DRIVE) LH *FRT WHEEL CAP LH	20.00	0.00	₩ *346.40 FL
9 F=Fr	1 anchise part. L=ListItemDi	The state of the s	-		
	anomoo para 2 alemena		otal (S\$)		4,072.15
		- List Item Discount on L Ite	ms (S\$)		814.43
		Total Pa	arts (S\$)		3,257.72

ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15. Not valid without Reference section. Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Lim Tien Siong

Estimates on Labour

No	Particulars Lab.Type		Α	Mount
Lab	our Items	New 3	150	800.00
1	PANEL BEATING		5720	600.00
2	SPRAY PAINTING		307	
3	CHECK LIGHTINGS	New		40.00
4		New	30	40.00
		Gross Labour Cost (S\$)	1	,480.00

ComfortDelGro Engineering Pte Ltd/SHA5981K/13/06/2023 16:15. Not valid without Reference section. Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

templin 9744 5749

"wp", 14 [& 173 C 4 pm

Ll's Rosing after capa
templine | thankson.

2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508989
383 Sin Ming Drive Singapore 575717

Date/Time: 45 Pandam Mad Singapore 509286: 01

Page: 1

JOB CARD Sales Order: 5900102 JC NO305557620 ARC Repair TP(CLSO)1 am: REGN NO.: SHA5981K MILEAGE **OMER** COMFORT TRANSPORTATION PTE LTD FUEL MAKE S HYUNDAI 7010045 E., OMER NO 383 SIN MING DRIVE 13.06.2023 13:40 MODE ESS IONIQ(G2) Singapore SINGAPORE 575717 65508755 TARGET DATE (O) MANU. 02.07.2019 (R) (P) COMPLETION DATE/TIME: CHASSIS CODE KMHC851CVKU164543 JUNT CARD NO. JOB DESCRIPTION :cident Date: 12.06.2023 TURE: 3P 12.06.2023/C FRONT DESCRIPTION NO LABOR CODE PANEL BEATING-SHA5981K-TP PB 10010 (ED & PASSED OUT BY: CUSTOMER'S SIGNATURE SERVICE ADVISOR

Service Advisor

dgement Slip

Signature/Date

LIMTS

Name of Service Advisor

Exit Pass

Vehicle No.:

Date

urned to Service Reception upon collection

SHA5981K

To be kept by Security Guard

SHA5981K