



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				CS3/EQ123004110/Tvy3-1	
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: <del>CS3/EQ123004110/y3</del> Date: <del>21/04/2023</del> 14/06/2023  Code: EQ1		
<b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>					
Insured Veh.		YQ 3321T	Veh. Inspected		FBR 7098D
Policy No.			Coverage (\$)		0.00
Claim No.		DM23HO00639/JS	Excess (\$)		0.00
Assign From		NEO JIE SI	Assign Date		<del>20/04/2023</del> 14/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>					
Make & Model			c.c		0
Engine No.		HIDDEN	Year of Reg.		
Chassis No.			Colour		
Odometer		-	Steering		
Brakes			Modification		
General					
<b>3. Conditions of Tyres</b>					
		Size	Make	Balance	
	R/H Front Tyre			mm	
	L/H Front Tyre			mm	
	R/H Rear Tyre			mm	
	L/H Rear Tyre			mm	
<b>4. Description of Damages</b>					
<b>5. General Information</b>					
Accident Date		20/04/2023	Inspection Date		
Survey held at		1102 SERANGOON ROAD S 328196			
Repairer		CCK CAR RENTAL			
<b>5a. Remarks</b>					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					