

(08/11/13) wef

ASS. REC. BY: TayfikREF: US/CT/23006020/Tnp3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

☒ OD ☐ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: \$450

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: \$29K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA ☒ REV ☐ REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: GBF8302X Yr Regn: 20/7, March.Type: M.Car / M.Cycle / Bus / ☒ Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Opel Combo c.c. 1598Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 99988 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WOL6WY41G9594925Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R16R: 195/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 15/6/23Survey held at Vino Auto.Des. of Damages: ☒ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Email workshop repair Unit \$10,000

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS, \$ _____

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : OD/062023/6277

Date : 01-06-2023

Accident Date: 01-06-2023

Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Vehicle Details

Make & Model : Opel COMBO L2H1 1.6 CDTI AT
6DR

Chassis No : W0L6WYL11G9594925

Registration No : GBF8302X

S/N	Description	Date:	Ref No.	Qty	Amount (S\$)
1	FRONT BONNET		0471	1.00	bt \$700.00
2	BONNET RH HINGE		0476	1.00	bt \$90.00
3	BONNET LH HINGE		0475	1.00	bt \$90.00
4	BONNET INSULATOR		0481	1.00	de \$160.00
5	BONNET LOCK		0493	1.00	bt \$140.00
6	BONNET LOCK CABLE		0500	1.00	? \$180.00
7	RH HEADLAMP (ORDER)		0562	1.00	cur \$520.00
8	LH HEADLAMP (ORDER)		0561	1.00	cur \$520.00
9	RH HEADLAMP LOWER PANEL		1000	1.00	bt \$190.00
10	LH HEADLAMP LOWER PANEL		1001	1.00	bt \$190.00
11	FRONT GRILLE		0410	1.00	cur \$330.00
12	FRONT GRILLE EMBLEM		1002	1.00	cur \$350.00
13	FRONT BUMPER		0281	1.00	de \$900.00
14	FRONT BUMPER NO. PLATE GARNISH		0258	1.00	de \$110.00
15	FRONT BUMPER CENTER LOWER GRILLE		0401	1.00	de \$140.00
16	FRONT BUMPER RH SIDE RETAINER		0316	1.00	de \$60.00
17	FRONT BUMPER LH SIDE RETAINER		0315	1.00	de \$60.00
18	FRONT BUMPER SPONGE		0341	1.00	de \$110.00
19	FRONT BUMPER REINFORCEMENT		0340	1.00	bt \$400.00
20	FRONT BUMPER CLIPS		1005	10.00	cur \$20.00
21	FRONT SUPPORT PANEL		0423	1.00	bt \$380.00
22	FRONT SUPPORT PANEL TOP COVER (ORDER)		0286	1.00	ms \$230.00
23	FRONT SUPPORT PANEL TOP COVER CLIPS		1006	10.00	cur \$20.00
24	AIRCON CONDENSER (ORDER)		4465	1.00	bt \$580.00
25	AIRCON CONDENSER DISCHARGE PIPE (ORDER)		1007	1.00	? \$460.00
26	AIRCON CONDENSER RECEIVER PIPE (ORDER)		1008	1.00	? \$460.00
27	AIRCON CONDENSER SUCTION PIPE (ORDER)		1009	1.00	? \$320.00
28	RADIATOR (ORDER)		7761	1.00	? \$670.00
29	RADIATOR TOP HOSE		7775	1.00	? \$110.00
30	RADIATOR LOWER HOSE		7776	1.00	? \$120.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	RADIATOR RH SIDE GUIDE	1010	1.00	\$90.00	?
32	RADIATOR LH SIDE GUIDE	1011	1.00	\$90.00	?
33	RADIATOR TOP BRACKET	1012	1.00	\$30.00	?
34	RADIATOR AIR DUCT (ORDER)	7737	1.00	\$220.00	?
35	RADIATOR TOP BUSH	7769	1.00	\$30.00	?
36	RADIATOR LOWER BUSH	7771	1.00	\$30.00	?
37	RADIATOR FAN MOTOR ASSY (ORDER)	7789	1.00	\$700.00	?
38	RADIATOR SPARE TANK	7787	1.00	\$260.00	do-
39	INTER COOLER (ORDER)	8739	1.00	\$900.00	?
40	INTER COOLER INLET PIPE	8742	1.00	\$370.00	?
41	INTER COOLER OUTLET PIPE	8741	1.00	\$370.00	?
42	AIR CLEANER BOX ASSY (ORDER)	7735	1.00	\$560.00	?
43	AIR CLEANER BOX TOP HOSE	1016	1.00	\$310.00	?
44	WIPER TANK	1435	1.00	\$280.00	?
45	BATTERY TRAY	9631	1.00	\$70.00	?
46	FUSE BOX TOP COVER	9663	1.00	\$120.00	?
47	FUSE BOX LOWER COVER	9660	1.00	\$270.00	?
48	FRONT LH FENDER	0741	1.00	\$370.00	bl-
49	FRONT LH FENDER INNER SHIELD	1131	1.00	\$150.00	de-
50	FRONT FENDER INNER SHIELD CLIPS	1013	20.00	\$40.00	wg-
51	FRONT WINDSCREEN GLASS	1401	1.00	\$900.00	cur
52	FRONT WINDSCREEN GLASS MOULDING	1015	1.00	\$100.00	ag-
53	DASHBOARD (ORDER)	4331	1.00	\$2,200.00	dis
54	STEERING AIRBAG (ORDER)	7445	1.00	\$1,400.00	cut-
55	PASSENGER AIRBAG (ORDER)	4325	1.00	\$1,400.00	aut-
56	STEERING CLOCK SPRING SENSOR (ORDER)	1017	1.00	\$700.00	aut-
57	FRONT RH SEAT BELT (ORDER)	4654	1.00	\$600.00	aut-
58	FRONT LH SEAT BELT (ORDER)	4653	1.00	\$600.00	aut-
59	AIRBAG SENSOR (ORDER)	1018	1.00	\$680.00	aut-
60	AIRBAG ECU (ORDER)	1019	1.00	\$1,700.00	aut-
				\$24,150.00	
61	FRONT NO. PLATE	1020	1.00	\$40.00	bt-
62	BATTERY	1021	1.00	\$180.00	x
63	WINDSCREEN GUM	1022	1.00	\$80.00	ag-
64	COOLANT	1023	1.00	\$80.00	?
65	TO RESET AIRBAG SYSTEMS	1025	1.00	\$280.00	200
66	TO REFILL AIRCON GAS	1026	1.00	\$180.00	100
67	TO REPAIR DAMAGES		1.00	\$1,373.40	} Antodeck
68	TO SPRAY PAINTING		1.00	\$1,241.19	

Taufik 97495749

Not Antodeck 15/10/13 2/145

Ex 450 1/5 Resurvey after repair
10 days. - To check repair unit.
taufik @ khantowm.

Subtotal w/o GST:

\$27,604.59

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Company

Owner ID:

517H

Vehicle Details

Vehicle No.:

GBF8302X

Vehicle to be Exported:

No

Intended Deregistration Date:

01 Jun 2023

Vehicle Make:

OPEL

Vehicle Model:

COMBO L2H1 1.6 CDTI AT 6DR

Primary Colour:

Silver

Manufacturing Year:

2016

Engine No.:

263A50007653051

Chassis No.:

W0L6WYL11G9594925

Maximum Power Output:

-

Open Market Value:

\$21,135.00

Original Registration Date:

20 Mar 2017

First Registration Date:

20 Mar 2017

Transfer Count:

0

Actual ARF Paid:

\$1,057.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

19 Mar 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$46,729.00

COE Rebate Amount:

\$17,749.00

Total Rebate Amount:

\$17,749.00

The information contained herein is correct as at 01 Jun 2023

OK