

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 16 Jun 2023

Preliminary Advice

Vehicle No	: GBF8302X	Accident Date	: 31/05/2023
Make	: OPEL COMBO L2H1	Policy No.	: DMCVSNA00027382302
Assignment Date	: 14/06/2023	Excess	: S\$450.00
Date of Inspection	: 15/06/2023	Est. Duration of Repair	: 10
Inspection At	: VIN'S MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE, #03-03, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,604.59
Revised Amount	:S\$	20,424.59
Check Items (Estimated)	:S\$	6,840.00
Total	:S\$	27,264.59

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	32,000.00
COE / PARF Rebate	:S\$	17,749.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,251.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :repairer able to repair the vehicle at \$13,000.00 on lump sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.