

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : China Taiping Insurance
(Singapore) Pte Ltd
3 Anson Road
#15-00 Springleaf Tower
Singapore 079909

Claim Details

Case Ref. No. : OD/062023/6277
Date : 01-06-2023

Accident Date: 01-06-2023

DK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Vehicle Details

Make & Model : Opel COMBO L2H1 1.6 CDTI AT
6DR
Chassis No : W0L6WYL11G9594925
Registration No : GBF8302X

S/N	Description	Date:	Ref No.	Qty	Amount (\$)
1	FRONT BONNET		0471	1.00	bt \$700.00
2	BONNET RH HINGE		0476	1.00	bt \$90.00
3	BONNET LH HINGE		0475	1.00	bt \$90.00
4	BONNET INSULATOR		0481	1.00	de \$160.00
5	BONNET LOCK		0493	1.00	bt \$140.00
6	BONNET LOCK CABLE		0500	1.00	? \$180.00
7	RH HEADLAMP (ORDER)		0562	1.00	cur \$520.00
8	LH HEADLAMP (ORDER)		0561	1.00	cur \$520.00
9	RH HEADLAMP LOWER PANEL		1000	1.00	bt \$190.00
10	LH HEADLAMP LOWER PANEL		1001	1.00	bt \$190.00
11	FRONT GRILLE		0410	1.00	cur \$330.00
12	FRONT GRILLE EMBLEM		1002	1.00	cur \$350.00
13	FRONT BUMPER		0281	1.00	de \$900.00
14	FRONT BUMPER NO. PLATE GARNISH		0258	1.00	de \$110.00
15	FRONT BUMPER CENTER LOWER GRILLE		0401	1.00	de \$140.00
16	FRONT BUMPER RH SIDE RETAINER		0316	1.00	de \$60.00
17	FRONT BUMPER LH SIDE RETAINER		0315	1.00	de \$60.00
18	FRONT BUMPER SPONGE		0341	1.00	de \$110.00
19	FRONT BUMPER REINFORCEMENT		0340	1.00	bt \$400.00
20	FRONT BUMPER CLIPS		1005	10.00	de \$20.00
21	FRONT SUPPORT PANEL		0423	1.00	bt \$380.00
22	FRONT SUPPORT PANEL TOP COVER (ORDER)		0286	1.00	ms \$230.00
23	FRONT SUPPORT PANEL TOP COVER CLIPS		1006	10.00	cur \$20.00
24	AIRCON CONDENSER (ORDER)		4465	1.00	bt \$580.00
25	AIRCON CONDENSER DISCHARGE PIPE (ORDER)		1007	1.00	? \$460.00
26	AIRCON CONDENSER RECEIVER PIPE (ORDER)		1008	1.00	? \$460.00
27	AIRCON CONDENSER SUCTION PIPE (ORDER)		1009	1.00	? \$320.00
28	RADIATOR (ORDER)		7761	1.00	? \$670.00
29	RADIATOR TOP HOSE		7775	1.00	? \$110.00
30	RADIATOR LOWER HOSE		7776	1.00	? \$120.00

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

31	RADIATOR RH SIDE GUIDE	1010	1.00	\$90.00 ?
32	RADIATOR LH SIDE GUIDE	1011	1.00	\$90.00 ?
33	RADIATOR TOP BRACKET	1012	1.00	\$30.00 ?
34	RADIATOR AIR DUCT (ORDER)	7737	1.00	\$220.00 ?
35	RADIATOR TOP BUSH	7769	1.00	\$30.00 ?
36	RADIATOR LOWER BUSH	7771	1.00	\$30.00 ?
37	RADIATOR FAN MOTOR ASSY (ORDER)	7789	1.00	\$700.00 ?
38	RADIATOR SPARE TANK	7787	1.00	\$260.00 de
39	INTER COOLER (ORDER)	8739	1.00	\$900.00 ?
40	INTER COOLER INLET PIPE	8742	1.00	\$370.00 ?
41	INTER COOLER OUTLET PIPE	8741	1.00	\$370.00 ?
42	AIR CLEANER BOX ASSY (ORDER)	7735	1.00	\$560.00 ?
43	AIR CLEANER BOX TOP HOSE	1016	1.00	\$310.00 ?
44	WIPER TANK	1435	1.00	\$280.00 ?
45	BATTERY TRAY	9631	1.00	\$70.00 ?
46	FUSE BOX TOP COVER	9663	1.00	\$120.00 ?
47	FUSE BOX LOWER COVER	9660	1.00	\$270.00 ?
48	FRONT LH FENDER	0741	1.00	\$370.00 bl-
49	FRONT LH FENDER INNER SHIELD	1131	1.00	\$150.00 de
50	FRONT FENDER INNER SHIELD CLIPS	1013	20.00	\$40.00 ur
51	FRONT WINDSCREEN GLASS	1401	1.00	\$900.00 cur
52	FRONT WINDSCREEN GLASS MOULDING	1015	1.00	\$100.00 ur
53	DASHBOARD (ORDER)	4331	1.00	\$2,200.00 dis
54	STEERING AIRBAG (ORDER)	7445	1.00	\$1,400.00 cut
55	PASSENGER AIRBAG (ORDER)	4325	1.00	\$1,400.00 aut
56	STEERING CLOCK SPRING SENSOR (ORDER)	1017	1.00	\$700.00 aut
57	FRONT RH SEAT BELT (ORDER)	4654	1.00	\$600.00 aut
58	FRONT LH SEAT BELT (ORDER)	4653	1.00	\$600.00 aut
59	AIRBAG SENSOR (ORDER)	1018	1.00	\$680.00 aut
60	AIRBAG ECU (ORDER)	1019	1.00	\$1,700.00 qat-
				\$24,150.00
61	FRONT NO. PLATE	1020	1.00	\$40.00 bt-
62	BATTERY	1021	1.00	\$180.00 x
63	WINDSCREEN GUM	1022	1.00	\$80.00 ur
64	COOLANT	1023	1.00	\$80.00 ?
65	TO RESET AIRBAG SYSTEMS	1025	1.00	\$280.00 200
66	TO REFILL AIRCON GAS	1026	1.00	\$180.00 100
67	TO REPAIR DAMAGES		1.00	\$1,373.40
68	TO SPRAY PAINTING		1.00	\$1,241.19

Subtotal w/o GST:

\$27,604.59

Taufik 97495749

Not Advise 15/10/73 2/145

Ex 450 1/5 Resurvey after repair

10 days.

- To check repair link?
taufik@khantow.com.