

Your Ref:

India International Insurance Pte Ltd
64 Cecil Street #04-00 & #05-00
IOB Building
Singapore 049711

Attn: Motor Claims Department

Dear Sir / Madam

Traffic Along Yishun Avenue 2**Involving** GBF8354X **and** SLK2959X **On** 07/06/2023

We/I, Messers Goldbell Leasing Pte Ltd (ROC No: 199001196N), the registered owners of m/vehicle - GBF8354X at all material times of the above accident. Our/my vehicle was surveyed by “ India Int’nl ” authorized appraiser and we/I based our/my claims on his recommendation for **S\$** 4,700-00 being the repair for 06 Days (Strictly on a Without Prejudice Basis).

We/I have ascertained that you were the insurers of the driver of m/vehicle GBF8354X when the same was involved in the aforesaid accident with our/my m/vehicle — SLK2959X.

We/I whereby you are the insurers of m/vehicle GBF8354X and the driver/owner was caused solely by the negligence of your insured and as a result there of our / my m/vehicle — SLK2959X has suffered loss and damage as follows:

(a) Cost of repairs	S\$	<u>4,700-00</u>
(b) PRI LOU for pre-repair notice 02 days @ S\$ 80-00 [2982 cc]		<u>160-00</u>
(c) LOU Fee for <u>06</u> days @ S\$ 80-00 [2982 cc]		<u>480-00</u>
(d) GIA / LTA search fee		<u>26-75</u>
(e) Towing Fee		<u> </u>
(f) Survey & Report Fee		<u> </u>
Total Amount	S\$	<u>5,366-75</u>

We/I enclose herewith copies of the supporting documents for vehicle no. GBF8354X as follows:-

- (i) Motor Accident Report & Documents
- (ii) Repair Invoices
- (iii) Survey Report & Receipt

Kindly look into the matter and let us/me hear from you on the settlement of our / my claims as soon as possible.

Please remit us/me your settlement sum in favor of **M/s Liu’s Brother Auto Engineering Workshop**. Forward the cheque to No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883.

Thank You

Yours faithfully,



The owner of m/vehicle GBF8354X
Messers Goldbell Leasing Pte Ltd
cc. Liu’s Bro Auto Engrg Auto Workshop



Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883

UEN No: 53291793J liusbros@gmail.com

Tel: 67411730

FINAL BILL

Name: India International Insurance Pte Ltd
Address: Motor Claims Department
64 Cecil Street #04-00 & #05-00
IOB Building Singapore 049711

Ref Date: 30-06-2023
Ref No: GBF8354X230607
Vehicle No: GBF8354X
Model / Make: Toyota Hiace
Capacity: 2982 cc DX 3.0 M

Item #	Damaged Area	Description	Unit Price	Qty	Estimation / Quotation	N / SN	Cost Of Repair
1	Rear	Tailgate	\$ 2,051.60	1	\$ 2,051.60		\$ -
2		Tailgate Inner Lock	\$ 359.00	1	\$ 359.00		\$ -
3		Tailgate Rubber	\$ 426.70	1	\$ 426.70		\$ -
4		Tailgate "70 KM/H" Sticker	\$ 15.00	1	\$ 15.00	SN	\$ -
5		Tailgate "8 PAX" Sticker	\$ 15.00	1	\$ 15.00	SN	\$ -
6		Tailgate "Toyota Logo" Motif	\$ 167.00	1	\$ 167.00		\$ -
7		Number Plate & Base	\$ 48.00	1	\$ 48.00	SN	\$ -
8		Tailgate Windscreen Glass Moulding	\$ 219.00	1	\$ 219.00		\$ -
9		Tailgate Windscreen Glass Sealant	\$ 50.00	1	\$ 50.00	SN	\$ -
10		Bumper	\$ 599.30	1	\$ 599.30		\$ -
11		Bumper Clips 1 set	\$ 48.00	1	\$ 48.00	SN	\$ -
12		Bumper Reverse Sensor	\$ 220.00	1	\$ 220.00	SN	\$ -
13		Bumper Step Panel	\$ 362.30	1	\$ 362.30	SN	\$ -
14		End Panel Inner	\$ 936.20	1	\$ 936.20		\$ -
15		End Panel Outer	\$ 566.10	1	\$ 566.10		\$ -
16		End Panel Sealant	\$ 50.00	1	\$ 50.00	SN	\$ -
17		Spare Tyre Carrier	\$ 345.20	1	\$ 345.20		\$ -
18	Rear Rh	Bumper Bracket	\$ 202.00	1	\$ 202.00		\$ -
19		Tail Lamp	\$ 365.10	1	\$ 365.10		\$ -
20		Corner Panel	\$ 185.80	1	\$ 185.80		\$ -
21		"Corporate" Advertisement & Artwork			\$ 300.00	SN	\$ -
22		Remove and refix rear tailgate components & wiper mechanism			\$ 80.00		\$ -
23		Remove & reinstall Tailgate Glass to facilitate repairs			\$ 120.00		\$ -
24		Remove and refix rear bumper reverse sensor			\$ 80.00		\$ -
25		Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc			\$ 1,000.00		\$ -
26		To putty & spray painting & including touch up paint on accident affected areas			\$ 700.00		\$ -
27		To apply Rust Proofing , reseal tuff-coating treatment on accident area			\$ 50.00		\$ -

Total Parts & Labour of estimate for damaged vehicle

\$ 9,561.30

Total amount in Parts By Parts Basis for repaired vehicle

\$ 4,700.00

SDL Four Thousand Seven Hundred Only



Liu's Bro Auto Engrg Wks

Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 12 Jun 2023 / 15:32:15
Receipt Date/Time : 12 Jun 2023 / 15:32:14

Tax Invoice/Receipt

Receipt No. : ITNET-00000-230612-002718

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLK2959X As at 07 Jun 2023/15:34:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SLK2959X Enquiry Fee 20230612153104449774	24.77	1.98	26.75
Sub-Total		24.77	1.98	26.75
Total Before Rounding		24.77	1.98	26.75
Rounding Difference				0.00
Total Amount Payable				26.75
Paid By				
426588XXXXXX1485		eNETS Credit Card		26.75
Total				26.75
Cash Change				0.00
Tendered Amount				26.75
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.