



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLZ1241K

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

Vehicle & Document Information

WIP No 10578
Reg No/Reg Date SLZ1241K / 24/04/2018
Date In/Mileage 0
Chassis No WDD1173422N634966
Engine No 27091031573418
Make/Model MB/MB CLA 180 COUPE (C117) "FACELIFT"
Colour/Trim 021 149 Polar White/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
WA000001	Credit	12/06/2023/ 18:46	YK	395 / Yik Chan Hoe				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
Z REQUEST								
Customer Request								
M BPNSUN								
POLICY NO/ACC DATE : SP2001256235-01 // 10/06/2023								
DRIVE IN/EXCESS : 12/06/2023 // TBA								
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
S BPNSUB								
1 PC FRONT NO PLATE 64/								60.00
A BPILAB								
PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH								5760? 3840 6720.00
A BPIRES								
RESPRAY FRONT BUMPER, LEFT FRONT FENDER, BOOT LID, REAR BUMPER								3200 3600.00
A BPILAB								
USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET SYSTEM TO STANDARD SETTINGS. NETT							0.10	380.00
A BPILAB								
CHECK HEADLAMP WITH FOCUS ADJUSTMENT. NETT								120.00
A BPILAB								
REMOVE / RENEW / REFIT RADIATOR AND CONDENSER, CHECK COOLING SYSTEM AND AIR-CON SYSTEM WITH RE-GAS. NETT							0.07	? 500.00
A BPILAB								
REMOVE AND REPLACE DRIVER'S AND PASSENGERS' SEAT BELTS								1840 2400.00
REPLACE CONTROL UNITS AND RESET 'SRS' SYSTEM								
M LEFT HEADLAMP UNIT?					1.00	3136.34	00.00	3136.34
M LEFT FRONT FENDER repair					1.00	712.78	00.00	712.78
M LEFT FRONT INTERMEDIATE LAYER?					1.00	18.88	00.00	18.88
M FRONT BUMPER					1.00	1447.62	00.00	1447.62
M FRONT LICENSE PLATE MOLDING de					1.00	124.27	00.00	124.27
M FRONT BUMPER MB EMBLEM					1.00	68.61	00.00	68.61
M FRONT BUMPER GRILLE					1.00	205.76	00.00	205.76
M FRONT BUMPER LOWER ORNAMENTAL TRIM?					1.00	317.41	00.00	317.41

Confirmed & accepted by

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center

DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SLZ1241K

ALLIANZ INSURANCE SINGAPORE PTE.
LTD.
MOTOR CLAIM DEPARTMENT
79 ROBINSON ROAD
#09-01
SINGAPORE 068897
67143369

WIP No 10578
Reg No/Reg Date SLZ1241K / 24/04/2018
Date In/Mileage 0
Chassis No WDD1173422N634966
Engine No 27091031573418
Make/Model MB/MB CLA 180 COUPE (C117) "FACELIFT"
Colour/Trim 021 149 Polar White/ 041 151-Leather Twi

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WA000001	Credit	12/06/2023/ 18:46	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M LEFT FRONT BUMPER GRILLE	1.00	74.14	00.00	74.14
M FRONT IMPACT ABSORBER	1.00	186.57	00.00	186.57
M FRONT TOP BASIC MOUNTING FOR BUMPER	1.00	184.87	00.00	184.87
M LEFT FRONT BASIC MOUNTING FOR BUMPER	1.00	37.38	00.00	37.38
M RIGHT FRONT BASIC MOUNTING FOR BUMPER	1.00	34.18	00.00	34.18
M FRONT DISTANCE SENSOR	2.00	205.45	00.00	410.90
M PTS SPACER RING	0.00	7.85	00.00	47.10
M FRONT SUPPORT PANEL	1.00	1080.64	00.00	1080.64
M FRONT CROSS MEMBER	1.00	353.78	00.00	353.78
M LEFT FRONT CROSS MEMBER ABSORBER	1.00	173.41	00.00	173.41
M RADIATOR GRILLE	1.00	304.40	00.00	304.40
M RADIATOR GRILLE TRIM GARNISH	1.00	199.16	00.00	199.16
M LEFT RADIATOR GRILLE TRIM SRIP	1.00	90.16	00.00	90.16
M RIGHT RADIATOR GRILLE TRIM SRIP	1.00	90.16	00.00	90.16
M RADIATOR GRILLE MERCEDES STAR CARRIER	1.00	82.12	00.00	82.12
M RADIATOR GRILLE MERCEDES STAR	1.00	145.89	00.00	145.89
M RIGHT FRONT SEAT BELT	1.00	632.21	00.00	632.21
M LEFT REAR SEAT BELT	1.00	404.80	00.00	404.80
M RIGHT REAR SEAT BELT	1.00	404.80	00.00	404.80
M SRS CONTROL UNIT	1.00	863.89	00.00	863.89
M SRS ACCELERATION SENSOR	2.00	173.78	00.00	347.56
M BOOT LID	1.00	2220.97	00.00	2220.97
M BOOT LID W/STRIP	1.00	206.92	00.00	206.92
M BOOT LID INTERMEDIATE LAYER	2.00	5.12	00.00	10.24
M BOOT LID RUBBER STOPPER	2.00	9.74	00.00	19.48
M BOOT LID RETAINER WEDGE	2.00	17.87	00.00	35.74
M GROMMET	3.00	2.73	00.00	8.19
M BOOT LID MERCEDES STAR	1.00	52.05	00.00	52.05
M BOOT LID CLA180 MODEL PLATE	1.00	99.90	00.00	99.90
M RIVETED NUT	4.00	4.43	00.00	17.72
M BOOT LID LOCK	1.00	306.88	00.00	306.88
M REAR CROSS MEMBER	1.00	669.12	00.00	669.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer
Signature: Yik Chan Hoe
Cycle & Carriage Industries Ltd
Repair & Repair Center
DID: 6771 4353 HP: 6186 5109 Fax: 6872 1272
Email: chanhoe.yik@cycyclecarriage.com.sg

Nett 29,607.00
8% GST on 29607.00 2368.56

Authorized signatory and company stamp

Total Payable 31,975.56

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6298 1818