

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 16 Jun 2023

Preliminary Advice

Vehicle No	: SLZ1241K	Accident Date	: 10/06/2023
Make	: MERCEDES-BENZ CLA180	Policy No.	: SP2001256235
Assignment Date	: 15/06/2023	Excess	: S\$0.00
Date of Inspection	: 14/06/2023	Est. Duration of Repair	: 8
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,607.00
Revised Amount	:S\$	16,101.06
Check Items (Estimated)	:S\$	8,553.16
Total	:S\$	24,654.22
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	107,000.00
COE / PARF Rebate	:S\$	39,984.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,016.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :the vehicle repair on part by parts basis.due to the workshop is agent workshop.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.