

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/AIS23006027/KNP3Q2**Date:** 03/07/2023**REFERENCE**

Handling Insurer: Allianz Insurance Singapore Pte. Ltd.

Policy No:

**Claimant Vehicle No :** SKL1934E**Insured Vehicle No :** SMX1029G

Date of Loss: 10/06/2023

Nature of Claim: TP Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE**Reg No: **SKL1934E**

Make &amp; Model: VOLKSWAGEN GOLF, 1.4 (A)

Engine No: CXS011801

Reg. Date: 08/10/2013 (Man. Year: 2013)

Chassis No: WVVZZZAUZEW033324

Colour: Metallic Pearl White

Odometer: 172405 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 8 mm

Rear Left Side: Pirelli 8 mm

Front Right Side: Pirelli 8 mm

Rear Right Side: Pirelli 8 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,738.10	3,833.10	905.00	19.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,850.00	1,580.00	270.00	14.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,588.10</b>	<b>5,413.10</b>	<b>1,175.00</b>	<b>17.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,800.00</b>		
<b>Nett Amount (S\$)</b>	<b>6,588.10</b>	<b>3,800.00</b>	<b>2,788.10</b>	<b>42.32</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

**INSPECTION**

Date of Assignment: 13/06/2023

Date Inspected: 13/06/2023

Inspected At: 160 SIN MING DRIVE  
#06-20 SIN MING AUTOCITY  
SINGAPORE 575722  
Repairer: RC AUTO (HQ)

Estimated Period of Repair: 5.0 days

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Jun 2023)
Parts:	144	VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL1934E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	1,550.00 FL	*1,550.00 FL
2	1		*REAR BOOTLID EMBLEM (LED)	Dented	55.00 FL	*55.00 FL
3	1		*REAR BUMPER	Buckled	1,020.00 FL	*1,020.00 FL
4	1		*REAR BUMPER BEAM	Bent	480.00 FL	*480.00 FL
5	1		*REAR BOOTLID LOCK	Dented	225.00 FL	*225.00 FL
6	1		*REAR BOOTLID HANDLE	Serviceable	450.00 FL	*- FL
7	1		*FRONT BUMPER	Buckled / Cracked	890.00 FL	*890.00 FL
8	1		*REAR BOOTLID EMBLEM (TSI)	Necessary	39.00 FL	*39.00 FL
9	2		*REVERSE SENSOR	Serviceable	500.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					5,209.00	4,259.00
- List Item Discount on L Items 10.00/10.00% (\$\$)					470.90	425.90
Total Parts (\$\$)					4,738.10	3,833.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	SPRAY PAINTING ON AFFECTED PARTS	New	800.00	800.00
2	TO RENEW ABOVE PARTS	New	100.00	60.00
3	TO REINSTATE WINDSCREEN	New	150.00	120.00
4	PANEL BEATING	New	800.00	600.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,850.00</b>	<b>1,580.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >