

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Faiz Rosli

Date: 23 Jun 2023

Preliminary Advice

Insured Vehicle No	: SMX1029G	Accident Date	: 10/06/2023
TP Vehicle No	: SKL1934E	Assignment Date	: 23/06/2023
Make	: VOLKSWAGEN GOLF	Est. Duration of Repair	: 5
Date of Inspection	: 13/06/2023		
Inspection At	: RC AUTO (HQ) 18 SIN MING INDUSTRIAL ESTATE SECTOR A, #01-43 SINGAPORE 575676		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,588.10
Revised Amount	:S\$	5,413.10
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,413.10
Lump Sum Repair	:S\$	3,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.