

## Re: Transporter Fire

Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

Thu 8/6/2023 5:17 PM

To: InnMeng\_Tay <InnMeng\_Tay@sats.com.sg>

Cc: Investigation <investigation@lkkauto.com>; MengFai\_Leow <MengFai\_Leow@sats.com.sg>; Alex\_KohLT <Alex\_KohLT@sats.com.sg>; Saravanan Shunmugham <Saravanan\_Shunmugham@sats.com.sg>

Dear Mr Tay

My colleague Sherwin is assign to this case. Please contact him at 81009370 to arrange for the inspection.

Bryan Ang  
LKK Auto Consultants Pte Ltd

On 8 Jun 2023, at 16:26, InnMeng\_Tay <InnMeng\_Tay@sats.com.sg> wrote:

Hi Bryan,

Can you arrange your team to head down to my site tomorrow?

We are at 34, Changi North Crescent. Singapore 499614.

Thank you  
Best Regards  
**Tay Inn Meng**  
Assistant Manager, Maintenance  
SATS LTD.  
t 65 6548 2007 m 65 96534885  
e InnMeng\_Tay@sats.com.sg  
sats.com.sg

A SATS Group company



---

**From:** Bryan Ang (LKKAuto) <bryanang@lkkauto.com>

**Sent:** Thursday, June 8, 2023 3:38 PM

**To:** InnMeng\_Tay <InnMeng\_Tay@sats.com.sg>; Investigation <investigation@lkkauto.com>

**Cc:** MengFai\_Leow <MengFai\_Leow@sats.com.sg>; Alex\_KohLT <Alex\_KohLT@sats.com.sg>; Saravanan Shunmugham <Saravanan\_Shunmugham@sats.com.sg>

**Subject:** RE: Transporter Fire

**CAUTION:** This email originated from outside of the organization. If you find it suspicious, please report using **Report Message > Phishing**

Dear Mr Tay

I refer to your email below.

Our professional fee to provide our opinion on the cause of fire is \$600/- excluding gst. The scope of work will be to inspect the transporter, carry out some groundwork technical analysis and thereafter to put up a written report with photos of our findings.

Due to our work commitments, the estimate timeline of report submission is about 10 to 14 days from date of inspection. We can provide you with our preliminary findings via email about 3 days after the inspection with full report to follow thereafter.

Best Regards,

**Bryan Ang**

**LKK Auto Consultants Pte Ltd**

phone: 6256-3561 | email: [bryanang@lkkauto.com](mailto:bryanang@lkkauto.com)

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** InnMeng\_Tay <[InnMeng\\_Tay@sats.com.sg](mailto:InnMeng_Tay@sats.com.sg)>

**Sent:** Thursday, June 8, 2023 10:17 AM

**To:** Investigation <[investigation@lkkauto.com](mailto:investigation@lkkauto.com)>

**Cc:** MengFai\_Leow <[MengFai\\_Leow@sats.com.sg](mailto:MengFai_Leow@sats.com.sg)>; Alex\_KohLT <[Alex\\_KohLT@sats.com.sg](mailto:Alex_KohLT@sats.com.sg)>;

Saravanan Shunmugham <[Saravanan\\_Shunmugham@sats.com.sg](mailto:Saravanan_Shunmugham@sats.com.sg)>

**Subject:** Transporter Fire

Hi,

Will you be able to quote us for :

1. Forensic Fire Investigation Service

As one of our transporter, having a short circuit on the instrumental cluster area, and causing a very small fire in it.

Thank you

Best Regards

**Tay Inn Meng**

Assistant Manager, Maintenance

SATS LTD.

t 65 6548 2007 m 65 96534885

e [InnMeng\\_Tay@sats.com.sg](mailto:InnMeng_Tay@sats.com.sg)

[sats.com.sg](http://sats.com.sg)

A SATS Group company

<image001.png>