



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : **ECICS LIMITED**
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/062023/6309
Date : 14-06-2023
Accident Date : 13-06-2023

Vehicle Details

Make & Model : Honda VEZEL 1.5X CVT
Chassis No : RU11311203
Registration No : SMH3634E

S/N	Description	Qty	Amount (\$S)
1	FRONT BONNET	1.00	it \$520.00
2	BONNET RH HINGE	1.00	XR \$30.00
3	BONNET LH HINGE	1.00	XR \$30.00
4	BONNET TOP RUBBER @ CENTER	1.00	X \$30.00
5	BONNET LOCK	1.00	can \$70.00
6	BONNET LOCK COVER	1.00	cur \$30.00
7	RH HEADLAMP	1.00	cur \$1,100.00
8	LH HEADLAMP	1.00	cur \$1,100.00
9	RH HEADLAMP LOWER BRACKET	1.00	? \$40.00
10	LH HEADLAMP LOWER BRACKET	1.00	? \$40.00
11	FRONT GRILLE	1.00	cur \$220.00
12	FRONT GRILLE OUTER CHROME GARNISH	1.00	cur \$170.00
13	FRONT GRILLE EMBLEM	1.00	ur \$20.00
14	FRONT GRILLE RH SUPPORT BRACKET	1.00	cur \$20.00
15	FRONT GRILLE LH SUPPORT BRACKET	1.00	? \$20.00
16	FRONT BUMPER	1.00	cur \$680.00
17	FRONT BUMPER TOWING COVER	1.00	cur \$20.00
18	FRONT BUMPER CENTER LOWER GRILLE	1.00	? \$70.00
19	FRONT BUMPER LOWER PAD	1.00	X \$220.00
20	FRONT BUMPER LOWER LIP	1.00	? \$110.00
21	FRONT BUMPER RH SIDE RETAINER	1.00	de \$10.00
22	FRONT BUMPER REINFORCEMENT	1.00	b7 \$220.00
23	FRONT BUMPER CLIPS	10.00	ur \$20.00
24	WIPER TANK	1.00	? \$50.00
25	FRONT SUPPORT PANEL TOP COVER	1.00	cur \$40.00
26	FRONT SUPPORT PANEL TOP COVER CLIPS	10.00	ur \$20.00
27	RADIATOR RH SIDE GUIDE	1.00	de \$30.00

\$4,930.00

Margin: 10%

\$493.00

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

28	FRONT NO. PLATE	1.00	HA✓	\$40.00
29	FRONT BUMPER PARKING SENSOR	1.00	?	\$280.00
30	TO RESET HEADLAMP SYSTEM	1.00	100	\$280.00
31	TO REPAIR DAMAGES	1.00	500	\$680.00
32	TO SPRAY PAINTING	1.00	600	\$880.00

Subtotal w/o GST: \$7,583.00

Tanpin 97495749
 'wp' not authorised
 Ex: to be advised
 • 4 days 15/6/23 @ 11/50
 p/p Resurvey before paint
 tanpin @ hant.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Issued by Kiara Tan Yun Xi

This is a computer-generated document. No signature is required.