

ASS. REC. BY:

REF:

C72/23006043/Knp3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS - SI

: Fixing

: Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

[illegible]

ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3

#01-80 SINGAPORE 159723

TEL:62715133 62717433 FAX:62745715

ESTIMATE REPAIR

China Taiping Insurance (S) Pte Ltd

Date: 23.6.2023

Owner's Name : Goh Heok Seng

Vehicle No : SLP9483D

Vehicle Make & Model : Toyota Allion 1.5 A

Registration Date : 26 Nov 2008 (YOM 2008) COE Expiry Date 25 Nov 2028

Claim Type: Third Party Claim

Chassis No: NZT2603033553

DOA: 11.6.2023

Pg 2

No	Description	Unit	List (\$)
	Special Nett		
	REAR DOOR INNER TRIM BOARD CLIPS	SET	\$ na 35.00 x
	Labour		
1	Spray Painting to All Affected Areas	1	\$ 800.00 400l
2	Labour Remove / Refix Accident Damages parts to knock , jack, cut weld and realign accident affected area	1	\$ 800.00 200l
3	Check Wiring System & Light	1	\$ 100.00 20l
4	To Remove / Refix Inner Compartment To Facilities Repair	1	\$ 150.00 60l
		Total (B) :	\$ 1,885.00
		Grand Total:	\$ 3,872.50