



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer	: ALLIANZ INSURANCE SINGAPORE PTE LTD 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	Document No.	: SQT23001784	Page	1
Registration No	: SLC5952L	Date	: 13. Jun 2023	Customer No.	: WZA011
Chassis No	: JHMGK5850GX202682	Svc Advisor	: LEE CHEN SIN	Engine No	: L15B31021045
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 13. Jun 2023 9:40:47 AM	Surveyor Name	:
Owner's Name	: LAU LI GUAN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 9/6/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:LAU LI GUAN OWNER INSURER:TOKIO MARINE ACC DATE:09/06/2023 SURVEYED BY: DATE: REF NO: TP INSURER:ALLIANZ TP VEH:PD256T						
76208-T5A-J32	MIRROR ASSY,R. <i>cm ✓</i>	1	542.20	25	406.65	32.53	439.18
76201-T5A-J31ZD	SKULL CAP,R.ST <i>cm ✓</i>	1	57.30	25	42.97	3.44	46.41
67324-T5A-003	TAPE SETR.FR.DOOR <i>cm ✓</i>	1	35.90	25	26.92	2.15	29.07
73331-T5A-003	GLASSR.FR.CORNER <i>X</i>	1	227.80	25	170.85	13.67	184.52
73335-T5A-003	RUBBERR.WINDSHIELD DAMPER <i>cm ✓</i>	1	39.40	25	29.55	2.36	31.91
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>cm ✓</i>	1	10.40	25	7.80	0.62	8.42
91513-T5A-003	CLIPFR.CORN WINDSHIELD <i>cm ✓</i>	3	3.90	25	8.77	0.70	9.47
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>cm ✓</i>	1	60.00		60.00	4.80	64.80
	Sum Item				753.51	60.27	813.78
BG42R	REPLACE FR. R QTR GLASS.(N)	1	450.00 <i>✓</i>		450.00 <i>✓</i>	36.00	486.00
BOSUN	SUNDRIES	1	100.00		100.00 <i>✓</i>	8.00	108.00
BKFE12K	REPAIR FR R FENDER & DOOR, RENEW SIDE MIRROR	1	1300.00		1300.00 <i>✓</i>	104.00	1404.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2600.00 <i>975 30 1300</i>		2600.00 <i>✓</i>	208.00	2808.00
	Sum Labor				4450.00	356.00	4806.00
BO-R-COOL-FRQ	SUPPLY & INSTALL SOLAR FILM ON FRONT QTR GLASS. <i>X</i>	1	280.00		280.00	22.40	302.40
	Sum Ext. Service				280.00	22.40	302.40

Printed on 13/6/2023 9:51:03 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: ALLIANZ INSURANCE SINGAPORE PTE LTD 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	Document No.	: SQT23001784	Page	2
Registration No	: SLC5952L	Date	: 13. Jun 2023	Customer No.	: WZA011
Chassis No	: JHMGK5850GX202682	Svc Advisor	: LEE CHEN SIN	Engine No	: L15B31021045
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 13. Jun 2023 9:40:47 AM	Surveyor Name	:
Owner's Name	: LAU LI GUAN	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 9/6/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
Survey By	<i>Patric - H7 9000068</i>						
Date & Time	<i>06/07/23 @ 1240</i>						
Excess							
Status							
Signature	<i>Resy after repair</i>						
					Total Amount	5,483.51	438.67
					Total (Inclusive of GST)		5,922.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 13/6/2023 9:51:03 AM
 This is a computer generated invoice. No signature is required.
 Part prices are subjected to change without notice.
 The above estimated cost of repair do not include any unforeseen damages
 GST Amount is calculated from individual line(s).
 An amount of \$63.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00
 However, if the repairs are subsequently done at Kah Motor Co Sdn Bhd, it will be refunded.
 All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.