



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: ALLIANZ INSURANCE SINGAPORE PTE 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	<b>Document No.</b>	: SQT23001784	<b>Page</b>	1
<b>Registration No</b>	: SLC5952L	<b>Date</b>	: 13. Jun 2023	<b>Customer No.</b>	: WZA011
<b>Chassis No</b>	: JHMGK5850GX202682	<b>Svc Advisor</b>	: LEE CHEN SIN	<b>Engine No</b>	: L15B31021045
<b>Model</b>	: JAZZ 1.5VTIR CVT 16YM	<b>Date   Time</b>	: 13. Jun 2023 9:40:47 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: LAU LI GUAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 9/6/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER:LAU LI GUAN OWNER INSURER:TOKIO MARINE ACC DATE:09/06/2023 SURVEYED BY: DATE: REF NO: TP INSURER:ALLIANZ TP VEH:PD256T						
<b>76208-T5A-J32</b>	MIRROR ASSY,R.	1	542.20	25	406.65	32.53	439.18
<b>76201-T5A-J31ZD</b>	SKULL CAP,R.ST	1	57.30	25	42.97	3.44	46.41
<b>67324-T5A-003</b>	TAPE SETR.FR.DOOR	1	35.90	25	26.92	2.15	29.07
<b>73331-T5A-003</b>	GLASSR.FR.CORNER	1	227.80	25	170.85	13.67	184.52
<b>73335-T5A-003</b>	RUBBERR.WINDSHIELD DAMPER	1	39.40	25	29.55	2.36	31.91
<b>73525-SYY-000</b>	RUBBERRR QTR W/SHIELD	1	10.40	25	7.80	0.62	8.42
<b>91513-T5A-003</b>	CLIPFR.CORN WINDSHIELD	3	3.90	25	8.77	0.70	9.47
<b>BO-WS-SEALANT</b>	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.80	64.80
				<b>Sum Item</b>	<b>753.51</b>	<b>60.27</b>	<b>813.78</b>
<b>BG42R</b>	REPLACE FR. R QTR GLASS.(N)	1	450.00		450.00	36.00	486.00
<b>BOSUN</b>	SUNDRIES	1	100.00		100.00	8.00	108.00
<b>BKFE12K</b>	REPAIR FR R FENDER & DOOR, RENEW SIDE MIRROR	1	1300.00		1300.00	104.00	1404.00
<b>BP05R</b>	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	2600.00		2600.00	208.00	2808.00
				<b>Sum Labor</b>	<b>4450.00</b>	<b>356.00</b>	<b>4,806.00</b>
<b>BO-R-COOL-FRQ</b>	SUPPLY & INSTALL SOLAR FILM ON FRONT QTR GLASS.	1	280.00		280.00	22.40	302.40
				<b>Sum Ext. Service</b>	<b>280.00</b>	<b>22.40</b>	<b>302.40</b>

Printed on 13/6/2023 9:51:03 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



# QUOTATION

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: ALLIANZ INSURANCE SINGAPORE PTE 12 MARINA VIEW #04-01, ASIA SQUARE TOWER 2 SINGAPORE 018961	<b>Document No.</b>	: SQT23001784	<b>Page</b>	2
<b>Registration No</b>	: SLC5952L	<b>Date</b>	: 13. Jun 2023	<b>Customer No.</b>	: WZA011
<b>Chassis No</b>	: JHMGK5850GX202682	<b>Svc Advisor</b>	: LEE CHEN SIN	<b>Engine No</b>	: L15B31021045
<b>Model</b>	: JAZZ 1.5VTIR CVT 16YM	<b>Date   Time</b>	: 13. Jun 2023 9:40:47 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: LAU LI GUAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 9/6/2023				

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
Survey By	_____						
Date & Time	_____						
Excess	_____						
Status	_____						
Signature	_____						
					<b>Total Amount</b>	5,483.51	438.67
					<b>Total (Inclusive of GST)</b>		<b>5,922.18</b>

**Printed on 13/6/2023 9:51:03 AM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.