

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: \$60FC1380G

Page

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

: MS FIRST CAPITAL INSURANCE LIMITED Customer

#42-0116 RAFFLES QUAY

HONG LEONG BUILDING

SINGAPORE 048581

Registration No

3 SNH363U

Chassis No

: JHMGR3830NS212768

Model

ltem

: JAZZ H-LUXE E-CVT 22YM

Owner's Name Ins Policy No.

04715-TZA-000ZZ

Date of Accident

ONG LI-AN, GLORIA

: 12/6/2023

Document No.

Date

Qtv

)

: SQT23001771

: 12. Jun 2023

Customer No. Svc Advisor

· WZF002

: ANIKKA LAI SWEE KAM

Amount

; 12. Jun 2023 2:27:17 PM

Engine No

: LEB82000371

Date | Time

Surveyor Name

Survey Date ٠

Authorisation Date

Unit Price

Disc %

8% GST **Amount**

Amount incld GST

341.01

15.14

15.14

32.80

3.73

591.21

302.37

1,301.40

108.00

172.80

1080.00

1620.00

TP DIRECT SETTLEMENT (J/NO:

OWNER:

Description

OWNER INSURER:

ACC DATE: SURVEYED BY:

FACE, RR. BUMPER

DATE: REF NO: TP INSURER:

TP VEH:

71630-TZA-003 SPACER, R.RR. BUMPER SIDE 71680-TZA-003 SPACER, L. RR. BUMPER SIDE 33505-TZA-J01 REFLECTOR ASSY, R.RR.

91505-TM8-003 CLIP, BUMPER 04646-TZA-310ZZ PANEL SET, L.RR. OUTSIDE

33550-TZA-J01 TAILLIGHT ASSY,L.

SUNDRIES

WATER

(2P)

2 2.30 1 1

1

1

729.90 373.30

100.00

160.00

1000.00

1500.00

421.00

18.70

18.70

40.50

25 25

25

25

25

25

25

279.97 Sum Item

1205.00 96.40

315.75

14.02

14.02

30.37

3.45

547.42

100.00 8.00 160.00 12.80

25.26

1.12

1.12

2.43

0.28

43.79

22.40

1500.00 120.00 Sum Labor 220.80

1000.00

2760.00

317.20

80.00

2,980.80

Survey By

BOSUN

BML02I

BKBU02R

RP02R

Date & Time

Total Amount

3,965.00

4,282.20

Printed on 13/6/2023 4:36:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice,

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53,50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

INSPECT RR LIGHTING MECHANISMS. PERFORM

REMOVE & RENEW RR BUMPER INCLUDING FITTINGS

SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.