

ASS. REC. BY:

REF:

SMR/ 23006061/Kn

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1.81

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNH 3634

Yr Regn:

09, 22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

c.c

1498

Colour

M.D. Blue

AC:

Insured / Std / NI / NA

Sp. Reading

9078

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMGR 3830NS 212768

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIm or

Tyre Size:

F:

R:

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

12/6/23

D.O.I.

26/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838 Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SNH363U
Chassis No : JHMGR3830NS212768
Model : JAZZ H-LUXE E-CVT 22YM
Owner's Name : ONG LI-AN, GLORIA
Ins Policy No. :
Date of Accident : 12/6/2023

Document No. : SQT23001771 **Page** 1
Date : 12. Jun 2023
Customer No. : WZF002
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : LEB82000371
Date | Time : 12. Jun 2023 2:27:17 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-TZA-000ZZ	FACE,RR.BUMPER	1	421.00	25	315.75	25.26	341.01
71630-TZA-003	SPACER,R.RR.BUMPER SIDE	1	18.70	25	14.02	1.12	15.14
71680-TZA-003	SPACER,L.RR.BUMPER SIDE	1	18.70	25	14.02	1.12	15.14
33505-TZA-J01	REFLECTOR ASSY,R.RR.	1	40.50	25	30.37	2.43	32.80
91505-TM8-003	CLIP,BUMPER	2	2.30	25	3.45	0.28	3.73
04646-TZA-310ZZ	PANEL SET,L.RR.OUTSIDE	1	729.90	25	547.42	43.79	591.21
33550-TZA-J01	TAILLIGHT ASSY,L.	1	373.30	25	279.97	22.40	302.37
Sum Item					1205.00	96.40	1,301.40
BOSUN	SUNDRIES	1	100.00		100.00	8.00	108.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00		160.00	12.80	172.80
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	1000.00		1000.00	80.00	1080.00
BP02R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1500.00		1500.00	120.00	1620.00
Sum Labor					2760.00	220.80	2,980.80

NOT Withheld
Return Bp pain
3 day

205m
80?
6501
5201

Survey By _____
Date & Time _____

I KK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Amount 3,965.00 317.20 4,282.20

Printed on 13/6/2023 4:36:06 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for claim value above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

Signature:
Date: