



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR23006064/Rny3m4 Date: 06/07/2023 Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
<b>Insured Veh.</b>	SMB 1376U	<b>Veh. Inspected</b>	SGA 2133Z
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	BUS/06/23/5017	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	HUA YEN	<b>Assign Date</b>	15/06/2023
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	HONDA ODYSSEY 2.4 EXV SR	<b>c.c</b>	2356
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JHMRC1890KC202225	<b>Colour</b>	BLUE
<b>Odometer</b>	103838 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	215/55R17	DUNLOP	6 mm
<b>L/H Front Tyre</b>	215/55R17	DUNLOP	6 mm
<b>R/H Rear Tyre</b>	215/55R17	DUNLOP	6 mm
<b>L/H Rear Tyre</b>	215/55R17	DUNLOP	6 mm
<b>4. Description of Damages</b>			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.		
<b>5. General Information</b>			
<b>Accident Date</b>	14/06/2023	<b>Inspection Date</b>	26/06/2023
<b>Survey held at</b>	KAH MOTOR CO SDN BERHAD NO. 255 ALEXANDRA ROAD SINGAPORE 159937		
<b>5a. Remarks</b>			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
<b>5b. Estimate Days of Repair</b>			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>