

(08/11/13) wof  
ASS. REC. BY: *[Signature]*

REF: CS/SMR2300664/RNG3

725F

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SGA 21332  
at Workshop m/s KAH MOTOR  
of MERANDA  
Insured: JMR  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	<input checked="" type="checkbox"/>

Bal. or Market Value: 139K  
IDAC Accident Rpt: Consistent?: Yes or No  
GIA / PR Seen: Consistent?: Yes or No  
Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
Lump Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS  
Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
Vehicle: IN / OUT

Veh No: SGA 21332 Yr Regn: 2019 / may  
Type:  M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or  
Make: HONDA ODYSSEY 2.4 EXL S/R.c.c 2356  
Colour: BLUE A/C: Insured / Std / NI / NA  
Sp. Reading: 163838 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: JHMRC1890KC202228  
Gen. Cond: Good /  Fair / Poor / Burnt  
Steering:  Inorder / Jammed / Leaked / Burnt or  
Brake:  Inorder / Jammed / Leaked / Burnt or  
Modi: Nil /  S/Rim / STD A/Rim or  
Tyre Size: F: 215/55R17  
R: \_\_\_\_\_  
BS  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or  
Front R/Bal. 6 mm Rear R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 14/06/23 D.O.I. 26/06/23  
Survey held at KAH MOTOR  
Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
REAR O/S  
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
REPAIN LIMIT - 84K

Date/Time, File Pass to?  : Prel. Report  
 : Final Report

1) Date/Time, File Return to?  
2) \_\_\_\_\_

Days Of Repair: \_\_\_\_\_  
Resurvey No. of Trip: \_\_\_\_\_

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_ )

Add Fee:  : Site Insp (\$ \_\_\_\_\_ )  
 : Interview (\$ \_\_\_\_\_ )  
 : Tech. Invs (\$ \_\_\_\_\_ )  
 : Weekend (\$ \_\_\_\_\_ )

Survey Fee: \_\_\_\_\_  
Transportation: \_\_\_\_\_  
S + RS: \_\_\_\_\_ SI  
Photos  
Others

**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED #42-0116 RAFFLES QUAY HONG LEONG BUILDING SINGAPORE 048581	<b>Document No.</b>	: SQT23001813	<b>Page</b>	1
<b>Registration No</b>	: SGA2133Z	<b>Date</b>	: 15. Jun 2023	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMRC1890KC202225	<b>Svc Advisor</b>	:	<b>Engine No</b>	: K24W72461097
<b>Model</b>	: ODYSSEY 2.4 EXV-S 19YM (EURO 6)	<b>Engine No</b>	: K24W72461097	<b>Date   Time</b>	: 15. Jun 2023 11:39:18 AM
<b>Owner's Name</b>	: KEE GEK CHENG	<b>Date   Time</b>	: 15. Jun 2023 11:39:18 AM	<b>Surveyor Name</b>	:
<b>Ins Policy No.</b>	:	<b>Surveyor Name</b>	:	<b>Survey Date</b>	:
<b>Date of Accident</b>	: 14/6/2023	<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:							
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER <i>de</i>	1	562.00	25	421.50	33.72	455.22	
71512-T6A-901ZA	SPOILER ASSY,R.RR. <i>sun</i>	1	105.60	25	79.20	6.34	85.54	
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m</i>	1	20.40	25	15.30	1.22	16.52	
91505-TM8-003	CLIP,BUMPER <i>m</i>	7	2.30	25	12.07	0.97	13.04	
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE <i>requir</i>	1	1001.10	25	750.82	60.07	810.89	
33500-T6A-J51	LIGHT ASSY,R.TAIL <i>br</i>	1	897.20	25	672.90	53.83	726.73	
42700-T6A-J43	WHEEL,DISK AL 17X7JJ <i>X</i>	1	904.80	25	678.60	54.29	732.89	
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>X</i>	2	10.40	25	15.60	1.25	16.85	
73810-T6A-003	SEALR.QUARTER GLASS <i>X</i>	1	37.60	25	28.20	2.26	30.46	
91501-SMA-003	CLIP AQTR. <i>X</i>	1	3.20	25	2.40	0.19	2.59	
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>X</i>	1	4.10	25	3.07	0.25	3.32	
91513-S70-003	CLIPL <i>X</i>	1	4.10	25	3.07	0.25	3.32	
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>X</i>	1	60.00		60.00	4.80	64.80	
					<b>Sum Item</b>	<b>2742.73</b>	<b>219.44</b>	<b>2,962.17</b>
BOSUN	SUNDRIES	1	110.00		<i>30</i> <del>110.00</del>	8.80	118.80	
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		<i>180</i> <del>250.00</del>	20.00	270.00	
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		<i>X</i> <del>650.00</del>	52.00	702.00	

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

**Customer** : MS FIRST CAPITAL INSURANCE LIMITED  
 #42-0116 RAFFLES QUAY  
 HONG LEONG BUILDING  
 SINGAPORE 048581

**Registration No** : SGA2133Z  
**Chassis No** : JHMRC1890KC202225  
**Model** : ODYSSEY 2.4 EXV-S 19YM (EURO 6)  
**Owner's Name** : KEE GEK CHENG  
**Ins Policy No.** :  
**Date of Accident** : 14/6/2023

**Document No.** : SQT23001813 **Page** 2  
**Date** : 15. Jun 2023  
**Customer No.** : WZF002  
**Svc Advisor** :  
**Engine No** : K24W72461097  
**Date | Time** : 15. Jun 2023 11:39:18 AM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST		
GYG31R	REMOVE & INSTALL RIGHT REAR QUARTER GLASS X	1	480.00		480.00	38.40	518.40		
BKDR32R	REMOVE & INSTALL RR R SLIDING DOOR. X	1	650.00		650.00	52.00	702.00		
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. X (N)	1	1500.00		1500.00	120.00	1620.00		
BPBODY	REMOVE & TRANSFER TYRE TO NEW RIM. X	1	60.00		60.00	4.80	64.80		
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	4000.00	1300	4000.00	320.00	4320.00		
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	1	3000.00	1560	3000.00	240.00	3240.00		
BOJSE	BODY JOINT SEALANT.	1	120.00	X	120.00	9.60	129.60		
<b>Sum Labor</b>					<b>10820.00</b>	<b>865.60</b>	<b>11,685.60</b>		
<b>BO-WHEEL ALIGN X4 WHEEL ALIGNMENT X4</b>					1	220.00	220.00	17.60	237.60
<b>Sum Ext. Service</b>					<b>220.00</b>	<b>17.60</b>	<b>237.60</b>		

Survey By: Rasau - Hp 90010068  
 Date & Time: 26/06/23 @ 1410  
 Excess: \_\_\_\_\_  
 Status: \_\_\_\_\_  
 Signature: [Signature]

*5 days  
 Reg & paint*

**Total Amount** 13,782.73 1,102.64 14,885.37  
**Total (Inclusive of GST)** 14,885.37

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Printed on 15/6/2023 11:52:37 AM  
 This is a computer generated invoice. No signature is required.  
 Part prices are subjected to change without notice.  
 The above estimated cost of repair do not include any unforeseen damages.  
 GST Amount is calculated from individual line(s).  
 An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
 However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.  
 All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

## Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	725F
Vehicle No.:	SGA2133Z
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2023
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	K24W72461097
Chassis No.:	JHMRC1890KC202225
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,027.00
Original Registration Date:	27 May 2019
First Registration Date:	27 May 2019
Transfer Count:	0
Actual ARF Paid:	\$35,438.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2029
PARF Rebate Amount:	\$26,578.00
COE Expiry Date:	26 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,010.00
COE Rebate Amount:	\$28,354.00
<b>Total Rebate Amount:</b>	<b>\$54,932.00</b>

The information contained herein is correct as at 29 Jun 2023

OK


# Honda Odyssey 2.4A EXV-S Sunroof

**\$138,200** Instalment \$1,603/mth

Apply for 2.28% loan

Shortlist

Get Warranty



## Overview

## Financial

## Photo

## Research

Depreciation

*i* \$20,140 / year

Reg. Date

18-Jun-2019

(5yrs 11mths 19days COE left)

Manufactured

*i* 2019

Mileage

80,622 km (20k / year)

Transmission

Auto

Engine Cap

2,356 cc

Road Tax

*i* \$1,630 / year

Power

129.0 kW (172 bhp)

Curb Weight

*i* 1,858 kg

COE

*i* \$48,010

OMV

*i* \$31,284

ARF

*i* \$35,798

Dereg Value

*i* \$55,523 as of today

No. of Owners

*i* 1

Type of Veh

MPV