

(08/11/13)

wef

ASS. REC. BY:

REF:

CS/SMR2300664/RNY3

725F

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGA 21332

at Workshop m/s

KAH MOTOR

of

MERANDA

Insured:

SMR

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

139K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 84K

Veh No:

SGA 21332

Yr Regn:

2014 / mayType: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

HONDA ODYSSEY 2.4 EXL S/R C.C. 2356

Colour:

BLUE

A/C:

Insured / Std / NI / NA

Sp. Reading

163838

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JHMRC1890KC202228Gen. Cond: Good ☒ Fair ☐ Poor ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

215/55R17

R:

BS ☒ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

14/06/23

D.O.I.

26/06/23

Survey held at

KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

We will be advising our principal a cost of repair P/P \$4,568.26 /- with 05 days

(red, \$9511.76, 67%)

Date/Time, File Pass to?



: Preli. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format:

Lump Sum / I.B.I. (\$

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
 #42-0116 RAFFLES QUAY
 HONG LEONG BUILDING
 SINGAPORE 048581

Registration No : SGA2133Z
 Chassis No : JHMRC1890KC202225
 Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
 Owner's Name : KEE GEK CHENG
 Ins Policy No :
 Date of Accident : 14/6/2023

Document No. : SQT23001813 Page 1
 Date : 15. Jun 2023
 Customer No. : WZF002
 Svc Advisor :
 Engine No : K24W72461097
 Date | Time : 15. Jun 2023 11:39:18 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER <i>de</i>	1	562.00	25	421.50	33.72	455.22
71512-T6A-901ZA	SPOILER ASSY,R.RR. <i>sun</i>	1	105.60	25	79.20	6.34	85.54
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m</i>	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER <i>m</i>	7	2.30	25	12.07	0.97	13.04
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE <i>requir</i>	1	1001.10	25	750.82	60.07	810.89
33500-T6A-J51	LIGHT ASSY,R.TAIL <i>br</i>	1	897.20	25	672.90	53.83	726.73
42700-T6A-J43	WHEEL,DISK AL 17X7JJ <i>X</i>	1	904.80	25	678.60	54.29	732.89
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>X</i>	2	10.40	25	15.60	1.25	16.85
73810-T6A-003	SEALR.QUARTER GLASS <i>X</i>	1	37.60	25	28.20	2.26	30.46
91501-SMA-003	CLIP AQTR. <i>X</i>	1	3.20	25	2.40	0.19	2.59
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>X</i>	1	4.10	25	3.07	0.25	3.32
91513-S70-003	CLIPL <i>X</i>	1	4.10	25	3.07	0.25	3.32
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>X</i>	1	60.00		60.00	4.80	64.80
Sum Item					2742.73	219.44	2,962.17
BOSUN	SUNDRIES	1	110.00		<i>30</i> 110.00	8.80	118.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		<i>180</i> 250.00	20.00	270.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		<i>X</i> 650.00	52.00	702.00

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)
Service and Body Repair
Tel: +65 6841 3838
Website: www.honda.com.sg
For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SGA2133Z
Chassis No : JHMRC1890KC202225
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : KEE GEK CHENG
Ins Policy No. :
Date of Accident : 14/6/2023

Document No. : SQT23001813
Date : 15. Jun 2023
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72461097
Date | Time : 15. Jun 2023 11:39:18 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
GYG31R	REMOVE & INSTALL RIGHT REAR QUARTER GLASS X	1	480.00		480.00	38.40	518.40
BKDR32R	REMOVE & INSTALL RR R SLIDING DOOR. X	1	650.00		650.00	52.00	702.00
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. X (N)	1	1500.00		1500.00	120.00	1620.00
BPBODY	REMOVE & TRANSFER TYRE TO NEW RIM. X	1	60.00		60.00	4.80	64.80
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	4000.00	1300	4000.00	320.00	4320.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	1	3000.00	1560	3000.00	240.00	3240.00
BOJSE	BODY JOINT SEALANT.	1	120.00	X	120.00	9.60	129.60
Sum Labor					10820.00	865.60	11,685.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	220.00		220.00	17.60	237.60
Sum Ext. Service					220.00	17.60	237.60

Survey By: Rasul - Hp 90010068
Date & Time: 26/06/23 @ 1410
Excess: _____
Status: _____
Signature: [Signature]

5 days
Reg & print

Total Amount 13,782.73 1,102.64 14,885.37
Total (Inclusive of GST) 14,885.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	725F
Vehicle No.:	SGA2133Z
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Jun 2023
Vehicle Make:	HONDA
Vehicle Model:	ODYSSEY 2.4 EXV-S CVT SR
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	K24W72461097
Chassis No.:	JHMRC1890KC202225
Maximum Power Output:	129.0 kW (172 bhp)
Open Market Value:	\$31,027.00
Original Registration Date:	27 May 2019
First Registration Date:	27 May 2019
Transfer Count:	0
Actual ARF Paid:	\$35,438.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 May 2029
PARF Rebate Amount:	\$26,578.00
COE Expiry Date:	26 May 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,010.00
COE Rebate Amount:	\$28,354.00
Total Rebate Amount:	\$54,932.00

The information contained herein is correct as at 29 Jun 2023

OK

Honda Odyssey 2.4A EXV-S Sunroof

\$138,200 Instalment \$1,603/mth

Apply for 2.28% loan

Shortlist

Get Warranty



Overview

Financial

Photo

Research

Depreciation	\$20,140 / year
Reg. Date	18-Jun-2019 (5yrs 11mths 19days COE left)
Manufactured	2019
Mileage	80,622 km (20k / year)
Transmission	Auto
Engine Cap	2,356 cc
Road Tax	\$1,630 / year
Power	129.0 kW (172 bhp)
Curb Weight	1,858 kg
COE	\$48,010
OMV	\$31,284
ARF	\$35,798
Dereg Value	\$55,523 as of today
No. of Owners	1
Type of Veh	MPV