



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SGA2133Z
Chassis No : JHMRC1890KC202225
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : KEE GEK CHENG
Ins Policy No. :
Date of Accident : 14/6/2023

Document No. : SQT23001813 Page 1
Date : 15. Jun 2023
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72461097
Date | Time : 15. Jun 2023 11:39:18 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER <i>de</i>	1	562.00	25	421.50	33.72	455.22
71512-T6A-901ZA	SPOILER ASSY,R.RR. <i>sun</i>	1	105.60	25	79.20	6.34	85.54
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m</i>	1	20.40	25	15.30	1.22	16.52
91505-TM8-003	CLIP,BUMPER <i>m</i>	7	2.30	25	12.07	0.97	13.04
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE <i>requir</i>	1	1001.10	25	750.82	60.07	810.89
33500-T6A-J51	LIGHT ASSY,R.TAIL <i>br</i>	1	897.20	25	672.90	53.83	726.73
42700-T6A-J43	WHEEL,DISK AL 17X7JJ <i>Xnn</i>	1	904.80	25	678.60	54.29	732.89
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>Xnn</i>	2	10.40	25	15.60	1.25	16.85
73810-T6A-003	SEALR.QUARTER GLASS <i>Xnn</i>	1	37.60	25	28.20	2.26	30.46
91501-SMA-003	CLIP AQTR. <i>Xnn</i>	1	3.20	25	2.40	0.19	2.59
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>Xnn</i>	1	4.10	25	3.07	0.25	3.32
91513-S70-003	CLIPL <i>Xm</i>	1	4.10	25	3.07	0.25	3.32
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>Xnn</i>	1	60.00		60.00	4.80	64.80
Sum Item					2742.73	219.44	2,962.17
BOSUN	SUNDRIES	1	110.00	<i>30</i>	110.00	8.80	118.80
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	<i>180</i>	250.00	20.00	270.00
BM103D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	<i>nn X</i>	650.00	52.00	702.00

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581

Registration No : SGA2133Z

Chassis No : JHMRC1890KC202225

Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)

Owner's Name : KEE GEK CHENG

Ins Policy No. :

Date of Accident : 14/6/2023

Document No. : SQT23001813 **Page** 2

Date : 15. Jun 2023

Customer No. : WZF002

Svc Advisor :

Engine No : K24W72461097

Date | Time : 15. Jun 2023 11:39:18 AM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST
GYG31R	REMOVE & INSTALL RIGHT REAR QUARTER GLASS Xnn	1	480.00		480.00	38.40	518.40
BKDR32R	REMOVE & INSTALL RR R SLIDING DOOR. Xnn	1	650.00		650.00	52.00	702.00
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. Xnn (N)	1	1500.00		1500.00	120.00	1620.00
BPBODY	REMOVE & TRANSFER TYRE TO NEW RIM. Xnn	1	60.00		60.00	4.80	64.80
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	4000.00	1300	4000.00	320.00	4320.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1	1	3000.00	1560	3000.00	240.00	3240.00
BOJSE	BODY JOINT SEALANT.	1	120.00	Xnn	120.00	9.60	129.60
Sum Labor					10820.00	865.60	11,685.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	220.00	Xnn	220.00	17.60	237.60
Sum Ext. Service					220.00	17.60	237.60

Survey By

Date & Time

Excess

Status

Signature

Rasou - Hp 90010068

26/06/23 @ 1410

5 days

Reg & print

Total Amount 13,782.73 1,102.64 14,885.37

Total (Inclusive of GST) 14,885.37

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

14080-02



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0080108 / KEE GEK CHENG

Document No: SVO23025578

Chassis No: JHMRC1890KC202225

Printed By: SHNG

License No: SGA2133Z

Order Date: 26. June 2023

Mileage: 98764

Order Time: 6:53:19 PM

Engine No: K24W72461097

Service Advisor: NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	8% GST Amount	Amount Incl GST
	SUPPLEMENTARY PART						
39680-T0A-R02YH	SENSOR ASSY,PARKING BACK SENSOR <i>new</i>	1	264.80	25	198.60	15.89	214.49
39684-T6A-N01ZG	RETAINER,PARKING D <i>new</i>	1	44.70	25	33.52	2.68	36.20
36934-T6A-J10	UNDERCOVERBSI RADAR R. <i>new</i>	1	53.70	25	40.27	3.22	43.49
75722-T6A-901	EMBLEM,RR. <i>new</i>	1	33.20	25	24.90	1.99	26.89
SUM PARTS:					297.29	23.78	321.07
TOTAL SGD					297.29	23.78	321.07

Total Payable (SGD)

321.07

GST Amount is calculated from individual line(s)