



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SGA2133Z
Chassis No : JHMRC1890KC202225
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : KEE GEK CHENG
Ins Policy No. :
Date of Accident : 14/6/2023

Document No. : SQT23001813 **Page** 1
Date : 15. Jun 2023
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72461097
Date | Time : 15. Jun 2023 11:39:18 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO:) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:							
04715-T6A-N10ZZ	FACE ASSY,RR.BUMPER <i>de ✓</i>	1	562.00	25	421.50 ✓	33.72	455.22	
71512-T6A-901ZA	SPOILER ASSY,R.RR. <i>sun ✓</i>	1	105.60	25	79.20 ✓	6.34	85.54	
71593-T6A-003	SPACERR.RR.BUMPER SIDE <i>m ✓</i>	1	20.40	25	15.30 ✓	1.22	16.52	
91505-TM8-003	CLIP,BUMPER <i>m ✓</i>	7	2.30	25	12.07 ✓	0.97	13.04	
04636-T6A-J22ZZ	PANEL SET,R.RR.OUTSIDE <i>requir ✓</i>	1	1001.10	25	750.82	60.07	810.89	
33500-T6A-J51	LIGHT ASSY,R.TAIL <i>bo ✓</i>	1	897.20	25	672.90 ✓	53.83	726.73	
42700-T6A-J43	WHEEL,DISK AL 17X7JJ <i>Xnn ✓</i>	1	904.80	25	678.60	54.29	732.89	
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>Xnn ✓</i>	2	10.40	25	15.60	1.25	16.85	
73810-T6A-003	SEALR.QUARTER GLASS <i>Xnn ✓</i>	1	37.60	25	28.20	2.26	30.46	
91501-SMA-003	CLIP AQTR. <i>Xnn ✓</i>	1	3.20	25	2.40	0.19	2.59	
91501-SYA-000	CLIPQUARTER WINDSHIELD A <i>Xnn ✓</i>	1	4.10	25	3.07	0.25	3.32	
91513-S70-003	CLIPL <i>Xm ✓</i>	1	4.10	25	3.07	0.25	3.32	
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>Xnn ✓</i>	1	60.00		60.00	4.80	64.80	
					Sum Item	2742.73	219.44	2,962.17
BOSUN	SUNDRIES	1	110.00		<i>30</i> 110.00 ✓	8.80	118.80	
BML021	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		<i>180</i> 250.00 ✓	20.00	270.00	
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		<i>nn X</i> 650.00 ✓	52.00	702.00	

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
#42-0116 RAFFLES QUAY
HONG LEONG BUILDING
SINGAPORE 048581
Registration No : SGA2133Z
Chassis No : JHMRC1890KC202225
Model : ODYSSEY 2.4 EXV-S 19YM (EURO 6)
Owner's Name : KEE GEK CHENG
Ins Policy No. :
Date of Accident : 14/6/2023

Document No. : SQT23001813 **Page** 2
Date : 15. Jun 2023
Customer No. : WZF002
Svc Advisor :
Engine No : K24W72461097
Date | Time : 15. Jun 2023 11:39:18 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	8% GST Amount	Amount incld GST	
GYG31R	REMOVE & INSTALL RIGHT REAR QUARTER GLASS X ⁿⁿ	1	480.00		480.00	38.40	518.40	
BKDR32R	REMOVE & INSTALL RR R SLIDING DOOR. X ⁿⁿ	1	650.00		650.00	52.00	702.00	
BMU22R	REMOVE & REPLACE RR R UNDERCARRIAGE PARTS. X ⁿⁿ (N)	1	1500.00		1500.00	120.00	1620.00	
BPBODY	REMOVE & TRANSFER TYRE TO NEW RIM. X ⁿⁿ	1	60.00		60.00	4.80	64.80	
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	4000.00	1300	4000.00	320.00	4320.00	
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. 1	1	3000.00	1560	3000.00	240.00	3240.00	
BOJSE	BODY JOINT SEALANT.	1	120.00	X ⁿⁿ	120.00	9.60	129.60	
					Sum Labor	10820.00	865.60	11,685.60
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	220.00		220.00	17.60	237.60	
					Sum Ext. Service	220.00	17.60	237.60

Survey By: Rasou - Hp 90010068
Date & Time: 26/06/23 @ 1410
Excess: _____
Status: _____
Signature: [Signature]

5 days
Res & paint

Total Amount 13,782.73 1,102.64 14,885.37
Total (Inclusive of GST) 14,885.37

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Printed on 15/6/2023 11:52:37 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

14080.02



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer:	CU0080108 / KEE GEK CHENG	Document No:	SVO23025578
Chassis No:	JHMRC1890KC202225	Printed By:	SHNG
License No:	SGA2133Z	Order Date:	26. June 2023
Mileage:	98764	Order Time:	6:53:19 PM
Engine No:	K24W72461097	Service Advisor:	NG SIN HAI

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	8% GST Amount	Amount Includ GST
39680-T0A-R02YH	SUPPLEMENTARY PART						
39680-T0A-R02YH	SENSOR ASSY,PARKING BACK SENSOR <i>new</i>	1	264.80	25	198.60	15.89	214.49
39684-T6A-N01ZG	RETAINER,PARKING D <i>new</i>	1	44.70	25	33.52	2.68	36.20
36934-T6A-J10	UNDERCOVERBSI RADAR R. <i>new</i>	1	53.70	25	40.27	3.22	43.49
75722-T6A-901	EMBLEM,RR. <i>new</i>	1	33.20	25	24.90	1.99	26.89
SUM PARTS:					297.29	23.78	321.07
TOTAL SGD					297.29	23.78	321.07

Total Payable (SGD) 321.07

GST Amount is calculated from individual line(s)