

(08/11 /13) wef

ASS. REC. BY: /

Tayfiter

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Ching

Veh No: SMD6813R. Yr Regn: 2016, April.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220 c.c. 2143.

Colour: white A/C: Insured / Std / NI / NA

Sp. Reading: 76259 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2120012B25675.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. _____

D.O.I. 15/6/73

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, SI

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD6813R

DATE 15.06.2023

MAKE REG. 08.04.2016

CHIANG /INCOME

MODEL MERC E6

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER			Rs \$1,510.00
1	REAR BUMPER RETAINER			X \$115.00
1	REAR DOOR PANEL LA RH			66 \$2,870.00
1	REAR WHEEL RIM RH			del \$1,250.00
	SUB TOTAL			\$4,495.00
	LESS 20%			\$899.00
				\$3,596.00
1	DOOR COMFORT/MAXI STICKER			all \$80.00
				\$80.00
	Labour Charge			
	Panel Beating		600	\$900.00
	Spray Painting Charge		1000	\$1,200.00
	Remove/Refix Upholstery rear		X	\$120.00
	Remove/Refix Door Parts		60	\$180.00
	TOTAL LABOUR			\$2,400.00
	ESTIMATE TOTAL			\$6,076.00
<p>Tanphun 97495749 wp' 15/6/23 @ 430 pm L/S Resurvey after repair Tanphun @ 16hants.wm 03 days</p>				
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Date/Time: 15.06.2023 13:40

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 5900362

JC NO305557764

STOMER
COMFORT TRANSPORTATION PTE LTD
MS 7010045
STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755
(R) (O)
(P)


REGN NO: SHD6813R	MILEAGE
MAKE: MERCEDES BENZ	FUEL E.....1/2.....F
MODEL E220CDI (E6)	DATE/TIME IN 15.06.2023 11:50
YR OF MANU. 08.04.2016	TARGET DATE
CHASSIS CODE WDD2120012B315675	COMPLETION DATE/TIME:

COUNT CARD NO.

JOB DESCRIPTION

Accident Date: 15.06.2023
NATURE: 3P 15.06.2023

3/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

No.: SHD6813R CHIANG

Vehicle No.: SHD6813R

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard