(08/11	/13)	wef	
ASS_	REC.	BY:	Tayfiler

REF:

NS/INC23006076/Tnp3

ASS_ REC. BY: / Tayfilch	INC.
AS	SSIGNMENT
From: Date:	Veh No: <u>SH41201F</u> Yr Regn: 2017, Mac
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TPIWS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To In Spect Vehicle No:	Make: Toyofa Prins c.c 1798
at Workshop m/s	Colour 223934 A/C: Insured / Std / NI / NA
of	Sp.Reading T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: 57 DK153 F 480355 6843
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil, / S/Rim / STD A/Rim or
	Tyre Size: F: 145/65/45
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Westake.
Bal. or Market Value:	<u>Front</u> Rear
DAC Accident Rport: Consistent?: Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. L/Bal. 6 mm
Est. Repairs: 2 days Res.: Yes or No	D.O.A. D.O.I. 14/6/23
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfut Co you
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted: Vehicle: IN / OU	
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Taufikh confirmed lump sum \$2250	and 2 repair days
(red, \$1681.58, 42%	
ate/Time, File Pass to?	
. Preli. Report	Days Of Repair: 2
late/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
	Transportation:
Add Fe)
leport Format :	: Interview (\$) Photos : Tech. Invs (\$) Others
ump Sum / I.B.I: (\$: Weekend (\$
	I TICCLCIU (V

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO MAKE/REG **SHA1201E**

25.05.2017

13.06.2023

CHIANG/INCOME

MODEL

TOYOTA PRIUS G4

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER CLIPS		
1	REAR BUMPER		m \$503.0
1	REAR BUMPER RETAINER LH		\$112.70
10	REAR BUMPER CLIPS	\$2.20	\$22.00
1	REAR BUMPER LOWER COVER		at \$654.9
1	REAR BUMPER LOWER SIDE COVER LH		\$232.0
1	TAIL LAMP UPPER LH		\$557.9
1	TAIL LAMP LOWER LH		\$570.0
	SUB TOTAL		\$2,652.6
	25.00%		\$663.1
	DISCOUNTED TOTAL		\$1,989.4
	REAR REVERESE SENSOR		× \$135.7
	REAR FENDER ADVERTISEMENT LH/RH		\$200.0
•	REAL TEMPERAD VERTISEIVE IV. 2.17.		\$322.1
	Labour Charge		
	Panel Beating	3	\$900.0
	Spray Painting Charge	2	\$600.0
	Tuff Kote		\$60.0
	Remove and Refix Reverse Sensor		\$60.0
	TOTAL LABOUR		\$1,620.0
	ESTIMATE TOTAL		\$3,931.5
	A		
	be prepared after the vehicle is surveyed by a motor Surveyor appo	inted by the insurance co	mpany.

Tauffin 97195719

UP/ 14/6/73 2330pm

US Kismy Mar report

Seding

fourfin Malanton

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

is ite:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops 205 Braddell Road Singapore 579701 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 Date/Time: 4512ndan Read Singeporg 609284:55

Page: 1

'eam:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 5900223

JC NO305557625

STOMER

(P)

/MS

COMFORT TRANSPORTATION PTE LTD

7010045

STOMER NO. 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65508755

. (R)

(O)

REGN NO. SHA1201E MILEAGE MAKE : TOYOTA FUEL PRIUS HYBRID(G4)13.06.2023 20:30

YR OF MANU. 25.05.2017

TARGET DATE

CHASSIS CODE JTDKB3FU803556893

COMPLETION DATE/TIME:

COUNT CARD NO


ident Date: 13.06.2023 IATURE: 3P 13.06.2023 '

:/NO

LABOR CODE

DESCRIPTION

JOB DESCRIPTION



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wledgement Slip

! No.:

SHA1201E

CHIANG

Vehicle No.:

Exit Pass

SHA1201E

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard