

ASS. REC. BY: / Taufikh

REF:

CS/ TM 23006078/Tvy3

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: SFT 3299J

Policy No. MQ004346

Claims No. M2303545

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: Juan Vehicle: IN / OUT

Veh No: SHA6918m Yr Regn: 2020, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: Hyundai toned c.c. 1500

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 47478 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM HC851CV L4189907

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or was there

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 15/6/2023 D.O.I. 15/6/23

Survey held at Comfort Logon

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

20/6/23 Taufikh confirmed lump sum \$1750 (Red 925.56, 34%)

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2) 22/6/23-typist

Days Of Repair: 2

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

Add Fee:  : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Report Format : Merimen

Lump Sum / I.B.I. (\$ 1750)


## ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive  
Singapore 508969  
Tel: 6214 8300

TP INSURER:  
CTPL

Tokio Marine Insurance Singapore Ltd (HQ)

*Jumani  
(Claim)*

Singapore

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	15/06/2023
Vehicle Reg. No.:	<b>SHA6918M</b>	Driveable?	YES
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Vehicle Reg. Date:	11/03/2020
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEKU408923	Chassis No:	KMHC851CVLU189907
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	4		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	1,864.56
Miscellaneous Items	11.00
Labour	800.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>2,675.56</b>
<b>+ GST 8.00% (S\$)</b>	<b>214.04</b>
<b>Nett Amount (S\$)</b>	<b>2,889.60</b>

This claim is handled by: JUMANI BIN MASUDIN

**REPAIR DETAILS****Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Jun 2023)**Parts:** 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** ComfortDelGro Engineering Pte Ltd/SHA6918M/15/06/2023 13:51**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER ASSY	20.00	0.00	<i>Pr</i> *459.40 FL
2	10		*REAR BUMPER CLIPS	20.00	0.00	<i>x</i> *22.00 FL
3	1		*REAR BUMPER BEAM	20.00	0.00	<i>?</i> *394.80 FL
4	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	<i>de</i> *451.25 FL
5	1		*REAR FOG LAMP ASSY	20.00	0.00	<i>at</i> *201.50 FL
6	1		*ANTENNA SMARTKEY	20.00	0.00	<i>?</i> *40.50 FL
7	1		*REAR BUMPER MAT	0.00	0.00	<i>x</i> *50.00 F
8	1		*REAR NUMBER PLATE	0.00	0.00	<i>Cus</i> *55.00 F
9	1		*REAR BUMPER LOWER MOULDING	20.00	0.00	<i>de</i> *155.00 FL
10	1		*REVERSE SENSOR	0.00	0.00	<i>ru</i> *180.00 F
11	2		*REAR FENDER ADVERTISEMENT LOGO	0.00	0.00	<i>ver</i> *200.00 F

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>2,209.45</b>
<b>- List Item Discount on L Items (\$\$)</b>	<b>344.89</b>
<b>Total Parts (\$\$)</b>	<b>1,864.56</b>

ComfortDelGro Engineering Pte Ltd/SHA6918M/15/06/2023 13:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (S\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350 400.00
2	SPRAY PAINT	New	250 300.00
3	CHECK WIRING	New	30 50.00
4	REMOVE/REFIX REVERSE SENSOR	New	30 50.00
<b>Gross Labour Cost (S\$)</b>			<b>800.00</b>

ComfortDelGro Engineering Pte Ltd/SHA6918M/15/06/2023 13:51. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanpin 97495749  
 WP 15/6/23 @ 445pm  
 2 days  
 tanpin @ lkkauto.com

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

am: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 5900361

JC NO305557763

OMER  
S COMFORT TRANSPORTATION PTE LTD  
OMER NO 7010045  
ESS 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)


REGN NO.: SHA6918M	MILEAGE
MAKE: HYUNDAI	FUEL E.....1/2.....F
MODEL IONIQ(G3)	DATE/TIME IN 15.06.2023 11:20
YR OF MANU. 11.03.2020	TARGET DATE
CHASSIS CODE KMHC851CVLU189907	COMPLETION DATE/TIME:

JUNT CARD NO.

JOB DESCRIPTION

Accident Date: 15.06.2023  
DURATION: 3P.15.06.23

NO                      LABOR CODE                      DESCRIPTION



RECEIVED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR

\_\_\_\_\_  
CUSTOMER'S SIGNATURE

Damage Slip  
No.: SHA6918M                      JU TOKIO

Exit Pass  
Vehicle No.:                      SHA6918M

\_\_\_\_\_  
Service Advisor                      Signature/Date

\_\_\_\_\_  
Name of Service Advisor                      Date

Returned to Service Reception upon collection

To be kept by Security Guard