| (08/11 | 13) | wef | | | | |
|--------|-----|-----|----|-------|-----|--|
| 100 | REC | DV. | To | u Cil | 11. | |

REF:

NS/INC23006079/Tnp3

INC

| ASS | IGNMENT |
|--|---|
| From Date: | Veh No: SHB3173 J. Yr Regn: 2020 1 Sept. |
| OD / TPIWS / TP RES / OD RES / EVA / INV / MV | Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or |
| To In spect Vehicle No: | |
| at Workshop m/s | Make: Toyota Vius c.c (798 |
| of | Colour Jellow A/C: Insured / Std / NI / NA |
| Insured: | Sp.Reading 7/Radio: Insured / Std / NI / NA |
| | Eng/No: |
| Policy No. MT/1227504-002 | C/No: STDKB3F4X63092747. |
| • | Gen. Cond: Good / Fair / Poor / Burnt |
| Sum Insured: Excess: | Steering: Inorder / Jammed / Leaked / Burnt or |
| (Client's Record) | Brake: Inorder / Jammed / Leaked / Burnt or |
| Make of Veh: | Modi: Nil/ S/Rim / STD A/Rim or |
| | Tyre Size: F: 195/6517/5 |
| (Po licy Condition) | R: |
| Remark: The veh had commenced its N/S O/S | BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / |
| repair at the time of inspection. | TOYO/YOKO or westake. |
| Bal, or Market Value: | Front Rear |
| IDAC Accident Rport: Consistent? : Yes or No | R/Bal. R/Bal. mm |
| GIA / PR Seen: Consistent? : Yes or No | L/Bal. L/Bal. mm |
| Est. Repairs: 2 days Res.: Yes or No | D.O.A. D.O.I. 14/6/73 |
| Lum Sum: % 3 Val.: Yes or No | Survey held at Love for Lougen |
| CA / REV / REP. / 24 HRS | Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or |
| Date:Person Contacted: Vehicle: IN / OUT | lea ofs |
| Date / Time Action / Instruction | The U/C / Chassis frame / Body Structure affected due to collision. |
| | |
| Taufikh confirmed lump sum \$900 and | d 2 days |
| (red, \$920.78, 50%) | |
| | |
| | |
| 1 | |
| - | |
| | |
| | Days Of Repair: 2 |
|) : Final Report F | Resurvey No. of Trip: Survey Fee: |
| | Transportation: |
| Add Fee: | |
| Report Format : | : Interview (\$) Photos |
| -ump Sum / I.B.I: (\$ | : Tech. Invs (\$) Others |
|) | : Weekend (\$) |
| | TOTAL |

COMFORT TRANSPORTATION PTE LTD ____ REPAIR ESTIMATE

Vehicle No.: SHB3173J

Make : Toyota

Model

: Prius (G4A)

Date: 14/06/2023 Insurance: INCOME

MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Туре | Unit Price | Amount |
|-----|--|------|------------|--------------|
| 1 | REAR BUMPER | | | \$ RY 503.04 |
| 10 | REAR BUMPER CLIPS | | | \$ 22.00 |
| 1 | REAR BUMPER LOWER COVER | | | \$ 9654.96 |
| 1 | REAR BUMPER REFLECTOR RH | | | \$ × 55.00 |
| 1 | REAR BUMPER SIDE RETAINER RH | | | \$ 112.70 |
| | SUB TOTA | _ | | \$ 1,347.70 |
| | LESS 25° | 6 | | \$ 336.93 |
| | DISCOUNTED TOTA | _ | | \$ 1,010.78 |
| 1 | REAR BUMPER RUBBER MAT | | | \$ 50.00 |
| | THE BOWN ENTROPER WAY | | | \$ 50.00 |
| | Labour Charge | | | 350 |
| | PANEL BEATING | | | \$ 250300.00 |
| | SPRAY PAINTING CHARGE | | | \$ 30 60.00 |
| | REMOVE/REFIX REVERSE SENSOR TOTAL LABOU | P | | \$ 760.00 |
| | TOTAL LABOU | | | Ψ 700.00 |
| | ESTIMATE TOTAL | L | | \$ 1,820.78 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Toughi 97495749

wip, 4/6/13 e 550 pm

2ely

els Mony offer report

toughir collisation

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 509286; 24

Page: 1

ARC Repair TP(CFSO)1

JOB CARD Sales Order: 5900232

JC NO305557626

MILEAGE

FUEL

USTOMER

IR/MS

DDRESS

EL. (R) (P)

CITYCAB PTE LTD 7010070

USTOMER NO 383 SIN MING DRIVE

Singapore SINGAPORE 575717

65551188

(O)

REGN NO.: SHB3173J MAKE TOYOTA

DATE/TIME IN 06.2023 14:10 PRIUS HYBRID (G4A14.

YR OF MANU. 30.09.2020 TARGET DATE

Date

CHASSIS CODE JTDKB3FUX03092747

COMPLETION DATE/TIME:

ISCOUNT CARD NO.

Accident Date: 14.06.2023 NATURE: 3P 14.06.2023

S/NO


ame of Service Advisor

be returned to Service Reception upon collection

LABOR CODE

DESCRIPTION

JOB DESCRIPTION



| 8 | | 3: |
|---------------------------------|-----------------------|----------------------|
| CHECKED & PASSED OUT BY: | | |
| SERVICE ADVISOR | | CUSTOMER'S SIGNATURE |
| knowledgement Slip | Exit Pass | |
| ne: No.: hicle No.: SHB3173J YY | Vehicle No.: SHB3173J | |
| | 9 | |

Signature/Date

Name of Service Advisor

To be kept by Security Guard