(08/11	/13)	wef	
ASS	REC	BY:	Taublus.

REF:

NS/INC23006080/Tnp3

INC	
(,,	

ASSI	GNMENT
From: Date:	Veh No: SHC 3232 S Yr Regn: Zul 9 / Nov
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP/WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To In spect Vehicle No:	Make: My under laving c.c 1580.
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 5/15 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: WMH (851 CVL-418484
Claims No. MT/1228535-001	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / S/Rim / STD A/Rim or /
	Tyre Size: F: 195/65 Rt5
(Policy Condition)	R: 1 ^
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or Westlete.
Bal. or Market Value:	<u>Front</u> <u>Rear</u>
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. mm L/Bal. mm
Est. Repairs: 2 days Res.: Yes or No	D.O.A. P.O.I. 14 6 23
Lum Sum: % 3 Val.: Yes or No	Survey held at Comfert Loyer
CA / REV / REP. / 24 HRS + W	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Date:Person Contacted:Vehicle: IN / OUT	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The 676 7 chassis frame 7 body structure affected due to collision.
Taufikh confirmed lump sum \$700 ar	nd 2 repair days
(red, \$1205.12, 63%)	
Date/Time, File Pass to?	
. Freii. Report	Days Of Repair: 2
1): Final Report F	Resurvey No. of Trip: Survey Fee:
And the second s	Transportation:
2) Add Fee:	The state of the s
Report Format :	: Interview (\$) Photos
Lump Sum / I.B.I: (\$: Tech. Invs (\$) Others
),	:Weekend (\$)

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

14.06.2023

INSURANCE:

SMW4588U INCOME (

MODEL:

Hyundai loniq

MVA:

LIM TS

VEHICLE NO.: SHC3232S

PART NO.	DESCRIPTION		UNIT PRICE		AMOUNT	
	Rear Bumper	1			\$	459.40
	Rear Bumper Clips	10	\$	2.20	\$	22.00
	SUB TOTAL				\$	481.40
	LESS 20%				\$	96.28
	SPARE PARTS TOTAL				\$	385.12
	Labour Charge Panel Beating - Rear Fender Arch RH				\$	800.00
	Spray Painting Charge				\$	600.00
	R/I Reverse Sensors				\$	120.00
	TOTAL LABOUR				\$	1,520.00
	ESTIMATE TOTAL				\$	1,905.12

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Lougher after repeir fourflire after repeir

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

C-te:



Service Advisor

urned to Service Reception upon collection

Signature/Date

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
Date/Time: 45Pandar God Singapore 50898: 54

Page: 1 JOB CARD Sales Order: 5900133 am: ARC Repair TP(CLSO)1 JC NO305557636 **OMER** REGN NO. SHC3232S MILEAGE COMFORT TRANSPORTATION PTE LTD S MAKE FUEL 7010045 HYUNDAI OMERNO 383 SIN MING DRIVE MODEL IONIQ(G3) 13.06.2023 14:40 Singapore SINGAPORE 575717 65508755 (R) (O) YR OF MANU. 14.11.2019 TARGET DATE (P) CHASSIS CODE KMHC851CVLU189484 COMPLETION DATE/TIME DUNT CARD NO. JOB DESCRIPTION :cident Date: 13.06.2023 TURE: 3P 13.06.2023 FRONT NO LABOR CODE DESCRIPTION 10010 PB PANEL BEATING-SHC3232S-TP 10020 SP SPRAYPAINT CHARGE LEFT SIDE KED & PASSED OUT BY: SERVICE ADVISOR CUSTOMER'S SIGNATURE edgement Slip Exit Pass Vehicle No.: SHC3232S LIMTS SHC3232S

Name of Service Advisor

To be kept by Security Guard

Date