

## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK

DATE: 14.06.2023

SMW4588U

MODEL: Hyundai IoniqINSURANCE: INCOME (L/S)VEHICLE NO.: SHC3232SMVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$ 459.40
	Rear Bumper Clips	10	\$ 2.20	\$ 22.00
	<b>SUB TOTAL</b>			\$ 481.40
	<b>LESS 20%</b>			\$ 96.28
	<b>SPARE PARTS TOTAL</b>			<b>\$ 385.12</b>
	<u>Labour Charge</u>			
	Panel Beating - <u>Rear Fender Arch RH</u>			\$ 800.00
	Spray Painting Charge			\$ 600.00
	R/I Reverse Sensors			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 1,520.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 1,905.12</b>

Handwritten notes on table: 886, 168700, 2 days, 350, 500, 30

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanji 97445749  
 WP 12/6/23 @ 240pm  
 - 2 days  
 Resurvey after repair  
 Tanji @ 11am

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: