

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ivy Yong

Date: 16 Jun 2023

Preliminary Advice

Vehicle No	: YQ1832Z	Accident Date	: 11/06/2023
Make	: MITSUBISHI CANTER	Policy No.	: DMCG22009179
Assignment Date	: 16/06/2023	Excess	: S\$500.00
Date of Inspection	: 16/06/2023	Est. Duration of Repair	: 18
Inspection At	: ALAN'S UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE, #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	46,764.50
Revised Amount	:S\$	24,093.00
Check Items (Estimated)	:S\$	19,891.50
Total	:S\$	43,984.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	91,000.00
COE / PARF Rebate	:S\$	16,824.00
Salvage Value	:S\$	
Margin for Repair	:S\$	74,176.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY ADVISE THE REAR CANOPY ALUMINIUM BOX WITH INSURER POLICY.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.