

**REPAIR ESTIMATE**

Vehicle No. : SHC7044S  
 Make : BYD  
 Model : NEW E6

Date: 14/06/2023  
 Insurance: INCOME  
 MVA MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER UPPER BODY			\$ 2,016.00
10	REAR BUMPER CLIPS			\$ 22.00
1	REAR BUMPER LOWER BODY			\$ 528.75
2	REAR BUMPER BRACKET LF RF		\$ 29.25	\$ 58.50
1	REAR BUMPER BRACKET LR RR		\$ 65.25	\$ 65.25
1	REAR BUMPER BEAM			\$ 661.50
	<i>Supp</i> line sticker \$18 SN nec			
	<b>SUB TOTAL</b>			\$ 3,417.25
	<b>LESS 20%</b>			\$ 683.45
	<b>DISCOUNTED TOTAL</b>			\$ 2,733.80
	REAR BUMPER RUBBER MAT		50	\$ 50.00
				\$ 50.00
	<b>Labour Charge</b>			
	PANEL BEATING			\$ 800.00
	SPRAY PAINTING CHARGE		830	\$ 500.00
	REMOVE/ REFIX REVERSE SENSOR			\$ 80.00
	<b>TOTAL LABOUR</b>			\$ 1,380.00
	<b>ESTIMATE TOTAL</b>			\$ 4,163.80

256.75  
 20% - 2053.40  
 18

\$2951.40  
 2 days

Tanfahin 9749 5749  
 up, 14/6/23 @ 4pm  
 p/p Roomy before paint  
 2 days  
 Tanfahin @ Kuantan

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: