



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKW 5538G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
1	FACE,RR BUMPER (SN)	DEFORMED	1,268.00	1,268.00
1	BRACKET,RR BUMPER,LH (SN)	NECESSARY	34.00	34.00
1	BRACKET,RR BUMPER,RH (SN)	NECESSARY	34.00	34.00
1	MARK,THREE-DIA (SN)	NECESSARY	86.00	86.00
1	MARK,ATTRAGE (SN)	NECESSARY	26.00	26.00
1	PANEL,RR END (SN)	BENT	440.00	440.00
1	LAMP ASSY,COMB,RR LH (SN)	NOT NECESSARY	661.00	-
1	LAMP ASSY,COMB,RR RH (SN)	NOT NECESSARY	661.00	-
1	PANEL,TRUNK LID (SN)	BENT	835.00	835.00
1	FRONT, REAR & SPOILER (SN) (ADDITIONAL)	CRACKED	1,000.00	1,000.00
1	BUZZER,KEYLESS OPERATIO,RR (SN) (ADDITIONAL)	CRACKED	96.00	96.00
1	COVER,RR VENTILATOR (SN) (ADDITIONAL)	CUT	50.00	50.00
1	BOARD,TRUNK ROOM FLOOR (SN) (ADDITIONAL)	CRACKED	204.00	204.00
3	CLIP,GEARSHIFT CONTROL LIN @\$3.00 (SN) (ADDITIONAL)	NECESSARY	9.00	9.00
			5,504.00	4,102.00
<b><u>LABOUR</u></b>				
RENEW RR BUMPER, BOOTLID, RR BODY KIT,RR END PANEL REPAIR BOTH REAR FENDER.			3,840.00	3,200.00
SPRAY RR BUMPER, BOOTLID, RR BODYKIT, RR END PANEL, RR BOTH RH & LH FENDER.			3,300.00	2,200.00
REMOVE AND REFIT SENSOR.			100.00	100.00
REMOVE AND TRANSFER TRIM AND BONNET MECHANISM.			280.00	280.00
REMOVE AND REFIT FLOOR COMPARTMENT.			280.00	180.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.			280.00	280.00
CHECK WIRING AND ELECTRICAL.			100.00	100.00
ANTI RUST PROOFING.			150.00	100.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SUPPLY BODY PNL SEALANT.	NOT NECESSARY	150.00	100.00
	SUPPLY CNC EMBLEM.		80.00	80.00
	SUPPLY NUMBER PLATE.		120.00	-
	REPAIR RH REAR FENDER (ADDITIONAL).		640.00	640.00
	RESPRAY RH REAR FENDER (ADDITIONAL).		550.00	550.00
			9,870.00	7,810.00
<b>GRAND TOTAL</b>			<b>15,374.00</b>	<b>11,912.00</b>

<b>RECOMMENDED COST OF REPAIRS</b>				<b>11,912.00</b>
------------------------------------	--	--	--	------------------

Report Ref No. CS/SMR23006085/Rvy3m4

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.