



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 64739722

**ESTIMATE**

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHUN HAN (CHEN JUNHAN)	Cust No/Name	/TAN CHUN HAN (CHEN JUNHAN)
100 Faber Terrace	Reg No/Reg Date	SKW5538G / 26/09/201
Singapore 129600	Date In/Mileage	/ 0
Contact No Mobile: 96882969	Chassis No	MMBSTA13AJH003490
	Engine No	3A92UHH3426
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	15/06/2023/ 19:17		1015/ Vikneswaran Naidu A	34769		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							3840.00
RENEW RR BUMPER, BONNET, RR BODY KIT,RR END PANEL							
REPAIR BOTH REAR FENDER							
E PNT98000							3300.00
SPRAY RR BUMPER, BONNET, RR BODYKIT, RR END PANEL,							
RR BOTH RH & LH FENDER,							
E PNT88000							100.00
REMOVE ADN REFIT SENSOR							
E PNT88000							280.00
REMOVE AND TRASNFER TRIM AND BONNET MECHANICSM							
E PNT88000							280.00
REMOVE AND REFIT FLOOR COMPARTMENT							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
A 10028901							100.00
CHECK WIRING AND ELECTRICAL							
M SUNDRY							150.00
ANTI RUST PROOFING							
M SUNDRY							150.00
SUPPLY BODY PNL SEALANT							
M SUNDRY							80.00
SUPPLY CNC EMBLEM							
M SUNDRY							120.00
SUPPLY NUMBER PLATE							
M SUNDRY							100.00
SUNDRIES							
M	FACE,RR BUMPER			1.00	1268.00	00.00	1268.00
M	BRACKET,RR BUMPER,LH			1.00	34.00	00.00	34.00
M	BRACKET,RR BUMPER,RH			1.00	34.00	00.00	34.00
M	MARK,THREE-DIA			1.00	86.00	00.00	86.00
M	MARK,ATTRAGE			1.00	26.00	00.00	26.00
M	PANEL,RR END			1.00	440.00	00.00	440.00
M	LAMP ASSY,COMB,RR LH			1.00	661.00	00.00	661.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAN CHUN HAN (CHEN JUNHAN)	Cust No/Name	/TAN CHUN HAN (CHEN JUNHAN)
100 Faber Terrace	Reg No/Reg Date	SKW5538G / 26/09/201
Singapore 129600	Date In/Mileage	/ 0
Contact No Mobile: 96882969	Chassis No	MMBSTA13AJH003490
	Engine No	3A92UHH3426
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	15/06/2023/ 19:17		1015/ Vikneswaran Naidu A	34769		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M LAMP ASSY,COMB,RR RH				1.00	661.00	00.00	661.00
Estimate							

Confirm & accepted by

Nett	11,990.00
8% GST on	11990.00
Total Payable	12,949.20

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.