

THE CHONG MOTOR SALES PTE. LTD.

511, BUKIT TIMAH ROAD

SINGAPORE 599621

DESTINATE : ROBINSON/ROBINSON
PERSONAL : BUKIT TIMAH
CONTACT NO : 6688551
DEPARTED : 10/10/1998/10/10/1998
DATE : 15-09-2003

ALLIANCE INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD 099-61

ST0000073
TEL : 63954776/67343305
FAX : 63953789
ATTN: MOTOR CLAIM MANAGER

OWNER & NAME : TAN SENG CHOLAN
ADDRESS : 61 JONGGONG STREET RTF 1
#15-01
SINGAPORE
TELEPHONE NO : 67327008

TYPE OF CLAIM : 10 00 00 REPAIRS CLAIM
POLICY NO : 000000000000
VEHICLE NO : 00000000
MODEL CODE : 000000000000-1-1
MODEL/TYPE : 000000000000 1-1 000000
ENGINE NO : 000000000000
CHASSIS NO : 0000000000000000
ALIAS : 00000000
DATE IN : 15/09/2003
LIABILITY : 0.00
REPAIR CLASS : 0.00
ATTACHED BY : LAWRENCE
ACCIDENT DATE : 15/09/2003

15/06/2003

00

CAR 2-1

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	/
2	FH1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
3	IBS	PERFORM NISSAN COMPUTERISED DIAGNOSIS, ALIGN VEH LEVEL, CALIBRATION OF RADAR SENSOR AND ROAD TEST	330.00	/
4	RIEMA	REMOVE/INSTALL EXHAUST MUFFLER ASSY AND PRE MUFFLER (RENEW)	240.00	/
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05	600.00	480
6	RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100
8	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	X
9	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	150.00	X
10	ZZ/001	REPAIR SUPPORT PANEL, BONNET, BUMPER SPOILER, LH/RH FRONT FENDER AND RENEW FRONT BUMPER	1950.00	1365
11	ZZ/002	S/PAINT FRONT BUMPER, BUMPER SPOILER, SUPPORT PANEL FENDER AND LH/RH FRONT FENDER	1750.00	1325
12	ZZ/003	RENEW STEERING WHEEL	120.00	/
13	ZZ/004	CHARGE/DISCHARGE A/CON GAS AND RENEW A/CON PARTS R1234Y	440.00	/
14	ZZ/005	RENEW RADIATOR	120.00	?
15	ZZ/006	SUPPLY AND FRONT/REAR NO PLATE (SMART PLATE WITH CASING) LONG		
16	ZZ/007	REPAIR END PANEL, S/TYRE HOUSING, LH REAR FENDER AND RENEW TAILGATE, REAR BUMPER, BUMPER SPOILER	1900.00	1560
17	ZZ/008	S/PAINT TAILGATE, END PANEL, REAR BUMPER, BUMPER SPOILER, LH REAR FENDER, S/TYRE HOUSING	1750.00	1625
18	ZZ/009	CHECK LIGHTING REAR	48.00	/
19	ZZ/10	TRANSFER TAILGATE MECHANICAL PARTS TO NEW DOOR	60.00	X

Supply

repair chassis frame -

4p

350/-

250/- 125

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM380S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
-----			-----	-----
TOTAL LABOUR CHARGES			10301.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TINAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN1808

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	S/TYRE HOUSING FOAM <i>T</i>	84975-3ZL0A	500.00			
2	SEAT SHIELD EXHAUST SUB <i>ht?</i>	74762-BC40A	152.60			
3	HEAT SHIELD EXHAUST (MAIN) <i>ht</i>	74772-1KE0A	116.40			
4	EXHUST MOUNTING \$12.70 EA X 03 <i>?</i>	20651-1KB1A				38.10
5	REAR BUMPER SPOILER <i>cm</i>	YH5920-00C13				380.00
6	EMBLEM REAR <i>m</i>	90891-3GF0B	115.60			
7	EMBLEM-BACK DOOR <i>m</i>	90890-3ZL0A	72.20			
8	EMBLEM RAD GRIL <i>m</i>	62890-1DA0B	72.20			
9	STRIKEN BACK DOOR <i>?</i>	90570-3ZL1A	128.70			
10	A LOCK LIFT TAILGATE <i>?</i>	90502-4EA0A	192.60			
11	W/STRIP TAILGATE <i>?</i>	90830-3ZLOC	225.70			
12	GLASS BACK DOOR <i>X</i>	90300-3ZL0A	1156.30			
13	DOOR A BACK TAILGATE <i>vgent</i>	K0190-3ZLAA	4487.30			
14	GROMMET BUMPER REAR \$3.00 EA X 02 <i>m</i>	63846-5V000	6.00			
15	REINFORCEMENT REAR BUMPER <i>?ht</i>	H5030-3ZLMA	736.50			
16	ABS ENERGY RH REAR BUMPER <i>X</i>	85092-3ZL0A	239.40			
17	ABS ENERGY LH REAR BUMPER <i>?cm</i>	85093-3ZL0A	182.70			
18	BRKT REAR BUMPER RH <i>X</i>	85226-3ZL0A	81.60			
19	BRKT REAR BUMPER LH <i>m</i>	85227-3ZL0A	81.60			
20	FASCIA KIT REAR <i>de</i>	H5022-3ZLMH	1657.20			
21	BOARD A LUGGAGE S/TYRE <i>?</i>	84906-3ZL1A	743.80			
22	PLATE LUGGAGE END PANEL <i>?</i>	84992-3ZL0A	271.60			
23	WTT EXHAUST SHIELD HEAT \$2.10 EA X 15 <i>m</i>	01241-01131				31.50
24	WSPR STAY REAR <i>X</i>	H5210-3ZLMA	880.50			
25	WSPR STAY REAR <i>X</i>	H5211-3ZLMA	880.40			

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM3808

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
26 MALE A HOOD ?	65601-32P0A	206.90			
27 CLIP-HOOD INSUL \$1.30 EA X 08 X	65846-40P00	10.40			
28 AIR GUIDE FRT RH ?	62822-3ZL0A	119.70			
29 AIR GUIDE FRT LH ?	62823-3ZL0A	175.90			
30 GRILLE RADIATOR can	62310-3ZL0A	697.90			
31 BRKT FRONT BUMPER RH m	62224-3ZL0A	23.30			
32 BRKT FRONT BUMPER LH m	62225-3ZL0A	23.30			
33 BRKT APRON LOWER BUMPER FRONT ?	62663-3ZL0A	151.40			
34 ARMATURE BUMPER FRONT do bt	F2030-3ZLAA	608.80			
35 ABS ENERGY BUMPER FRONT can	62090-3ZL0A	239.40			
36 CLIP BUMPER/GRILLE/PROETCOR \$1.50 EA X 33 m	01553-10501	49.50			
37 FASCIA KIT FRT de	F2022-3ZLMH	1614.70			
38 WHEEL A STEERING cut	48430-3ZL2C				668.70
39 COND & LIQUID bt	92100-BA61B				604.50
40 CLIP C/LAMP \$7.30 EA X 02 m	26398-9N00A				14.60
41 GROMET C/LAMP \$5.40 EA X 02 m	26557-2U000	10.80			
42 COMB LAMP LH TAILGATE can	26555-3ZP5B	514.60			
43 COMB LAMP LH COMB can	26555-3ZL0A	514.60			
44 GROMMET H/LAMP \$3.00 EA X 02 m	76848-AS500	6.00			
45 BRKT A H/LAMP LH/RH \$60.20 EA X 02 m	26042-3ZL0A				120.40
46 HEAD LAMP RH can	26010-3ZP5A	1511.90			
47 HEAD LAMP LH can	26060-3ZP5A	1511.90			
48 CLIP ANTENNA \$4.00 EA X 02 m	63848-89900	8.00			
49 ANTENNA-SMART RELESS ?	28985-JK60A	53.50			

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM380S

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
50 BRKT DISTANCE FRONT BUMPER <i>short</i>	28452-3EL1A			896.50
51 SENSOR BUMPER FRONT DISTANCE <i>?</i>	28438-3ZU1D			1211.20
52 HORN-ANTI THEFT LOW <i>?</i>	25605-3EL0A			68.00
53 HORN A ELECTRIC HIGH <i>?</i>	25610-3EL0B			111.70
54 TANK & RADIATOR <i>del</i>	21710-3ZU0A			152.30
55 MOUNTG RUBR-RADIATOR \$7.60 EA X 03	21506-AX600			22.80
56 RADIATOR <i>?</i>	21410-HX51B			836.00
57 GASKET SUB MUFFLER <i>m</i>	20692-8H30A			19.70
58 MUFFLER SUB <i>St</i>	20300-3ZU0B			843.80
59 GASKET-EXHAUST MUFFLER <i>m</i>	20691-9Y400			7.00
60 MUFFLER ASSY (REAR) <i>St</i>	20100-3ZU0A			1116.80
61 RUBBER INSERT SEAL SPOILER \$18.00 EA X 02 <i>m</i>	Y03000-00C11			36.00
62 NISSAN SILL COOLANT \$9.50 EA X 02 <i>?</i>	NC-01			19.00
63 SUNDRIES	NPN			40.00 <i>✓</i>
64 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP <i>con</i>				60.00 <i>✓</i>
65 FRT LICENCE PLATE (SMART PLATE WITH CASING) LONG FLP <i>con</i>				60.00 <i>✓</i>
SUB TOTAL		20953.40	0.00	7358.60
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		4190.68	0.00	0.00
GRAND TOTAL		16762.72	0.00	7358.60
OVERALL TOTAL		24121.32		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TINAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM380S

TOTAL LABOUR CHARGES	10301.00
TOTAL SPARE PARTS CHARGES	24121.32
GRAND TOTAL	34422.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

Plate - 4p 90010068
16/06/23 01445

14 days

0.00

EXCESS: 500

Revers

Resy before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: