

(06/11/13) waf
ASS. REC. BY: *[Signature]*

REF:

CS/ALW 23006085/Rvp3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SLM 3803
at Workshop m/s TAN CHONG
of BUKIT TIMAH
Insured: AIS
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: 500
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: 59K
IDAC Accident Rpt: _____ Consistent?: Yes or No
GIA / PR Seen: _____ Consistent?: Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLM 3803 Yr Regn: 2011 OCT
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____

Make: NISSAN PULSAR c.c. 1197
Colour: RED A/C: Insured / Std / NI / NA
Sp. Reading: 85802 T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: VSK0DAC13 U0098602

Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/SOR17
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. <u>6</u> mm		R/Bal. <u>6</u> mm	
L/Bal. <u>6</u> mm		L/Bal. <u>6</u> mm	
D.O.A. <u>14/06/23</u>		D.O.I. <u>16/06/23</u>	

Survey held at TAN CHONG
Des. of Damages: FR / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 35K

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee:

☐ : Site Insp (\$ _____)	) S + RS _____ SI
☐ : Interview (\$ _____)	) Photos
☐ : Tech. Invs (\$ _____)	) Others
☐ : Weekend (\$ _____)	)

Report Format :

Lump Sum / I.B.I. (\$) _____

TOTAL

THE CHINA MOTOR SALES PTE. LTD.

111, BUKIT TIMAH ROAD

SINGAPORE 59623

DESTINATE : ACCIDENT/LOSS REPORT
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4688591
REFERENCE : THE/PC/LAW/0178/2023
DATE : 15-JUN-2023

ALLIANCE INSURANCE SINGAPORE PTE LTD
79 ROBINSON ROAD 09A-01

ST000097)

TEL : 63956778/67143305

FAX : 63963788

ATTN: MOTOR CLAIM MANAGER

OWNER'S NAME : THE PERM COY HOLDING
ADDRESS : 61 SIMONS ROAD RTF 1
#10-01
SINGAPORE
TELEPHONE NO : 67907858

TYPE OF CLAIM : AS OR TO RECOVER LOSS
POLICY NO : 00000000000000000000
VEHICLE NO : 2143394
MODEL CODE : D01A0000000000000000
MODEL/TYPE : 20000000000000000000
ENGINE NO : 00000000000000000000
CHASSIS NO : 00000000000000000000
VARIANT : 00000000000000000000
DATE IN : 15/06/2023
LIABILITY : 0.00
ACCIDENT CLASS : 0.00
ATTACHED BY : LAWRENCE
ACCIDENT DATE : 14/06/2023

14/11/23

15/06/2023

00

CAR 74

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	CRP	CONDUCT CONSULT, RESET & PROGRAMMING	240.00	/
2	FH1	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	/
3	IBS	PERFORM NISSAN COMPUTERISED DIAGNOSIS, ALIGN VEH LEVEL, CALIBRATION OF RADAR SENSOR AND ROAD TEST	330.00	/
4	RIEMA	REMOVE/INSTALL EXHAUST MUFFLER ASSY AND PRE MUFFLER (RENEW)	240.00	/
5	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 05	600.00	480
6	RS	SUPPLY & INSTALL REVERSE SENSOR	55.00	/
7	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100
8	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	X
9	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	150.00	X
10	ZZ/001	REPAIR SUPPORT PANEL, BONNET, BUMPER SPOILER, LH/RH FRONT FENDER AND RENEW FRONT BUMPER	1950.00	1365
11	ZZ/002	S/PAINT FRONT BUMPER, BUMPER SPOILER, SUPPORT PANEL FENDER AND LH/RH FRONT FENDER	1750.00	1325
12	ZZ/003	RENEW STEERING WHEEL	120.00	/
13	ZZ/004	CHARGE/DISCHARGE A/CON GAS AND RENEW A/CON PARTS R1234Y	440.00	/
14	ZZ/005	RENEW RADIATOR	120.00	?
15	ZZ/006	SUPPLY AND FRONT/REAR NO PLATE (SMART PLATE WITH CASING) LONG		
16	ZZ/007	REPAIR END PANEL, S/TYRE HOUSING, LH REAR FENDER AND RENEW TAILGATE, REAR BUMPER, BUMPER SPOILER	1900.00	1560
17	ZZ/008	S/PAINT TAILGATE, END PANEL, REAR BUMPER, BUMPER SPOILER, LH REAR FENDER, S/TYRE HOUSING	1750.00	1625
18	ZZ/009	CHECK LIGHTING REAR	48.00	/
19	ZZ/10	TRANSFER TAILGATE MECHANICAL PARTS TO NEW DOOR	60.00	X

Supplies

repair chassis frame -

21P

350/-

250/- 125

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLM380S

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
-----			-----	-----
TOTAL LABOUR CHARGES			10301.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLN3808

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/NETT REMARKS
		NETT	LIST		
1 S/TYRE HOUSING FOAM ?	84975-3ZL0A	500.00			
2 HEAT SHIELD EXHAUST SUB bt ?	74762-BC40A	152.60			
3 HEAT SHIELD EXHAUST (MAIN) bt ✓	74772-1KE0A	116.40			
4 EXHUST MOUNTING \$12.70 EA X 03 ?	20651-1KB1A				38.10
5 REAR BUMPER SPOILER cm ✓	YH5920-00C13				380.00
6 EMBLEM REAR m ✓	90891-3GF0B	115.60			
7 EMBLEM-BACK DOOR m ✓	90890-3ZL0A	72.20			
8 EMBLEM RAD GRIL m ✓	62890-1DA0B	72.20			
9 STRIKER BACK DOOR ?	90570-3ZL1A	128.70			
10 A LOCK LIFT TAILGATE ?	90502-4EA0A	192.60			
11 W/STRIP TAILGATE ?	90830-3ZL0C	225.70			
12 GLASS BACK DOOR X	90300-3ZL0A	1156.30			
13 DOOR A BACK TAILGATE rgm ✓	K0100-3ZLAA	4487.30			
14 GROMMET BUMPER REAR \$1.00 EA X 02 m ✓	63846-5V000	6.00			
15 REINFORCEMENT REAR BUMPER ?H ✓	H5030-3ZLMA	736.50			
16 ABS ENERGY RH REAR BUMPER .X ✓	85092-3ZL0A	239.40			
17 ABS ENERGY LH REAR BUMPER ?cm ✓	85093-3ZL0A	182.70			
18 BRKT REAR BUMPER RH X	85226-3ZL0A	81.60			
19 BRKT REAR BUMPER LH m ✓	85227-3ZL0A	81.60			
20 FASCIA KIT REAR de ✓	H5022-3ZLMH	1657.20			
21 BOARD A LUGGAGE S/TYRE ?	84906-3ZL1A	743.80			
22 PLATE LUGGAGE END PANEL ?	84992-3ZL0A	271.60			
23 WTT EXHAUST SHIELD HEAT \$2.10 EA X 15 m ✓	01241-01131				31.50
24 WTT STAY REAR m X	H5210-3ZLMA	880.50			
25 WTT STAY REAR m X	H5211-3ZLMA	880.40			

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM3808

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 MALE A HOOD ?	65601-32P0A	206.90		
27 CLIP-HOOD INSUL \$1.30 EA X 08 X	65846-40P00	10.40		
28 AIR GUIDE FRT RH ?	62822-3ZL0A	119.70		
29 AIR GUIDE FRT LH ?	62823-3ZL0A	175.90		
30 GRILLE RADIATOR con	62310-3ZL0A	697.90		
31 BRKT FRONT BUMPER RH m	62224-3ZL0A	23.30		
32 BRKT FRONT BUMPER LH m	62225-3ZL0A	23.30		
33 BRKT APRON LOWER BUMPER FRONT ?	62663-3ZL0A	151.40		
34 ARMATURE BUMPER FRONT dbt	F2030-3ZLAA	608.80		
35 ABS ENERGY BUMPER FRONT con	62090-3ZL0A	239.40		
36 CLIP BUMPER/GRILLE/PROETCOR \$1.50 EA X 33 m	01553-10501	49.50		
37 FASCIA KIT FRT de	F2022-3ZLMH	1614.70		
38 WHEEL A STEERING cut	48430-3ZL2C			668.70
39 COND & LIQUID bt	92100-BA61B			604.50
40 CLIP C/LAMP \$7.30 EA X 02 m	26398-9N00A			14.60
41 GROMET C/LAMP \$5.40 EA X 02 m	26557-2U000	10.80		
42 COMB LAMP LH TAILGATE sur	26555-3ZP5B	514.60		
43 COMB LAMP LH COMB sur	26555-3ZL0A	514.60		
44 GROMMET H/LAMP \$3.00 EA X 02 m	76848-AS500	6.00		
45 BRKT A H/LAMP LH/RH \$60.20 EA X 02 m	26042-3ZL0A			120.40
46 HEAD LAMP RH con	26010-3ZP5A	1511.90		
47 HEAD LAMP LH con	26060-3ZP5A	1511.90		
48 CLIP ANTENNA \$4.00 EA X 02 m	63848-89900	8.00		
49 ANTENNA-SMART RE/LESS ?	28585-JK60A	53.50		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLM3806

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
50 BRKT DISTANCE FRONT BUMPER <i>.short</i>	28452-3EL1A			896.50	
51 SENSOR BUMPER FRONT DISTANCE <i>?</i>	28438-3ZUID			1211.20	
52 HORN-ANTI THEFT LOW <i>?</i>	25605-3EL0A			68.00	
53 HORN A ELECTRIC HIGH <i>?</i>	25610-3EL0B			111.70	
54 TANK A RADIATOR <i>de</i>	21710-3ZU0A			152.30	
55 MOUNTG RUBR-RADIATOR \$7.60 EA X 03	21506-AX600			22.80	
56 RADIATOR <i>?</i>	21410-HXS1B			836.00	
57 GASKET SUB MUFFLER <i>m</i>	20692-8H30A			19.70	
58 MUFFLER SUB <i>St</i>	20300-3ZU0B			843.80	
59 GASKET-EXHAUST MUFFLER <i>m</i>	20691-9Y400			7.00	
60 MUFFLER ASSY (REAR) <i>St</i>	20100-3ZU0A			1116.80	
61 RUBBER INSERT SEAL SPOILER \$18.00 EA X 02 <i>m</i>	Y03000-00C11			36.00	
62 NISSAN SILL COOLANT \$9.50 EA X 02 <i>?</i>	NC-01			19.00	
63 SUNDRIES	NPN			40.00	
64 REAR LICENCE PLATE (SMART PLATE WITH CASING) LONG RLP <i>con</i>				60.00	
65 FRT LICENCE PLATE (SMART PLATE WITH CASING) LONG FLP <i>con</i>				60.00	
SUB TOTAL		20953.40	0.00	7358.60	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		4190.68	0.00	0.00	
GRAND TOTAL		16762.72	0.00	7358.60	
OVERALL TOTAL		24121.32			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TINAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLM380S

TOTAL LABOUR CHARGES	10301.00
TOTAL SPARE PARTS CHARGES	24121.32
GRAND TOTAL	34422.32 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME

SURVEYED DATE

AUTHORIZED DATE

EXCESS CLAUSE

LIABILITY

REMARKS

NAME - 1p 90010068
16/06/23 01445

14 days

0.00

0.00

EXCESS: 500

Revers

Resy before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

368I

Vehicle Details

Vehicle No.:

SLM3805

Vehicle to be Exported:

No

Intended Deregistration Date:

14 Jun 2023

Vehicle Make:

NISSAN

Vehicle Model:

PULSAR 1.2L DIG-T

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

HRA2395739A

Chassis No.:

VSKDDAC13U0098602

Maximum Power Output:

85.0 kW (113 bhp)

Open Market Value:

\$17,532.00

Original Registration Date:

24 Oct 2017

First Registration Date:

24 Oct 2017

Transfer Count:

0

Actual ARF Paid:

\$7,532.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

23 Oct 2027

PARF Rebate Amount:

\$5,272.00

Intended COE Rebate Details

COE Expiry Date:

23 Oct 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$41,617.00

COE Rebate Amount:

\$18,134.00

Total Rebate Amount:

\$23,406.00

The information contained herein is correct as at 14 Jun 2023

OK

Nissan Pulsar 1.2A DIG-T

\$55,800 Instalment \$911/mth

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation	i \$12,910 / year
Reg. Date	30-Jun-2017 (4yrs 10days COE left)
Manufactured	i 2017
Mileage	-
Transmission	Auto
Engine Cap	1,197 cc
Road Tax	i \$508 / year
Power	85.0 kW (113 bhp) View specs of the Nissan Pulsar (2017-2017)
Curb Weight	i 1,265 kg
COE	i \$42,801
OMV	i \$17,532
ARF	i \$7,532
Dereg Value	i \$22,522 as of today
No. of Owners	i 1