

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/0562/2023/EQ  
**DATE** : 13-Jun-23  
**WIP** : 24497

**VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/6/2023**  
**YOUR INSURED VEH NO : SLZ 1241 K**

**Allianz Insurance Singapore Pte Ltd**

79 Robinson Road

#09-01

Singapore 068897

Attn: Motor Claims Dept

**OWNER'S NAME** : MR KOH POH HONG  
**ADDRESS** : 17F JALAN HOCK CHYE  
SINGAPORE 538200

**TELEPHONE** : HP +65 96660018  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : 2100426879-07  
**VEHICLE NO** : **SKV 186 B**  
**MODEL CODE** : AUDI A1 SPORTBACK 1.0 TFSI S-TRONIC  
**MODEL YEAR** : 26/8/2015  
**ENGINE NO** : CHZ 002482  
**CHASSIS NO** : WAUZZZ8X9FB028134  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 10-Jun-23  
**PLACE OF ACCIDENT** : SENTOSA GATEWAY TUNNEL KEPPEL ROAD EXIT TOWARDS  
AYE (KEPPEL ROAD)

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

### ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 186 B - FRONT

| S/N                                 | NATURE OF JOBS                                                                                                                                                                                               | ESTIMATED CHARGES      | SURVEYOR'S RECOMMENDATIONS |
|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|----------------------------|
| 1                                   | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.                                                                                | S/N \$ 360.00          | ?                          |
| 2                                   | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                                                                       | S/N \$ 700.00          | <del>?</del> ?             |
| 3                                   | TO REMOVE AND RENEW AIRCON CONDENSER, ADDITIONAL RADIATOR AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS.                                    | S/N \$ 1,400.00        | ?                          |
| 4                                   | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ <del>5,600.00</del> | 1400                       |
| 5                                   | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS AND BONNET.                                                                                                                                                      | \$ <del>3,600.00</del> | 1400                       |
| <b>TOTAL LABOUR CHARGES - FRONT</b> |                                                                                                                                                                                                              | <b>: \$ 11,660.00</b>  |                            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 186 B - REAR**

| S/N                                | NATURE OF JOBS                                                                                                                                                                        |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                                  | TO REMOVE AND TRANSFER REAR PARKING AID.                                                                                                                                              | S/N \$ | 280.00               | ✓                             |
| 2                                  | TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE<br>LOCK SYSTEM WIRE HARNESS FOR TAIL LIGHTS AND REAR<br>LID WIPER ASSY.                                                                 | S/N \$ | 480.00               | ✓                             |
| 3                                  | TO RENEW REAR WINDSCREEN.                                                                                                                                                             | S/N \$ | 480.00               | ✓                             |
| 4                                  | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.                                                                                                                                            | S/N \$ | 400.00               | ✓                             |
| 5                                  | TO CARRY OUT WATER SEEPAGE TEST FOR REAR<br>WINDSCREEN.                                                                                                                               | S/N \$ | 200.00               | ✓                             |
| 6                                  | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR<br>LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS,<br>ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR<br>DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ | 1,400.00             | ✓                             |
| <b>TOTAL LABOUR CHARGES - REAR</b> |                                                                                                                                                                                       | :      | <b>\$ 3,240.00</b>   |                               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKV 186 B - REAR**

| S/N                                            | NATURE OF JOBS                                                                                                                                                           | ESTIMATED CHARGES     | SURVEYOR'S RECOMMENDATIONS |
|------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 7                                              | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.<br>TO CUT OUT AND WELD REAR END PANELLING. RE-<br>ORGANIZE CRASH MANAGEMENT COMPONENTS.<br>REINSTALL ALL PARTS REMOVED. | \$ 4,200.00           | 1400                       |
| 8                                              | TO RESPRAY REAR BUMPER, REAR LID, REAR END<br>PANELLING AND SPARE WHEEL HOUSING.                                                                                         | \$ 3,500.00           | 1400                       |
| 9                                              | TO CARRY OUT STONE CHIP TREATMENT AND SEALANT<br>WORKS ON REAR END PANELLING.                                                                                            | S/N \$ 280.00         | ?                          |
| 10                                             | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                           | S/N \$ 192.00         | ✓                          |
| <b>TOTAL LABOUR CHARGES - FRONT &amp; REAR</b> |                                                                                                                                                                          | <b>: \$ 23,072.00</b> |                            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 186 B - FRONT**

|                                      |                                                            |     |        | DAMAGED PARTS & PRICES |         |
|--------------------------------------|------------------------------------------------------------|-----|--------|------------------------|---------|
| S/N                                  | PARTS DESCRIPTION                                          | QTY | S/NETT | S/NETT                 | REMARKS |
| 1                                    | FRONT BUMPER <i>Dented</i>                                 | 1   | \$     | 1,839.00               | ✓       |
| 2                                    | FRONT BUMPER FIXING PARTS <i>new</i>                       | 1   | \$     | 274.00                 | ✓       |
| 3                                    | FRONT WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i>     | 2   | \$     | 40.00                  | ✓       |
| 4                                    | FRONT BUMPER GRILLE - CENTER <i>Crushed</i>                | 1   | \$     | 231.00                 | ✓       |
| 5                                    | FRONT BUMPER CLOSING ELEMENT <i>new</i>                    | 1   | \$     | 198.00                 | +       |
| 6                                    | FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>1st missing</i> | 2   | \$     | 956.00                 | 478     |
| 7                                    | RADIATOR GRILLE <i>Crushed</i>                             | 1   | \$     | 1,140.00               | ✓       |
| 8                                    | CAUTION SIGN STICKER <i>2 new</i>                          | 1   | \$     | 17.00                  | ✓       |
| 9                                    | AIR CONDITIONER STICKER <i>1 new</i>                       | 1   | \$     | 45.00                  | ✓       |
| 10                                   | FRONT BUMPER SIDE REINFORCEMENT <i>?</i>                   | 1   | \$     | 813.00                 | ?       |
| 11                                   | FRONT BUMPER FOAM FILLER PIECE <i>?</i>                    | 1   | \$     | 139.00                 | ?       |
| 12                                   | HORN HIGH TONE - RH <i>2 new</i>                           | 1   | \$     | 255.00                 | +       |
| 13                                   | HORN LOW TONE - LH <i>1 new</i>                            | 1   | \$     | 255.00                 | +       |
| 14                                   | FRONT FENDER - LH / RH <i>2</i>                            | 2   | \$     | 2,108.00               | ✓       |
| 15                                   | FRONT FENDER ATTACHMENT PARTS                              | 1   | \$     | 49.00                  | ✓       |
| 16                                   | FRONT FENDER BRACKET - LH / RH                             | 2   | \$     | 142.00                 | ✓       |
| 17                                   | FRONT FENDER RIVET                                         | 4   | \$     | 16.00                  | ✓       |
| 18                                   | FRONT FENDER BRACE - LH / RH                               | 2   | \$     | 128.00                 | ✓       |
| 19                                   | FRONT WHEEL HOUSING LINER - LH / RH                        | 2   | \$     | 396.00                 | ✓       |
| 20                                   | BONNET <i>Dented</i>                                       | 1   | \$     | 2,427.00               | ✓       |
| <b>SUB TOTAL SPARE PARTS - FRONT</b> |                                                            |     | :      | <b>\$ 11,468.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 186 B - FRONT**

|                                      |                                                 |     | DAMAGED PARTS & PRICES |         |  |
|--------------------------------------|-------------------------------------------------|-----|------------------------|---------|--|
| S/N                                  | PARTS DESCRIPTION                               | QTY | S/NETT                 | REMARKS |  |
| 21                                   | BONNET ATTACHMENT PARTS <i>new</i>              | 1   | \$ 153.00              | f       |  |
| 22                                   | BONNET EDGE PROTECTION <i>new</i>               | 1   | \$ 24.00               | ✓       |  |
| 23                                   | BONNET CATCH HOOK <i>new</i>                    | 1   | \$ 75.00               | f       |  |
| 24                                   | BONNET CATCH HOOK <i>new</i>                    | 1   | \$ 78.00               | f       |  |
| 25                                   | BONNET LOCK BAR - LH / RH <i>new</i>            | 2   | \$ 119.00              | f       |  |
| 26                                   | BONNET LOCK - LH / RH <i>new</i>                | 2   | \$ 481.00              | x       |  |
| 27                                   | BONNET BOWDEN CABLE - CENTER <i>new</i>         | 1   | \$ 67.00               | f       |  |
| 28                                   | BONNET RELEASE CABLE COVER <i>new</i>           | 1   | \$ 12.00               | f       |  |
| 29                                   | HEADLIGHT MOUNTING - LH / RH <i>new</i>         | 2   | \$ 280.00              | f       |  |
| 30                                   | HEADLIGHT FOR GAS DISCHARGE LAMP - LH / RH ?    | 2   | \$ 4,402.00            | ?       |  |
| 31                                   | LIFT CYLINDER - LH / RH <i>new</i>              | 2   | \$ 330.00              | +       |  |
| 32                                   | LIFT CYLINDER HOSE <i>new</i>                   | 1   | \$ 208.00              | +       |  |
| 33                                   | LOCK CARRIER <i>new?</i>                        | 1   | \$ 1,203.00            | ?       |  |
| 34                                   | CROSS MEMBER REINFORCEMENT - LH / RH <i>new</i> | 2   | \$ 59.00               | +       |  |
| 35                                   | OUTSIDE TEMPERATURE SENSOR BRACKET <i>new</i>   | 1   | \$ 22.00               | f       |  |
| 36                                   | A/C CONDENSER WITH DRYER <i>new</i>             | 1   | \$ 641.00              | +       |  |
| 37                                   | ADDITIONAL RADIATOR <i>new</i>                  | 1   | \$ 913.00              | +       |  |
| 38                                   | RADIATOR <i>new</i>                             | 1   | \$ 1,023.00            | +       |  |
| 39                                   | READY-MIX COOLANT ?                             | 6   | \$ 326.00              | ?       |  |
| 40                                   | RADIATOR SEAL - LOWER <i>new</i>                | 1   | \$ 17.00               | +       |  |
| <b>SUB TOTAL SPARE PARTS - FRONT</b> |                                                 | :   | <b>\$ 10,433.00</b>    |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 186 B - FRONT**

|                                  |                                  |     | DAMAGED PARTS & PRICES |         |
|----------------------------------|----------------------------------|-----|------------------------|---------|
| S/N                              | PARTS DESCRIPTION                | QTY | S/NETT                 | REMARKS |
| 41                               | RADIATOR SEAL - LH / RH          | 2   | \$ 46.00               | f       |
| 42                               | ADDITIONAL RADIATOR SEAL - LOWER | 1   | \$ 29.00               | f       |
| 43                               | RADIATOR AIR GUIDE - LH / RH     | 2   | \$ 84.00               | f       |
| 44                               | FRONT NUMBER PLATE               | S/N | \$ 60.00               | ✓       |
| <b>TOTAL SPARE PARTS - FRONT</b> |                                  | :   | <b>\$ 22,120.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 186 B - REAR**

|                                     |                                                                |     | DAMAGED PARTS & PRICES       |         |  |
|-------------------------------------|----------------------------------------------------------------|-----|------------------------------|---------|--|
| S/N                                 | PARTS DESCRIPTION                                              | QTY | S/NETT                       | REMARKS |  |
| 1                                   | REAR BUMPER <i>Distorted</i>                                   | 1   | \$ 1,717.00                  | ✓       |  |
| 2                                   | REAR BUMPER FIXING PARTS <i>new</i>                            | 1   | \$ 83.00                     | +       |  |
| 3                                   | REAR BUMPER SPOILER <i>Del'd</i>                               | 1   | \$ 496.00                    | -       |  |
| 4                                   | REAR BUMPER REFLECTOR - LH / RH <i>RH cancelled</i>            | 2   | \$ <del>720.00</del> 36      |         |  |
| 5                                   | REAR LICENCE PLATE LIGHT - LH / RH <i>new</i>                  | 2   | \$ 136.00                    | +       |  |
| 6                                   | REAR TAIL LIGHT - LH / RH <i>RH cancelled</i>                  | 2   | \$ <del>2,980.00</del> 1490. |         |  |
| 7                                   | REAR BUMPER REINFORCEMENT BEAM                                 | 1   | \$ 597.00                    | ?       |  |
| 8                                   | REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>                 | 2   | \$ 114.00                    | ✓       |  |
| 9                                   | REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece missing</i> | 3   | \$ <del>815.00</del> 203.75  |         |  |
| 10                                  | REAR PARKING AID SEAL RING <i>new</i>                          | 4   | \$ 6.00                      | +       |  |
| 11                                  | REAR BUMPER WIRING SET <i>new</i>                              | 1   | \$ 688.00                    | +       |  |
| 12                                  | REAR LID <i>Del'd</i>                                          | 1   | \$ 3,732.00                  | ✓       |  |
| 13                                  | REAR LID ATTACHMENT PARTS <i>new</i>                           | 1   | \$ 317.00                    | +       |  |
| 14                                  | REAR LID LOCK <i>new</i>                                       | 1   | \$ 196.00                    | +       |  |
| 15                                  | REAR LID FLAP LOCK COVER CAP <i>new</i>                        | 1   | \$ 9.00                      | +       |  |
| 16                                  | REAR LID EXTERIOR DOOR HANDLE <i>new</i>                       | 1   | \$ 222.00                    | +       |  |
| 17                                  | REAR LID EXTERIOR DOOR HANDLE COVER CAP <i>new</i>             | 1   | \$ 15.00                     | +       |  |
| 18                                  | REAR LID STRIKER PLATE <i>new</i>                              | 1   | \$ 143.00                    | +       |  |
| 19                                  | REAR LID FLAP GASKET <i>new</i>                                | 1   | \$ 182.00                    | +       |  |
| 20                                  | PACKING ADHESIVE <i>new</i>                                    | 1   | \$ 22.00                     | ✓       |  |
| <b>SUB TOTAL SPARE PARTS - REAR</b> |                                                                | :   | <b>\$ 12,542.00</b>          |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKV 186 B - REAR**

|                                                |                         |     | DAMAGED PARTS & PRICES |         |
|------------------------------------------------|-------------------------|-----|------------------------|---------|
| S/N                                            | PARTS DESCRIPTION       | QTY | S/NETT                 | REMARKS |
| 21                                             | AUDI EMBLEM             | 1   | \$ 152.00              | ✓       |
| 22                                             | "A1" INSCRIPTION        | 1   | \$ 110.00              | ✓       |
| 23                                             | "TFSI" INSCRIPTION      | 1   | \$ 110.00              | ✓       |
| 24                                             | REAR WINDOW             | 1   | \$ 914.00              | ✓       |
| 25                                             | WINDOW PRIMER           | 1   | \$ 24.00               | ✓       |
| 26                                             | REAR CROSS PANEL TRIM   | 1   | \$ 260.00              | ✗       |
| 27                                             | REAR LID TRIM PANEL     | 1   | \$ 473.00              | ?       |
| 28                                             | REAR END PANEL - OUTER  | 1   | \$ 450.00              | ?       |
| 29                                             | REAR END PANEL - INNER  | 1   | \$ 1,302.00            | ?       |
| 30                                             | REAR NUMBER PLATE       | S/N | \$ 60.00               | ✓       |
| 31                                             | REAR WINDSCREEN SEALANT | S/N | \$ 200.00              | ✓       |
| 32                                             | ACRYLIC SEALANT         | S/N | \$ 180.00              | ✓       |
| 33                                             | CAVITY WAX              | S/N | \$ 140.00              | ?       |
| 34                                             | STONE CHIP              | S/N | \$ 180.00              | ?       |
| 35                                             | METAL FILLER POWDER     | S/N | \$ 280.00              | ?       |
| 36                                             | SUNDRIES                |     | \$ 700.00              | ?       |
| <b>TOTAL SPARE PARTS - FRONT &amp; REAR</b>    |                         | :   | <b>\$ 40,197.00</b>    |         |
| <b>TOTAL LABOUR CHARGES - FRONT &amp; REAR</b> |                         | :   | <b>\$ 23,072.00</b>    |         |
| <b>GRAND TOTAL</b>                             |                         | :   | <b>\$ 63,269.00</b>    |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian Lim

SURVEYED DATE

: 15/06/28. J

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 09 Days.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,

PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT