

(08/11/13)

wef

REF:

CC4/LPC23006108/Rpa3

2004

ASS. REC. BY:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SNF 6573Bat Workshop m/s BORNEOof PANDAN CRESCENT

Insured:

LPC

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

136K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SNF 6573B

Yr Regn:

2022 JunType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA SIENNA HYBRID ST c.c. 1497

Colour:

BLACK

A/C: Insured / Std / NI / NA

Sp. Reading

80409

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

3TD 229H 330 L001013Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

13/06/23

D.O.I.

13/06/23

Survey held at

BORNEODes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LUM SUM - 65K

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$))

TOTAL



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia			S1000007 / ICLP11		M/S Grab Rentals Pte. Ltd		
			Document No. 0		3 Media Close #01-03/06 Singapore 138498		
			Document Date 13/06/2023		Work: 65703925		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDZZ9H330L001013		1NZ9398158	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR POLICY NO.:XB9047L ACC DATE:13/06/23 DRIVE IN:13/06/23 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00	
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST				198.00	
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00	
5	L	BP-LPO SUPPLY REAR REGN PLATE (PO#)				80.00	
6	L	BP-LPO SUPPLY PHV STICKER				20.80	
7	B	BP-LAB2 REMOVE AND TRANSFER TAILGATE COMPARTMENT				594.00	
8	B	BP-LAB2 REMOVE AND REPLACE TAILGATE GLASS				594.00	
9	B	BP-LAB2 REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR				792.00	
10	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN AND PANEL BEAT ACC AFF AREA				4752.00	
11	B	BP-RES2 RESPRAY ACC ACC AREA	1.00	431.30		396 431.30	
12	1	T52159-52978 COVER, RR BUMPER	10.00	5.70		53 57.00	
13	2	T52161-16010 PIECE, RR BUMPER	1.00	128.40		128.40	
14	3	T52155-52131 SUPPORT, RR BUMPER					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.		Customer Details				
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLPI1		M/S Grab Rentals Pte. Ltd				
		Document No. 0		3 Media Close #01-03/06 Singapore 138498				
		Document Date 13/06/2023		Work: 65703925				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDZZ9H330L001013		1NZ9398158	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
15	4	T52156-52130	SUPPORT, RR BUMPER	1.00	128.40		128.40	
16	5	T52575-52200	RETAINER, RR BUMPER	1.00	95.40		95.40	
17	6	T52576-52180	RETAINER, RR BUMPER	1.00	95.40		95.40	
18	7	T52591-52360	SEAL, RR BUMPER	1.00	78.70		78.70	
19	8	T52592-52350	SEAL, RR BUMPER	1.00	78.70		78.70	
20	9	T52151-52010	EXTENSION, RR BUMPER	1.00	243.00		243.00	
21	0	T52161-52170	EXTENSION, RR BUMPER	1.00	165.20		165.20	
22	1	T52162-52150	EXTENSION, RR BUMPER	1.00	165.20		165.20	
23	2	T58307-52670	PANEL SUB-ASSY, BODY	1.00	588.10		588.10	
24	3	T58302-52162	PANEL SUB-ASSY, LWR	1.00	944.00		944.00	
25	4	T64716-52180 C0	COVER, DECK TRIM, RR	1.00	188.20		188.20	
26	5	T64421-52100 C0	TRAY, LUGGAGE	1.00	571.60		571.60	
27	6	T58408-52100 C0	BOARD SUB-ASSY, X	1.00	357.90		357.90	
28	7	T67005-52E50	PANEL SUB-ASSY, BACK	1.00	1535.20		1535.20	
29	8	T67881-52220	WEATHERSTRIP, BACK	1.00	476.60		476.60	
30	9	T67750-52100 C0	BOARD ASSY, BACK	1.00	176.60		176.60	
31	0	T68105-52660	GLASS SUB-ASSY, BACK	1.00	1404.30		1404.30	
32	1	T56117-64010	DAM, WINDOW GLASS	1.00	66.30		66.30	
33	2	T68950-0W840	STAY ASSY, BACK	1.00	310.80		310.80	
34	3	T68960-0W840	STAY ASSY, BACK	1.00	310.80		310.80	
For & on behalf of		Customer's Signature		Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors



TOYOTA

inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details					
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		S1000007 / ICLP1	M/S Grab Rentals Pte. Ltd					
		Document No. 0	3 Media Close #01-03/06 Singapore 138498					
		Document Date 13/06/2023	Work: 65703925					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2022	NHP170R	MWXNB H2	15/06/2022	SNF6573B	0	22497	75/DS/SNF6573B	
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On			
JTDZZ9H330L001013	1NZ9398158	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
35	4	T69350-52401	LOCK ASSY, BACK DOOR	XN1	1.00	599.10		599.10
36	5	T69430-52050	STRIKER ASSY, BACK	XN1	1.00	33.20		33.20
37	6	T76801-52411 C1	GARNISH SUB-ASSY,	XN1	1.00	266.80		266.80
38	7	T75403-52010	EMBLEM SUB-ASSY,		1.00	86.60		86.60
39	8	T75441-52170	PLATE, BACK DOOR		1.00	66.60		66.60
40	9	T81551-52E30	LENS & BODY, RR		1.00	479.80		479.80
41	0	T81561-52E30	LENS & BODY, RR		1.00	479.80		479.80
42	1	T81581-52380	LENS & BODY, RR		1.00	258.60		258.60
43	2	T81591-52380	LENS & BODY, RR		1.00	258.60		258.60
44	3	T81270-0D120	LAMP ASSY, LICENSE		1.00	84.20		84.20
45	4	T81910-52030	REFLECTOR ASSY, X	N1	1.00	77.20		77.20
46	5	T81920-52030	REFLECTOR ASSY, X	N1	1.00	77.20		77.20
47	6	SPC507-0D014 209	BACK SENSOR 209, BLACK MICA-	XN1	1.00	172.40		172.40
48	7	T21000-20	SIKA 182010 SIKA TACK GO! (BLA	N1	1.00	108.00		108.00
49	8	T21000-22	SIKA 207. G+P ADHESIVE PRIMER		1.00	200.00		200.00

Handwritten notes:
Panel
HP 9001068
5 days
13/06/23 P1615
Resin by part

For & on behalf of		Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts	23,310.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			Labour	1,864.80
			Sublet	
			Lubrication/Fluid	
			Others	
			Less	0.00
			Amount Due	25,174.80

Customer Copy