

# FC Garage

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #04-03 Singapore 415875

Tel: 90110243

CO. Reg. No.: 53409207A

Model : **HONDA SHUTTLE**  
 Registraion No : **SMP6357T**  
 Chassis No: **GK8-2100225**  
 Year of Manufacturing: **2019**

TP HSBC.  
 Xiao Tony

| S/No | Qty | Items                                        | Unit Price | Amount      |
|------|-----|----------------------------------------------|------------|-------------|
| 1    | 1   | FRONT BUMPER <i>Replaced</i>                 | \$ 729.74  | \$ 729.74 ✓ |
| 2    | 1   | FRONT BUMPER RETAINER (LH) <i>Replaced</i>   | \$ 9.42    | \$ 9.42 ✓   |
| 3    | 1   | FRONT BUMPER TOWING COVER <i>New</i>         | \$ 21.19   | \$ 21.19 +  |
| 4    | 1   | FRONT BUMPER LOWER GRILLE <i>New</i>         | \$ 105.93  | \$ 105.93 + |
| 5    | 1   | FRONT BUMPER FOG LAMP GARNISH LHS <i>New</i> | \$ 94.16   | \$ 94.16 +  |
| 6    | 1   | FRONT BUMPER UPPER GRILLE BASE <i>New</i>    | \$ 211.86  | \$ 211.86 + |
| 7    | 1   | FRONT BUMPER UPPER GRILLE CHROME <i>New</i>  | \$ 317.79  | \$ 317.79 + |
| 8    | 1   | FRONT BUMPER EMBLEM - LOGO <i>New</i>        | \$ 294.25  | \$ 294.25 + |
| 9    | 1   | FRONT SUPPORT PANEL <i>New</i>               | \$ 447.26  | \$ 447.26 + |
| 10   | 1   | FRONT BUMPER REINFORCEMENT <i>New</i>        | \$ 317.79  | \$ 317.79 + |
| 11   | 1   | FRONT BONNET <i>New</i>                      | \$ 647.35  | \$ 647.35 + |
| 12   | 1   | FRONT HEADLAMP RH <i>Changed</i>             | \$ 564.96  | \$ 564.96 ✓ |
| 13   | 1   | FRONT FENDER RH <i>Repaired</i>              | \$ 211.86  | \$ 211.86 + |
| 14   | 1   | FRONT FENDER SHIELD RH <i>Repaired</i>       | \$ 100.05  | \$ 100.05 + |
| 15   | 1   | FRONT HEADLAMP BRACKET RH <i>Repaired</i>    | \$ 47.08   | \$ 47.08 +  |

\$ 4,120.69

-20% \$ 824.14

Total for spare parts \$ 3,296.55

1404.17  
 less 20%: 1123.33

**Special Nett**

|   |    |                              |                              |                               |
|---|----|------------------------------|------------------------------|-------------------------------|
| 1 | 10 | FRONT BUMPER CLIPS <i>RV</i> | \$ 5.00                      | \$ <del>50.00</del> <i>30</i> |
|   |    |                              | <b>Total for SP</b>          | <b>\$ 50.00</b>               |
|   |    |                              | <b>Sub-Total for Parts :</b> | <b>\$ 3,346.55</b>            |

| S/No | Qty | Items                                                                                                                                  | Unit Price | Amount                          |
|------|-----|----------------------------------------------------------------------------------------------------------------------------------------|------------|---------------------------------|
| 1    |     | To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts |            | \$ <del>600.00</del> <i>300</i> |
| 2    |     | To putty and spray paint on all accident damage parts and other accident affected areas                                                |            | \$ <del>600.00</del> <i>400</i> |
| 3    |     | Apply rust proofing on the adjacent panels                                                                                             |            | \$ <del>80.00</del> <i>30</i>   |
| 4    |     | To supply under coating / putty on parts replaced                                                                                      |            | \$ 80.00 <i>X</i>               |
| 5    |     | To perform water seepage test after repair                                                                                             |            | \$ 80.00 <i>X</i>               |
| 6    |     | Disconned and check electrical wiring, harness, wire socket                                                                            |            | \$ <del>60.00</del> <i>30</i>   |
| 7    |     | Reset engine management system with diagnostic fault                                                                                   |            | \$ 80.00 <i>X</i>               |

**TOTAL AMOUNT : \$ 1,580.00**  
**OVERALL COST: \$ 4,926.55**

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*Adrian Lj*  
*L/S 16/06/23.*  
*03 Days.*  
*96893735.*

*total: 1913.33*  
*L/S: 1.5K.*