



HKL LIM TEAM MOTORSPORT PTE LTD

UEN: 202218929Z

Blk 1008 #01-24 Bukit Merah Lane 3, Singapore 159722.

Tel: 6275 6656 Email: hklimteam@gmail.com

FBK6264J

1	FRONT FORK ASSY LH/RH <i>repair</i>	\$2,400
2	FRONT FORK UNDER BRACKET <i>X</i>	\$420
3	STEERING CONE BEARING <i>X</i>	\$150
4	FRONT BRAKE DISC RH <i>X</i>	\$580
5	HANDLE BAR <i>bt</i>	\$280
6	HANDLE BAR BALANCER RH <i>sur</i>	\$45
7	BRAKE LEVER <i>bt</i>	\$95
8	SIDE MIRROR RH <i>ca</i>	\$150
9	ENGINE GUARD <i>sur</i>	\$180
10	EXHAUST GASKET <i>ca</i>	\$55
11	EXHAUST MUFFLER <i>bt</i>	\$850
12	TOP BOX <i>ca</i>	\$480
13	HEAD LIGHT COVER <i>cm</i>	\$220
14	HEAD LIGHT RIM <i>?</i>	\$180
15	HEAD LIGHT GLASS <i>?</i>	\$280
16	EXHAUST COVER <i>sur</i>	\$140
17	LABOUR	\$880 350

TOTAL AMOUNT:

\$7,085

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Repa
Hp 50010068 P/P
4 days / 1/1
16/06/23 @ 1200
Rey after repair