

FC Garage

NO.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #02-15 Singapore 415875

Tel: 90110243

CO. Reg. No.: 202115045W

Model : Mazda 6
 Registraion No : SLE7656T
 Chassis No: JM6GJ1072G0242212
 Year of Manufacturing: 2016

TP H=BC

Xiao Tong

S/No	Qty	Items	Unit Price	Amount
1	1	FRONT BUMPER <i>Del</i>	\$ 1,378.50	\$ 1,378.50 <i>1151</i>
2	1	FRONT BUMPER RETAINER LHS <i>one</i>	\$ 38.60	\$ 38.60 <i>+</i>
3	1	FRONT BUMPER BRACKET LHS <i>new</i>	\$ 68.50	\$ 68.50 <i>+</i>
4	1	FRONT BUMPER FOG LAMP LHS <i>new</i>	\$ 853.60	\$ 853.60 <i>+</i>
5	1	FRONT BUMPER FOG LAMP COVER LHS <i>new</i>	\$ 68.50	\$ 68.50 <i>+</i>
6	1	FRONT BUMPER FOG LAMP CHROME LHS <i>new</i>	\$ 212.20	\$ 212.20 <i>+</i>
7	1	HEADLAMP LHS <i>Sim</i>	\$ 4,357.50	\$ 4,357.50 <i>3209</i>
8	1	HEADLAMP BRACKET LHS <i>new</i>	\$ 68.50	\$ 68.50 <i>+</i>
9	1	FRONT FENDER LHS <i>Del</i>	\$ 643.20	\$ 643.20 <i>+</i>
10	1	FRONT FENDER SHIELD LHS <i>Del</i>	\$ 215.60	\$ 215.60 <i>+</i>
11	1	FRONT WHEEL BEARING WITH HUB LHS <i>new</i>	\$ 882.30	\$ 882.30 <i>525</i>
12	1	FRONT KNUCKLE LHS <i>Del</i>	\$ 637.50	\$ 637.50 <i>455</i>
13	1	FRONT ABSORBER LHS <i>new</i>	\$ 558.10	\$ 558.10 <i>+</i>

6198.80

Less 20%: 4959.04

	\$ 9,982.60
-20%	\$ 1,996.52
Total for spare parts	\$ 7,986.08

Special Nett

1	10	FRONT BUMPER CLIPS <i>new</i>	\$ 5.00	\$ 50.00 <i>30</i>
2	1	FRONT RIM LHS <i>at</i>	\$ 1,500.00	\$ 1,500.00 <i>650</i>
3	1	FRONT TYRE LHS <i>new</i>	\$ 800.00	\$ 800.00 <i>+</i>

Total for SP	\$ 2,350.00
Sub-Total for Parts :	\$ 10,336.08

680

S/No	Qty	Items	Unit Price	Amount
1		To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mention repair parts, inclusive of replacement parts.		\$ 1,000.00 500
2		To putty and spray paint on all accident damage parts and other accident affected areas		\$ 1,200.00 400
3		Apply rust proofing on the adjacent panels		\$ 80.00 30
4		To supply under coating / putty on parts replaced		\$ 80.00 +
5		To perform water seepage test after repair		\$ 80.00 +
6		Check and re-adjust wheel alignment	1190	\$ 120.00 80
7		Disconned and check electrical wiring, harness, wire socket		\$ 80.00 30
8		Reset engine management system with diagnostic fault		\$ 120.00 +
9		Remove and replace front undercarrige		\$ 250.00 7 150

TOTAL AMOUNT : \$ 3,010.00
OVERALL COST: \$ 13,346.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adnan L
w/s 16/06/23.
OSRy

total: 6829.04
L/s: S.H.K.

MotorMed Pte Ltd

8 Kaki Bukit Ave 4 #02-14/44

Premier @ Kaki Bukit

Singapore 415875

Phone Number: 69777077

Fax Number: 69777080

Customer:		Date:	16-Jun-23 11:44 AM
Company:	FC	VIN	SLE7656T
License NO:		Technician:	
Odometer:		Order NO:	

VEHICLE ALIGNMENT REPORT

MAZDA, 6 GL Series, 16-17 (Customized)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	5°13'	7°13'	----
		Right	----	5°13'	7°13'	----
	Camber	Left	-0°36'	-1°18'	0°42'	-0°36'
		Right	-0°06'	-1°18'	0°42'	-0°06'
	Toe	Left	1°21'	-0°05'	0°15'	1°21'
		Right	0°06'	-0°05'	0°15'	0°06'
Total		1°27'	-0°10'	0°29'	1°27'	
Rear	Camber	Left	-1°00'	-1°58'	0°02'	-1°00'
		Right	-1°06'	-1°58'	0°02'	-1°06'
	Toe	Left	0°03'	-0°05'	0°15'	0°03'
		Right	0°12'	-0°05'	0°15'	0°12'
		Total	0°15'	-0°10'	0°30'	0°15'
	Max Thrust Angle		0°05'	----		0°05'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI		Left	----	15°09'	15°09'	----
		Right	----	15°09'	15°09'	----
Included Angle		Left	----	----	----	----
		Right	----	----	----	----
Toe Out On Turns		Left	----	----	----	----
		Right	----	----	----	----
Max Turn Inside		Left	----	36°36'	42°36'	----
		Right	----	36°36'	42°36'	----
Toe Curve Change		Left	----	----	----	----
		Right	----	----	----	----
Setback		Front	0mm	----	----	0mm
		Rear	-6mm	----	----	-6mm
Track Width Diff.			11mm			11mm
Wheel Base Diff.			7mm			7mm
Front Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Rear Ride Height		Left	----	----	----	----
		Right	----	----	----	----
Frame Angle						----