

Date: 12/6/2023
Vehicle No: SNJ2569U
Model: HONDA FREED HYBRID 1.5G
Chassis: GB73150786
Reg.Year: 2021

Not Notation
Return B4 paint
5-6 day

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJR7374L
Date of Accident: 9/6/2023
Estimator: SIMON KOH
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER COVER <i>Buy</i>	1	\$ 987.00	\$ 987.00
2	FRONT RADIATOR GRILLE <i>Buy</i>	1	\$ 922.00	\$ 922.00
3	FRONT BUMPER LOWER GRILLE	1	\$ 181.00	\$ 181.00
4	FRONT BUMPER HOLE COVER LH	1	\$ 108.00	\$ <i>PL</i> 108.00
5	FRONT BUMPER SIDE BRACKET LH	1	\$ 34.00	\$ <i>DI</i> 34.00
6	FRONT HEADLAMP ASSY LH	1	\$ 1,920.00	\$ 1,920.00
7	FRONT HEADLAMP BRACKET LH	1	\$ 67.00	\$ 67.00
8	FRONT FENDER ASSY LH	1	\$ 986.00	\$ <i>R</i> 986.00
9	REAR BOOT COVER ASSY <i>Buy</i>	1	\$ 1,270.00	\$ 1,270.00
10	REAR BOOT HONDA LOGO EMBLEM <i>Buy</i>	1	\$ 76.00	\$ 76.00
11	REAR BOOT HYBRID EMBLEM <i>Buy</i>	1	\$ 97.00	\$ 97.00
12	REAR BOOT FREED WORDING EMBLEM <i>Buy</i>	1	\$ 79.00	\$ 79.00
13	REAR BOOT INNER TRIM BOARD	1	\$ 285.00	\$ 285.00
14	REAR BUMPER COVER <i>Buy</i>	1	\$ 1,008.00	\$ 1,008.00
15	REAR END PANEL	1	\$ 732.00	\$ 732.00
16	REAR END PANEL TOP COVER	1	\$ 129.00	\$ 129.00
SUB TOTAL				\$ 8,881.00
LESS 20%				-\$ 1,776.20
PARTS TOTAL				\$ 7,104.80

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1	\$ 50.00	\$ <i>Buy</i> 50.00
2	REAR BUMPER CLIPS	1	\$ 50.00	\$ <i>Buy</i> 50.00
3	FRONT NUMBER PLATE WITH CASING	1	\$ 60.00	\$ <i>Buy</i> 60.00
4	REAR NUMBER PLATE WITH CASING	1	\$ 60.00	\$ <i>Buy</i> 60.00
5	REAR WINDSCREEN SEALANT	1	\$ 80.00	\$ <i>Buy</i> 80.00
S/N TOTAL				\$ 300.00

LABOUR CHARGES:

LABOUR TO REMOVE, REPLACE/REPAIR, REALIGN AND REFIX THE LISTED ACCIDENT AFFECTED DAMAGED PARTS \$ 1,000.00

LABOUR TO REMOVE, TRANSFER AND REFIX REAR TAILGATE INNER MECHANISM, TRIM BOARD AND RELATED PARTS FROM DAMAGED TAILGATE TO NEW TAILGATE \$ 150.00

Head office

6 Kung Chong Road Singapore 159143
Tel (+65) 6472 1313 | Fax (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel (+65) 6484 9919 | Fax (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind Park 2A #01-05 Singapore 568047
Tel (+65) 6481 1522 | Fax (+65) 6481 1011



Date: 12/6/2023
Vehicle No: SNJ2569U
Model: HONDA FREED HYBRID 1.5G
Chassis: GB73150786
Reg.Year: 2021

Third Party Insurer: CHINA TAIPING
Third Party Veh No: SJR7374L
Date of Accident: 9/6/2023
Estimator: SIMON KOH
Surveyor:

LABOUR TO REMOVE AND REFIX REAR WINDSCREEN AND TO CHECK WATER LEAKAGE	\$	150.00	1201
LABOUR TO CHECK AND RECTIFY REAR REVERSE SENSOR WIRING SYSTEM FOR PROPER WORKING CONDITION	\$	120.00	501
LABOUR TO PUTTY, RESPRAY AND POLISH FRONT BUMPER, FRONT LH FENDER, REAR TAILGATE, REAR BUMPER AND OTHER ACCIDENT AFFECTED AREA	\$	1,000.00	8001
TO TUFF KOTE & UNDERSEAL MATERIALS	\$	120.00	?
LABOUR TOTAL	\$	2,540.00	

Simon	TOTAL	\$	9,944.80
-------	-------	----	----------

