

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Mr Lim Hai Min Benedict

Third Party Insurer: Allianz
 Date of accident : 14 June 2023
 Date: 15 June 2023

Estimate To Repair
 SLL3615B - Mazda 3 Sedan 1.5 AT
 Chassis No : JM6BN22A8H0141402

Click - 16/06/2023

S/No	Quantity	Description	Amount
LIST ITEMS			
1	1 pc	bootlid	\$ 958.00 <i>Rx</i>
2	1 pc	bootlid skyactiv badge	\$ 64.00 <i>as</i>
3	1 pc	bootlid mazda 3 badge	\$ 54.00 <i>as</i>
4	1 pc	rear end panel	\$ 556.00 <i>Rx</i>
5	1 pc	rear end panel inner trim	\$ 96.00 <i>X</i>
6	4 pc	rear end panel inner trim clips @ \$5.00	\$ 20.00 <i>X</i>
7	1 pc	rear bumper	\$ 1,075.00 <i>dl</i>
8	1 pc	rear bumper centre clips	\$ 12.50 <i>as</i>
9	1 pc	rear bumper reinforcement	\$ 558.00 <i>?</i>
10	2 pc	rear bumper side retainer @ \$92.00	\$ 184.00 <i>?</i>
11	2 pc	rear bumper side holder @ \$74.00	\$ 148.00 <i>?</i>
12	4 pc	rear bumper side holder rivet @ \$6.00	\$ 24.00 <i>as</i>
13	2 pc	rear bumper reflector @ \$55.00	\$ 110.00 <i>X</i>
14	2 pc	rear bumper screw @ \$9.00	\$ 18.00 <i>as</i>
15	1 pc	rear bumper screw spacer	\$ 10.00 <i>as</i>
16	2 pc	rear bumper tow cover @ \$18.00	\$ 36.00 <i>as</i> <i>RH</i>
17	1 pc	bonnet	\$ 1,068.00 <i>bt</i>
18	2 pc	bonnet hinge @ \$41.00	\$ 82.00 <i>bt</i>
19	10 pc	bonnet under weatherstirp clips @ \$4.00	\$ 40.00 <i>X</i>
20	1 pc	boonet lock	\$ 198.00 <i>?</i>
21	1 pc	bonnet lock stay	\$ 39.00 <i>?</i>
22	1 pc	boonet lock cover	\$ 11.00 <i>?</i>
23	1 pc	bonnet support panel-metal	\$ 140.00 <i>bt</i>
24	1 pc	bonnet support panel - fibre	\$ 470.00 <i>as</i>
25	2 pc	head lamp @ \$1020.00	\$ 2,040.00 <i>LH?</i> <i>RH as</i>
26	1 pc	radiator assy	\$ 1,065.00 <i>?</i>
27	1 pc	radiator fan motor assy	\$ 1,367.00 <i>?</i>
28	2 pc	radiator top mount bush	\$ 37.00 <i>?</i>
29	1 pc	radiator expansion tank	\$ 98.00 <i>?</i>
30	1 pc	radiator grille	\$ 150.00 <i>as</i>
31	2 pc	radiator grille chrome garnish @ \$183.00	\$ 366.00 <i>as</i>
32	2 pc	radiator grille chrome garnish base @ \$20.00	\$ 40.00 <i>as</i>
Balance c/f			\$ 11,134.50

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Mr Lim Hai Min Benedict

Third Party Insurer: Allianz
 Date of accident : 14 June 2023
 Date: 15 June 2023

Estimate To Repair
 SLL3615B - Mazda 3 Sedan 1.5 AT
 Chassis No : JM6BN22A8H0141402

S/No	Quantity	Description	Amount
		Balance b/f	\$ 11,134.50
33	2 pc	radiator grille side cover @ \$13.00	\$ 26.00 <i>de</i>
34	2 pc	radiator grille inner side bracket @ \$13.00	\$ 26.00 <i>de</i>
35	2 pc	radiator grille inner side bracket white clips @ \$5.00	\$ 10.00 <i>na</i>
36	2 pc	radiator grille inner side bracket white clips holder @ \$5.00	\$ 10.00 <i>na</i>
37	1 pc	radiator grille emblem badge	\$ 59.00 <i>na</i>
38	6 pc	radiator grille clips @ \$8.70	\$ 52.20 <i>na</i>
39	1 pc	radiator grille outer garnish	\$ 339.00 <i>na</i>
40	4 pc	radiator grille outer garnish rivets @ \$9.00	\$ 36.00 <i>na</i>
41	1 pc	radiator grille outer garnish support	\$ 185.00 <i>dis</i>
42	1 pc	radiator grille outer garnish top cover	\$ 40.00 <i>de</i>
43	5 pc	radiator grille outer garnish top cover clips @ \$5.00	\$ 25.00 <i>na</i>
44	3 pc	radiator grille outer garnish clips @ \$5.00	\$ 15.00 <i>na</i>
45	1 pc	radiator licence plate garnish	\$ 71.00 <i>de</i>
46	1 pc	front bumper	\$ 826.00 <i>de</i>
47	2 pc	front bumper side retainer @ \$19.00	\$ 38.00 <i>de</i>
48	1 pc	front bumper reinforcement	\$ 480.00 <i>na</i>
49	1 pc	front bumper reinforcement cover	\$ 98.00 <i>na</i>
50	4 pc	front bumper reinforcement cover @ \$4.00	\$ 16.00 <i>?</i>
51	2 pc	front bumper air guide @ \$56.00	\$ 112.00 <i>?</i>
52	1 pc	front bumper lower splashshield cover	\$ 84.00 <i>x</i>
53	8 pc	front bumper lower splashshield cover clips @ \$4.00	\$ 32.00 <i>x</i>
54	6 pc	front bumper air guide clips @ \$5.00	\$ 30.00 <i>x</i>
55	1 pc	front bumper lower support garnish	\$ 96.00 <i>x</i>
56	1 pc	front bumper tow cover	\$ 32.00 <i>int</i>
57	2 pc	front bumper fog lamp @ \$248.00	\$ 496.00 <i>HY R4?</i>
58	2 pc	front bumper fog lamp garnish @ \$25.00	\$ 50.00 <i>HY R4 de</i>
59	1 pc	air con condensor	\$ 987.00 <i>de</i>
60	1 pc	o/s front fender	\$ 334.00 <i>de</i>
61	1 pc	o/s front fender inner cowling	\$ 130.00 <i>x</i>
62	6 ps	o/s front fender inner cowling clips	\$ 5.00 <i>x</i>
63	1 pc	o/s front door (repair)	\$ 1,062.00 <i>Rx</i>
		Balance c/f	\$ 16,936.70

Ar

Ar

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Mr Lim Hai Min Benedict

Third Party Insurer: Allianz
 Date of accident : 14 June 2023
 Date: 15 June 2023

Estimate To Repair
 SLL3615B - Mazda 3 Sedan 1.5 AT
 Chassis No : JM6BN22A8H0141402

S/No	Quantity	Description	Amount
		Balance b/f	\$ 16,936.70
64	1 pc	front windscreen glass with moulding	\$ 1,062.00 <i>cut</i>
65	2 ps	front windscreen glass side garnish @ \$55.00	\$ 110.00 <i>cut</i>
66	1 pc	front licence plate garnish	\$ 71.00 <i>cut</i>
			\$ 18,108.70
		Less 20%	\$ 3,621.74
			\$ 14,486.96
		<u>SPECIAL NETT ITEMS</u>	
67	1 pc	rear licence plate	\$ 80.00 <i>X</i>
68	1 set	rear bumper parking sensor	\$ 450.00 <i>200 new</i>
69	1 pc	radiator coolant	\$ 20.00 <i>?</i>
70	1 pc	front licence plate	\$ 80.00 <i>45 hr</i>
71	1 set	front windscreen sealant	\$ 35.00 <i>cut</i>
72	1 pc	To resupply I.U. bracket.	\$ 12.00 <i>cut</i>
			\$ 677.00
		<u>LABOUR & MISC. CHARGES</u>	
1		Towing service.	\$ 100.00 <i>Towing receipt</i>
2		To check electrical lighting concerned.	\$ 150.00 <i>40</i>
3		To reinstall of rear bumper parking sensor.	\$ 120.00 <i>40</i>
4		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 80.00 <i>X</i>
5		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 150.00 <i>60</i>
			\$ 600.00
		Balance c/f	\$ 15,763.96

Ac

M.

TLM Automobile Pte Ltd
1 Defu Lane 6 Singapore 539365
UEN number: 202244624K

Mr Lim Hai Min Benedict

Third Party Insurer: Allianz
 Date of accident : 14 June 2023
 Date: 15 June 2023

Estimate To Repair
 SLL3615B - Mazda 3 Sedan 1.5 AT
 Chassis No : JM6BN22A8H0141402

S/No	Quantity	Description	Amount
		Balance b/f	\$ 15,763.96
		LABOUR & MISC. CHARGES	
6		To dismantle air-con assy, remove and renewal of parts, vacuum and charge-in gas.	\$ 150.00 <i>100</i>
7		Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$ 350.00 <i>x</i>
8		To resupply I.U. bracket.	\$ 12.00 <i>✓</i>
9		To remove and refit front windscreen glass.	\$ 100.00 <i>✓</i>
10		Panel beating, knocking and straighten the necessary portion,	\$ 2,500.00 <i>1200</i>
11		To rust-proofing of the affected areas.	\$ 200.00 <i>60</i>
12		Putty and spray painting of the affected portion.	\$ 2,500.00 <i>1500</i>
			\$ 5,812.00
		Grand Total	\$ 21,575.96

Tanpin 97495719
'wp' 16/6/23 @ 330
1/3 Resny after repair
Tanpin @ 10 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: