

ASS. REC. BY:

REF:

HSB/ 2300 8148 / kg3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

826K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKP 4955U Yr Regn: 09, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Elantra c.c. 1591

Colour

M. Red

A/C: Insured / Std / NI / NA

Sp. Reading

181380

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMITD H41CMEU 293586

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

d

mm

Rear

R/Bal.

d

mm

L/Bal.

d

mm

L/Bal.

d

mm

D.O.A.

16/6/23

D.O.I.

20/6/2023

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear n/s

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/6 21:00 @ 4800. Cnhr 27/6/23 (Per 5028-60, 51/6)

Date/Time, File Pass to?



: Preli. Report

1) 28/6 14:00



: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Sweet Claims

Lump Sum / I.B.A. (\$

4800

AUTHORIZE WORKSHOP PTE LTD

160, Sin Ming Drive, #03-19, Sin Ming Autocity, Singapore 575722

Tel: 64560226 Fax: 64584500

Registration No: 201603203R

Not Authorized
L1 Rep & 4800h
Resurvey After Pain
6 days

		ESTIMATE
Mr Cheng Han Ching Blk 62 Woodlands Dr 16, #09-28 Singapore 737895		Date : 19th June 2023
		Veh No : SKP 4915U
		Make/Model : Hyundai Elantra
		Chassis No : KMHDH41CMEU293586
		Date of Acc : 16.06.23
		TP Veh No : SHA 1837X

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Rear Boot Lid		\$ 1,782.40
2	1 pc	Rear Boot Hyundai Logo		\$ 41.00
3	1 pc	Rear Boot lid Elantra Emblem		\$ 52.10
4	2 pcs	Rear Boot Lid Hinges L/R	\$ 76.20	\$ 152.40
5	1 pcs	Rear Boot Lid Mechanism Lock		\$ 194.60
6	2 pcs	Rear Boot Lid Reflector Lamp L/R	\$ 298.20	\$ 596.40
7	1 pc	Rear Bumper		\$ 569.50
8	2 pcs	Rear Bumper Reflector L/R	\$ 54.80	\$ 109.60
9	1 pc	Rear Bumper Lower Trim		\$ 758.00
10	2 pcs	Rear Bumper Side Retainer L/R	\$ 44.30	\$ 88.60
11	1 pc	Rear Bumper Mudflap LH		\$ 78.50
12	1 pc	Rear Bumper Reinforcement		\$ 488.00
13	2 pcs	Rear Bumper Reinforcement Bracket L/R	\$ 88.60	\$ 177.20
14	1 pc	Rear End Panel		\$ 484.60
15	1 pc	Rear Boot Weatherstrip		\$ 139.20
16	2 pcs	Rear Lamp L/R	\$ 427.30	\$ 854.60
17	1 pc	Rear Fender LH		\$ 1,496.30
18	1 pc	Rear Fender Inner Trim LH		\$ 228.20
19	1 pc	Rear Fender Liner LH		\$ 102.10
20	1 pc	Rear Windscreen Molding		\$ 86.20
				\$ 8,479.50
			Less 20% :	\$ 1,695.90
			Parts Total :	\$ 6,783.60
Special Nett				
1	1 set	Rear Bumper Clips		\$ 45.00
2	1 set	Reverse Sensor		\$ 250.00
3	1 set	Rear Fender Liner Clips		\$ 30.00
4	1 set	Rear Fender Inner Trim Clips		\$ 40.00
5	1 pc	Windscreen Sealant		\$ 50.00
			Special Nett :	\$ 415.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$ 80.00	
2		To remove & replace upholstery, trim garnishes to facilitate repairs.	\$ 100.00	
3		To remove, instal rear windscreen.	\$ 150.00	
4		To remove, transfer boot lid components	\$ 100.00	
5		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$ 1,000.00	
6		Putty and respray painting on affected portions.	\$ 1,000.00	
7		To remove & renew reverse sensor	\$ 100.00	
8		Rust proofing on affected portions.	\$ 100.00	
			Labour :	\$ 2,630.00
			Total Parts & Labour :	\$ 9,828.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repairs
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

for Authorize Workshop Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	795C
Vehicle Details	
Vehicle No.:	SKP4915U
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jun 2023
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	G4FGEU087695
Chassis No.:	KMHDH41CMEU293586
Maximum Power Output:	97.0 kW (130 bhp)
Open Market Value:	\$13,596.00
Original Registration Date:	16 Sep 2014
First Registration Date:	16 Sep 2014
Transfer Count:	1
Actual ARF Paid:	\$13,596.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Sep 2024
PARF Rebate Amount:	\$7,477.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$64,841.00
COE Rebate Amount:	\$8,026.00
Total Rebate Amount:	\$15,503.00

The information contained herein is correct as at 19 Jun 2023

OK