



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI23006153/Kqy3m4 Date: 03/07/2023	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJP 7477J	Veh. Inspected	CB 3366D	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10022890 /JT	Excess (\$)	0.00	
Assign From	FRAULEINE KHOO	Assign Date	19/06/2023	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA COASTER(A)	c.c	4009	
Engine No.	HIDDEN	Year of Reg.	2023	
Chassis No.	JTGBDAC8906600309	Colour	WHITE	
Odometer	9810 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/70 R17.5	BRIDGESTONE	9 mm	
L/H Front Tyre	215/70 R17.5	BRIDGESTONE	9 mm	
R/H Rear Tyre	215/70 R17.5 (D)	BRIDGESTONE	9/9 mm	
L/H Rear Tyre	215/70 R17.5 (D)	BRIDGESTONE	9/9 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	14/06/2023	Inspection Date	22/06/2023	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		