

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURAN	INSURANCE BHD			CS3/LPC23006156/Rvy3e2	
	300 BEACH ROAD #17-04/07 THE CO	Γ	Date:	19/07/2023		
			(	Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	XE 8184P	Veh. Inspected		SNJ 5899Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	23/23/23/VC00/027521	Excess (\$)		0.00	
	Assign From	CHARMAINE KONG	Assign Date		19/06/2023	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALPHARD HYBRID 2.5 SRC	c.c		2493	
	Engine No.	HIDDEN	Year of Reg.		2023	
	Chassis No.	AYH300152126	Colour		WHITE	
	Odometer	41123 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/45Z R20	FALKEN		6 mm	
	L/H Front Tyre	245/45Z R20	FALKEN		6 mm	
	R/H Rear Tyre	245/45Z R20	FALKEN		6 mm	
	L/H Rear Tyre	245/45Z R20	FALKEN		6 mm	
4. Description of Damages						
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT PORTION.				
	DAMAGES SEE DE					
5.	General Information					
	Accident Date	07/06/2023	Inspect Date / Ti	ime	17/07/2023 ( 04:38 PM )	
	Survey held at	TRIDENT AUTO SERVICE CENTRE PTE LTD				
		8 KAKI BUKIT AVENUE 4, #02-42, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC23006156/Rvy3e2

Inspected By

**Automotive Assessor** 

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.