

# CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

VEHICLE NO: SGA1038Y

MAKE & MODEL: TOYOTA/CAMRY

DOA: 18.06.2023

CLAIM TYPE: Third Party Claim

M2053BK4107059922

TP HL

Veron.

## ESTIMATION QUOTE

| PARTS                                         | QTY | PRICE (\$)             | REMARKS |
|-----------------------------------------------|-----|------------------------|---------|
| FRONT BUMPER <i>Distorted</i>                 | 1   | \$ <del>955.60</del>   | ✓ 641   |
| FRONT BUMPER RETAINER <i>Distorted</i>        | 2   | \$ 205.00              | ✓       |
| FRONT BUMPER BRACKET <i>new</i>               | 2   | \$ 167.00              | ✓       |
| FRONT BUMPER SPONGE <i>new</i>                | 1   | \$ 88.80               | ✓       |
| FRONT BUMPER REINFORCEMENT <i>new</i>         | 1   | \$ 382.50              | ✓       |
| FRONT BUMPER CENTRE AIR-GRILLE <i>new</i>     | 1   | \$ 296.80              | ✓       |
| FRONT BUMPER TOW GARNISH <i>Distorted</i>     | 2   | \$ 96.40               | ✓       |
| FRONT BUMPER CENTRE CHROME GARNISH <i>new</i> | 1   | \$ 155.40              | ✓       |
| FRONT BUMPER SIDE CHROME GARNISH <i>new</i>   | 2   | \$ 317.20              | ✓       |
| FRONT BUMPER SIDE GARNISH <i>new</i>          | 2   | \$ 311.20              | ✓       |
| FRONT BONNET <i>Distorted</i>                 | 1   | \$ <del>1,347.20</del> | ✓ 982   |
| FRONT BONNET HINGE <i>new</i>                 | 2   | \$ 130.00              | ✓       |
| FRONT BONNET INSULATOR <i>new</i>             | 1   | \$ 88.80               | ✓       |
| FRONT BONNET CHROME <i>new</i>                | 1   | \$ 146.80              | ✓       |
| FRONT BONNET RUBBER <i>new</i>                | 1   | \$ 44.00               | ✓       |
| FRONT BONNET LOCK <i>Distorted</i>            | 1   | \$ 155.60              | ✓       |
| FRONT HEADLAMP ASSY LH <i>new</i>             | 1   | \$ <del>2,221.70</del> | ✓ 1201  |
| FRONT HEADLAMP ASSY RH <i>new</i>             | 1   | \$ <del>2,221.70</del> | ✓ 1201  |
| FRONT HEADLAMP LOWER BRACKET LH <i>new</i>    | 1   | \$ 132.20              | ✓       |
| FRONT HEADLAMP LOWER BRACKET RH <i>new</i>    | 1   | \$ 132.20              | ✓       |
| FRONT FOG LAMP LH <i>new</i>                  | 1   | \$ 314.00              | ✓       |
| FRONT FOG LAMP RH <i>new</i>                  | 1   | \$ 314.00              | ✓       |
| FRONT FOG LAMP COVER LH <i>new</i>            | 1   | \$ 168.00              | ✓       |
| FRONT FOG LAMP COVER RH <i>new</i>            | 1   | \$ 168.00              | ✓       |
| REAR BOOTLID <i>new</i>                       | 1   | \$ 1,433.00            | ✓       |
| REAR BOOTLID HINGE LH <i>new</i>              | 1   | \$ 54.00               | ✓       |
| REAR BOOTLID HINGE RH <i>new</i>              | 1   | \$ 54.00               | ✓       |
| REAR BOOTLID ABSORBER LH <i>new</i>           | 1   | \$ 309.00              | ✓       |
| REAR BOOTLID ABSORBER RH <i>new</i>           | 1   | \$ 309.00              | ✓       |
| REAR BOOTLID LOCK <i>new</i>                  | 1   | \$ 384.00              | ✓       |
| REAR BOOTLID LOGO <i>new</i>                  | 1   | \$ 98.20               | ✓       |
| REAR BOOTLID EMBLEM 'CAMRY' <i>new</i>        | 1   | \$ 78.40               | ✓       |
| REAR BOOTLID LOCK STRIKER <i>new</i>          | 1   | \$ 54.00               | ✓       |
| REAR BOOTLID LOCK SENSOR <i>new</i>           | 1   | \$ 318.00              | ✓       |
| REAR BOOTLID WEATHERSTRIP <i>new</i>          | 1   | \$ 218.00              | ✓       |
| REAR BOOTLID OUTER GARNISH <i>new</i>         | 1   | \$ 219.00              | ✓       |
| REAR BOOTLID EMBLEM <i>new</i>                | 1   | \$ 65.00               | ✓       |
| REAR BOOTLID INNER LAMP LH <i>new</i>         | 1   | \$ 384.00              | ✓       |
| REAR BOOTLID INNER LAMP RH <i>new</i>         | 1   | \$ 384.00              | ✓       |
| REAR BOOTLID INSULATOR <i>new</i>             | 1   | \$ 139.00              | ✓       |
| REAR BUMPER <i>Distorted</i>                  | 1   | \$ <del>1,293.00</del> | ✓ 685   |
| REAR BUMPER RETAINER LH <i>new</i>            | 1   | \$ 65.00               | ✓       |
| REAR BUMPER RETAINER RH <i>new</i>            | 1   | \$ 65.00               | ✓       |
| REAR BUMPER REFLECTOR LH <i>new</i>           | 1   | \$ 108.00              | ✓       |
| REAR BUMPER REFLECTOR RH <i>new</i>           | 1   | \$ 108.00              | ✓       |
| REAR BUMPER SPONGE <i>new</i>                 | 1   | \$ 143.00              | ✓       |
| REAR BUMPER REINFORCEMENT <i>new</i>          | 1   | \$ 531.00              | ✓       |

|                                            |           |                        |              |        |
|--------------------------------------------|-----------|------------------------|--------------|--------|
| REAR BUMPER LOWER GARNISH <i>new</i>       | 1         | \$ 409.00              | <del>+</del> |        |
| TAILLAMP LH <i>cat</i>                     | 1         | \$ <del>755.00</del>   | <del>+</del> | 583    |
| TAILLAMP RH <i>Build</i>                   | 1         | \$ <del>755.00</del>   | <del>+</del> | 583    |
| TAILLAMP PANEL LH <i>3 pps</i>             | 1         | \$ 178.60              | <del>+</del> |        |
| TAILLAMP PANEL RH                          | 1         | \$ 178.60              | <del>+</del> |        |
| REAR END PANEL <i>Replaced Dented</i>      | 1         | \$ 563.00              | <del>+</del> |        |
| REAR END PANEL TOP GARNISH <i>Replaced</i> | 1         | \$ 219.00              | <del>+</del> |        |
| SPARE TYRE PANEL <i>new</i>                | 1         | \$ 1,031.70            | <del>+</del> |        |
| SPARE TYRE PANEL TOP BOARD                 | 1         | \$ 361.20              | <del>+</del> |        |
| SPARE TYRE PANEL CENTRE TOP FOAM           | 1         | \$ 298.70              | <del>+</del> |        |
| SPARE TYRE PANEL SIDE FOAM TRAY <i>new</i> | 2         | \$ 451.20              | <del>+</del> |        |
| REAR EXHAUST <i>new</i>                    | 1         | \$ 981.30              | <del>+</del> |        |
| REAR PDC SENSOR <i>Dented</i>              | 4         | \$ <del>1,020.00</del> | <del>+</del> | 200/SN |
| REAR SENSOR HOLDER <i>new</i>              | 4         | \$ 60.00               | <del>+</del> |        |
|                                            |           | \$ 24,636.00           |              |        |
|                                            | LESS 25%  | \$ 6,159.00            |              |        |
|                                            | SUB TOTAL | \$ 18,477.00           |              |        |

| SPECIAL NETT ITEMS                     | QTY       | PRICE (\$) | REMARKS       |
|----------------------------------------|-----------|------------|---------------|
| FRONT BUMPER CLIP <i>new</i>           | 1 SET     | \$ 50.00   | <del>30</del> |
| FRONT NUMBER PLATE <i>Missing</i>      | 1         | \$ 100.00  | <del>50</del> |
| REAR NUMBER PLATE <i>new</i>           | 1         | \$ 100.00  | <del>+</del>  |
| REAR BUMPER CLIP <i>new</i>            | 1 SET     | \$ 50.00   | <del>30</del> |
| REAR BOOTLID INSULATOR CLIP <i>new</i> | 1 SET     | \$ 40.00   | <del>+</del>  |
| REVERSE SENSOR <i>Replaced</i>         | 1 SET     | \$ 400.00  | <del>+</del>  |
| JOINT SELANT <i>new</i>                | 1         | \$ 150.00  | <del>60</del> |
|                                        | SUB TOTAL | \$ 890.00  |               |

| LABOUR                                                       | QTY | PRICE (\$)  | REMARKS            |
|--------------------------------------------------------------|-----|-------------|--------------------|
| CHECK FRONT LIGHTNING AND WIRING SYSTEM                      | 1   | \$ 100.00   | 30 Front           |
| CHECK REAR LIGHTNING AND WIRING SYSTEM                       | 1   | \$ 100.00   | 30 Rear            |
| REMOVE AND RENEW REAR REVERSE SENSOR                         | 1   | \$ 150.00   | 50 Rear            |
| REMOVE AND REFIT FRONT LINING, TRIM AND GARNISH              | 1   | \$ 200.00   | <del>+</del> Front |
| REMOVE AND REFIT REAR LINING, TRIM AND GARNISH               | 1   | \$ 200.00   | <del>60</del> Rear |
| REMOVE AND STRAIGHTEN REAR EXHAUST                           | 1   | \$ 150.00   | <del>+</del> Rear  |
| TRANSFER PARTS, ATTACHMENT FROMT OLD BOOTLID TO NEW          | 1   | \$ 250.00   | <del>+</del> Rear  |
| PANEL BEATING ON FRONT AFFECTED AREAS AND RENEW DAMAGE PARTS | 1   | \$ 1,400.00 | 600 Front          |

|                                                             |   |             |           |
|-------------------------------------------------------------|---|-------------|-----------|
| PANEL BEATING ON REAR AFFECTED AREAS AND RENEW DAMAGE PARTS | 1 | \$ 1,200.00 | 800 Rear  |
| SPRAY PAINTING ON FRONT AFFECTED AREAS                      | 1 | \$ 1,400.00 | 600 Front |
| SPRAY PAINTING ON REAR AFFECTED AREAS                       | 1 | \$ 1,200.00 | 700 Rear  |
| APPLY ANTI RUST ON AFFECTED AREAS                           | 1 | \$ 200.00   | 60 Rear   |

SUB TOTAL \$ 6,550.00

GRAND TOTAL \$ 25,917.00

hist (Front) 4867.60

Less 25% : 3650.70

S.N (Front) 80

Labour : 1230

Total (Front) : 4960.70

L/S (Front) 3950 #

hist (Rear) : 3578.60

Less 25% : 2683.55

S.N (Rear) : 290

Labour (Rear) : 1700

Total (Rear) : 4673.55

L/S (Rear) : 3710 #

Grand total: \$7650

Adrian Lj  
L/S 20/06/23

No of days 11 Days



Front : 5 Days

Rear : 6 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: