

(08/11/13) Wef

ASS. REC. BY: /

Tayfiteh

REF:

CS/EQ/123006170/T93

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 845K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No:

SLB/357L

Yr Regn:

2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Monta 5933

C.C.

1498

Colour

Blue-

A/C: Insured / Std / NI / NA

Sp. Reading

108548

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JHMGK5850GX 201810

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

20/6/23

Survey held at

Everest

Des. of Damages: Frt / Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$ _____).

Vehicle No. SLB 1357 L

HONDA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Rear bumper		1452.00	Rx
2	Rear bumper Side Retainer L/R @ \$72.00		144.00	x
1	RHS rear fender		1250.00	Rx
1	RHS rear door		982.00	bt
2	RHS rear door black tape @\$80		160.00	we
1	RHS rear door inner trim		520.00	R
1	RHS rear door lock		430.00	x
1	RHS rear door window power actuator w/motor		640.00	bl
1	RHS front door		1100.00	bt
2	RHS front door black tape @\$80		160.00	we
1	RHS front door inner trim		560.00	R
1	RHS front door lock		340.00	x
1	RHS front door window power actuator w/motor		640.00	bt
1	RHS centre pillar		1640.00	Rx
1	RHS rocker panel cover		480.00	?? - photo de
			10498.00	
		20%	2099.60	20%
			8398.40	
SPECIAL NETT ITEMS				
1	RHS rear sports rim		980.00	wt 600
10	Rear bumper clips		60.00	x
1set	RHS rear fender inner shield clips		60.00	x
Total Parts			9498.40	

Vehicle No. SLB 1357 L HONDA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components.	2000.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1600.00	1000
3	To remove and refix rear RH fender glass	120.00	X
4	To check wiring and dismantle 2 door components	300.00	120
5	To remove /refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear fender	200.00	60
6	To conduct computerised wheel alignment test	180.00	80
7	To remove and replace reverse sensors and reverse camera and check for proper function	120.00	30
8	To perform anti rust treatment on affected areas	200.00	40
Labour Total :		4720.00	
TOTAL (PARTS & LABOUR):		14218.40	

Taufik 97495749/62563561

WP' 20/6/2020

C/S Resurvey after repair

Taufik @ lkhands.com

06 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: