

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Vehicle number: SMG 3084 Y

Make & Model: Toyota Sienta

Chassis number: MHFZ28H3600059802

No.	Description of spare parts	Qty	Amount S\$	
1	Tailgate	1	\$ pb 1,117.30	✓
2	Tailgate windscreen glass rubber moulding	1	\$ rel 174.00	✓
3	Tailgate centre emblem	1	\$ rel 72.20	✓
4	Tailgate "G" emblem	1	\$ rel 56.00	✓
5	Tailgate "Sienta" emblem	1	\$ rel 52.40	✓
6	Tailgate RH lamp	1	\$ X nn 518.00	
7	Tailgate LH lamp	1	\$ X nn 518.00	
8	Tailgate chrome moulding	1	\$ rel 281.00	✓
9	Tailgate wiper motor	1	\$ X nn 338.00	
10	Tailgate inner trim board	1	\$ de 287.00	✓
11	Tailgate inner trim board clips	1set	\$ rel 20 70.00	✓
12	Tailgate inner handle	1	\$ X nn 87.00	
13	Tailgate weatherstrip	1	\$ ent 367.30	✓
14	Rear bumper	1	\$ de 621.00	✓
15	Rear bumper (upper)	1	\$ de 242.00	✓
16	Rear bumper clips	1set	\$ rel 30 80.00	✓
17	Rear bumper RH reverse sensor	1	\$ 7 200 344.80	225 ✓
18	Rear bumper LH reverse sensor	1	\$ 5 200 344.80	225 ✓
19	Rear bumper RH reflector	1	\$ X nn 59.00	
20	Rear bumper LH reflector	1	\$ X nn 59.00	
21	Rear bumper RH side garnish	1	\$ de 127.40	✓
22	Rear bumper LH side garnish	1	\$ de 127.40	✓
23	Rear bumper RH side retainer	1	\$ X nn 69.60	
24	Rear bumper RH support bracket	1	\$ X nn 72.60	
25	Rear bumper LH side retainer	1	\$ ent 69.60	✓
26	Rear bumper LH support bracket	1	\$ X nn 72.60	
27	Rear bumper tow cover	1	\$ X nn 25.00	
28	Rear bumper centre fog lamp	1	\$ ent 234.50	✓
29	Rear bumper centre fog lamp cover	1	\$ de 47.70	✓
30	Rear antenna sensor	1	\$ X nn 72.00	
31	RH taillamp assy	1	\$ X nn 942.80	
32	RH taillamp panel	1	\$ X nn 208.00	
33	RH taillamp lock clips	1set	\$ X nn 60.00	
34	LH taillamp assy	1	\$ X nn 942.80	
35	LH taillamp panel	1	\$ X nn 208.00	
36	RH taillamp lock clips	1set	\$ X nn 60.00	
37	End panel inner garnish	1	\$ de 225.00	✓
38	End panel inner garnish clips	1set	\$ 20 200 45.00	
39	End panel (upper)	1	\$ X nn 724.00	
40	End panel (lower)	1	\$ bf 586.00	✓
41	Rear tyre panel upper board	1	\$ X nn 378.00	

42	Rear tyre panel jack tray	1	\$ 409.00 409.00	322 ✓
43	Rear RH fender inner trim board	1	\$ 715.00 715.00	608 ✓
44	Rear RH fender inner trim board clips	1set	\$ X nn 70.00	
45	Rear RH fender outer garnish	1	\$ X nn 462.80	
46	Rear RH fender outer garnish clips	1set	\$ X nn 70.00	
47	Rear LH fender inner trim board	1	\$ 715.00 715.00	608 ✓
48	Rear LH fender inner trim board clips	1set	\$ X nn 70.00	
49	Rear LH fender outer garnish	1	\$ X nn 462.80	
50	Rear LH fender outer garnish clips	1set	\$ X nn 70.00	

6725.80
-25%
5044.35

\$ 14,031.40
Parts less 25% \$ 3,507.85
Total: \$ 10,523.55

No.	Special Nett Items	Qty	Amount S\$
1	Rear number plate	1	\$ X nn 70.00
2	Tailgate windscreen glass sealant	1	\$ 40 ea 80.00
3	Tailgate windscreen glass inner seal	1	\$ 30 ea 60.00
4	Tailgate reverse camera	1	\$ X nn 750.00
5	End panel joint sealant	1	\$ 40 ea 80.00

110

Total: \$ 1,040.00

No.	Labour and painting	Amount S\$
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 600 1,600.00
2	Spray painting on affected areas and panels	\$ 600 1,400.00
3	Check wiring and lighting system on affected areas	\$ 30 60.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 80.00
5	Remove and replace tailgate windscreen glass to assist repair	\$ 120 240.00
6	Remove and replace tailgate reverse camera to assist repair	\$ 30 100.00
7	Remove and replace tailgate inner mechanism to new tailgate	\$ 60 180.00
8	Remove and replace rear bumper reverse sensors	\$ 30 100.00
9	Remove and replace rear inner trims and garnish to assist repair	\$ 60 320.00

Agreed Amount: _____ (Part by Part / Lump sum)
Working days: _____

Total: \$ 2,480.00

Spare Parts: \$ 10,523.55
Special Nett: \$ 1,040.00
Labour: \$ 2,480.00

Total Amount: \$ 14,043.55

Taufik 97495241
wp 20/6/23 @ 2:15 pm
C/S Resurvey after repair
5 days
taufik@lkhauto.com
- To check consistency of accident
- To check part prices

6714.35

L/S - 5371.48
= 5350

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: