

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546 Email:
soonsanmotor@gmail.com

LONPAC INSURANCE BHD

300m Beach Road

07, THE CONCOURSE #17-04

S,pore 199555

Accident date:17/06/2023

Date:17/06/2023

Estimate cost to repair vel: SNG 3448U (318i BMW) claims under vel: GBH 6639C.

1pce boot lid	\$ 1,356.50	by -
2pcs boot lid dampers@\$160	320.00	X
2pcs boot lid hinges@\$85.55	171.10	X
1pce boot lid 318i plate	68.50	net
1pce boot lid emblem	75.50	net
2pcs boot lid reflectors@\$364.55	729.10	?
1pce boot lid rubber	105.10	X
1pce boot lid top lock	120.05	?
1pce boot lid lower lock	55.20	X
2pcs tail lamps@\$402.85	805.70	?
1pce rear bumper	1,155.50	del
2 4pcs rear bumper reverse sensors@\$280.10	1,120.40	net
1pce rear bumper tow cover	42.00	mit
1pce rear bumper top side cover	102.50	?
2pcs rear bumper side holders@\$150.50	301.00	L4X RH-?
10pcs rear bumper inner clips@\$12	120.00	net
1pce rear bumper inner sponge	160.10	?
1pce rear bumper reinforcement	650.50	?
2pcs rear bumper inner brackets@\$95	190.00	?
1pce rear panel	680.50	R+
1pce rear panel lower lock cover	95.50	X
1pce rear inner spare tool holder	680.50	X
1pce rear exhaust pipe	1,200.00	X
1pce rear exhaust pipe outer chrome	180.50	X
	\$ 10,485.75	
Less 5%	524.28	
	\$ 9,961.46	

SOON SAN MOTOR TRADING

Blk.3006,UBI ROAD 1,#01-390,SINGAPORE 408700,TEL:68414445 & FAX:67473546 Email:
soonsanmotor@gmail.com

LONPAC INSURANCE BHD

300m Beach Road

07, THE CONCOURSE #17-04

S,pore 199555

Accident date:17/06/2023

Date:17/06/2023

Estimate cost to repair vel: SNG 3448U (318i BMW) claims under vel: GBH 6639C.

Page 2	\$ 9,961.46
1pce rear number plate with cover	100.00 X
To rustproof	150.00 30
To remove/refit rear interior to effect repair	100.00 60
To dismantle/renew reverse sensors	100.00 40
To check wiring	50.00 30
To dismantle/renew exhaust pipe	150.00 X
To dismantle/renew accident portion	1,500.00 700
To spray paint	1,200.00 700
Total:	\$13,311.46

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

File:

Tanpin 97495749 / 62563561
wpr 19/6/23 @ 350pm
L/S Resurvey after repair
tanpin @lkkauto.com
4-5 days