



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DVS22/0056

Date: 05th July 2023

Our Ref: CS1/LIP23006177/Rvy3m4

M/s Liberty Insurance Pte Ltd

51 Club Street, #03-00

Liberty House

Singapore 069428

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: CB 8578B

INSURED VEHICLE: SMP 2806R

ACCIDENT DATE: 18/05/2022

We thank you for your instruction on 19/06/2023.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of CB 8578B from Tommie Lim Appraisal.
- b) Singapore Accident Statement of Vehicles CB 8578B and SMP 2806R.
- c) Final Repair Bill of CB 8578B from M/s Sincerelead Garage Pte Ltd.
- d) Colour damaged vehicle photographs of CB 8578B.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: CB 8578B
Make & Model	: Toyota Hiace 2.5 M
Year of Registration	: 2007
Chassis Number	: KDH2005015113
Engine Capacity	: 2494 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.