

Date: 19/06/2023

Vehicle No: SNC7827D

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA9MC385368-2021

Reg.Year: 2021

*Not Authorised
Resuming Bepaint
6 days*

Third Party Insurer: AIG

Third Party Veh No: SFB6999Y

Date of Accident: 17/06/2023

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT HEADLAMP LH	1		<i>By</i> \$1,308.41
2	FRONT HEADLAMP LOWER BRACKET LH	1		<i>Ry</i> \$7.48
3	FRONT HEADLAMP RH	1		\$1,308.41
4	FRONT HEADLAMP LOWER BRACKET RH	1		\$7.48
5	FRONT BUMPER	1		<i>Tn</i> \$1,214.95
6	FRONT BUMPER SIDE BRACKET LH	1		<i>mi'</i> \$9.35
7	FRONT BUMPER SIDE BRACKET RH	1		<i>mi'</i> \$9.35
8	FRONT BUMPER UPPER BRACKET LH	1		<i>mi'</i> \$1.87
9	FRONT BUMPER UPPER BRACKET RH	1		<i>mi'</i> \$1.87
10	FRONT BUMPER INNER BRACKET LH	1		<i>cm</i> \$12.15
11	FRONT BUMPER INNER BRACKET RH	1		\$12.15
12	FRONT BUMPER FOG LAMP GARNISH COVER LH	1		<i>mi'</i> \$6.54
13	FRONT BUMPER FOG LAMP GARNISH COVER RH	1		<i>mi'</i> \$6.54
14	FRONT BUMPER TOW COVER	1		<i>mi'</i> \$14.95
15	FRONT BUMPER LOWER GRILLE	1		<i>mi'</i> \$102.80
16	FRONT BUMPER REINFORCEMENT	1		<i>mi'</i> \$271.03
17	FRONT BUMPER REINFORCEMENT SUPPORT LH	1		<i>Ry</i> \$52.34
18	FRONT BUMPER REINFORCEMENT SUPPORT RH	1		<i>Ry</i> \$52.34
19	FRONT BUMPER LOWER REINFORCEMENT	1		<i>Ry</i> \$102.80
20	FRONT BUMPER LOWER REINFORCEMENT SUPPORT LH	1		<i>Ry</i> \$29.91
21	FRONT BUMPER LOWER REINFORCEMENT SUPPORT RH	1		\$29.91
22	FRONT BUMPER ABSORBER FOAM	1		<i>mi'</i> \$46.73
23	FRONT BUMPER PARKING SENSOR	4	\$163.55	<i>mi'</i> \$654.20
24	FRONT BUMPER PARKING SENSOR BRACKET	4	\$4.67	<i>mi'</i> \$18.68
25	FRONT BUMPER WIRING HARNESS	1		\$93.46
26	FRONT HEADLAMP WIRING HARNESS	1		\$88.79
27	FRONT NUMBER PLATE HOLDER	1		<i>Ry</i> \$29.91
28	FRONT FENDER LH	1		<i>Ry</i> \$448.60
29	FRONT FENDER INNER BRACKET LH	1		<i>Ry</i> \$23.36
30	FRONT FENDER INNER SHIELD LH	1		<i>mi'</i> \$116.82
31	FRONT LUGGAGE COMPARTMENT	1		\$64.49
32	FRONT SUPPORT PANEL	1		<i>cm</i> \$766.36
33	FRONT SUPPORT PANEL BRACKET LH	1		<i>mi'</i> \$7.48
34	FRONT SUPPORT PANEL BRACKET RH	1		<i>mi'</i> \$7.48
35	FRONT RADAR SENSOR	1		<i>shen</i> \$345.79
36	FRONT RADAR SENSOR HOLDER	1		<i>cm</i> \$4.67
37	FRONT RADAR SENSOR BRACKET	1		<i>Ry</i> \$7.48

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1622 | Fax: (+65) 6481 1011



Date: 19/06/2023
Vehicle No: SNC7827D
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA9MC385368-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SFB6999Y
Date of Accident: 17/06/2023
Estimator: TING AN
Surveyor:

38	FRONT COMPRESSOR BRACKET	1		\$29.91	7
39	FRONT AIR DUCT ASSY	1		Di \$186.92	2
40	FRONT AIRCON CONDENSER	1		\$420.56	7
41	FRONT AIRCON CONDENSER FAN SHROULD ASSY	1		\$373.83	7
42	FRONT RADIATOR	1		\$79.44	7
43	FRONT RADIATOR FAN SHROULD ASSY	1		\$84.11	7
44	FRONT FENDER RH	1		REPAIR	
45	FRONT BONNET	1		REPAIR	
				SUB TOTAL	\$8,461.70
				LESS 10%	-\$846.17
				PARTS TOTAL	\$7,615.53

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		RM \$50.00	—
2	FRONT FENDER INNER SHIELD CLIPS LH	1		RM \$40.00	—
3	FRONT NUMBER PLATE & HOLDER	1		RM \$50.00	45.00
4	RADIATOR COOLANT	1		\$80.00	7
				S/N TOTAL	\$220.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$1,000.00 600

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BONNET, FRONT BUMPER, FRONT FENDER LH, FRONT FENDER RH & ETC.

\$1,000.00 680

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER WIRING HARNESS.
TO EFFECT REPLACE OF FRONT BUMPER.

\$120.00 60

TO REFILL AIRCON GAS & ETC.

\$120.00 7

TO TUFF KOTE & UNDERSEAL MATERIALS.

\$150.00 30

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 668047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 19/06/2023
Vehicle No: SNC7827D
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA9MC385368-2021
Reg.Year: 2021

Third Party Insurer: AIG
Third Party Veh No: SFB6999Y
Date of Accident: 17/06/2023
Estimator: TING AN
Surveyor:

TO DIAGNOSIS FAULT CODE & RESET MEMORY.

\$250.00 180

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$120.00 20

LABOUR TOTAL \$2,760.00

TING AN

TOTAL \$10,595.53

